



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1402
Vehicle No. : SKJ5299P
Make & Model : LAND ROVER DISCOVERY

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Boot lid <i>bt</i>		2832.00	
1	Boot lid weatherstrip <i>tom</i>		198.00	
1	Boot lid lock <i>X Svc</i>		204.00	X
1	Boot lid logo badge <i>ne</i>		82.00	
1	Boot lid emblem "DISCOVERY" <i>ne</i>		238.00	
1	Boot lid emblem "SPORT" <i>ne</i>		144.00	
1	Rear bumper <i>de</i>		2472.00	
2	Rear bumper side retainer RH/LH@2*\$82 <i>X Svc</i>		164.00	X
1	Rear bumper reflector LH <i>cm</i>		296.00	
1	Rear bumper lower garnish <i>de</i>		584.00	
2	Rear bumper reverse sensor@2*\$202 <i>? X Svc</i>		404.00	X
1	Rear reinforcement <i>? bt</i>		1158.00	
1	Exhaust pipe LH <i>reg bt</i>		3912.00	
1	End panel (Repair refer to labour)		0.00	
			11916	
			10%	
			10724.40	
			Part Items Total: -10%	
			12688.00	
			-1268.80	
			11419.20	
SPECIAL NETT ITEMS				
1	Rear bumper clip <i>ne</i>		35.00	
1	Rear carplate with holder <i>X Svc</i>	65	35.00	X
1	Rear bumper lower garnish clip <i>ne</i>		30.00	
SN Items Total:			100.00	
Total Parts:			11519.20	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1402
Vehicle No. : SKJ5299P
Make & Model : LAND ROVER DISCOVERY

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	200
3	To remove and refix wiring system at accident damaged area and check for all electrical	60.00	30
4	To remove and replace rear reverse sensor	100.00	60
5	To remove and refit rear windscreen	100.00	
6	To remove and replace exhaust pipe	200.00	80
Labour Total :		1860.00	
TOTAL (PARTS & LABOUR):		13379.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

10724.40

65.00

870.00

1356.40

12015.80

Rasul

Hp 900 100 68

5 days

P/P

04/11/24

Reg after repair



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1402
Vehicle No. : SKJ5299P
Make & Model : LAND ROVER DISCOVERY

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	End panel top garnish <i>cm</i>		396.00	
			396	
			-10%	
			396.00	
			-39.60	
			356.40	
<u>SPECIAL NETT ITEMS</u>				
<u>LABOUR</u>				
1	To remove and replace exhaust pipe <i>Xnn</i>		308.00	Xnn
Total Parts			656.40	