



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

FINALIZATION ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851		
			Document No. 0				
			Document Date 01/11/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	23/10/2024 8.00		01/11/2024 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC23A00367800 ACC DATE:21/10/2024 TOW/DRIVE IN:DRIVE IN EXCESS:\$0 DATE-IN:21/10/2024 DATE SURVEY:21/10/2024 NO OF REPAIR DAYS:10 REPAIR DAYS BY:RASUL LKK AUTHORISED ON:23/10/2024				50.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00	
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS	*			2304.00	
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS	*			2832.00	
5	B	BP-LAB2 TO CHECK WIRING SYSTEM	*			97.92	
6	B	BP-MECH2 TO REMOVE AND REPLACE A/C CONDENSER & RA DIATOR	BP63			288.00	
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP63			144.00	
8	B	BP-WS2 TO REMOVE AND INSTALL FRONT WINDSCREEN	*			369.60	
9	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR FRONT WINDSCREE N	0650			480.00	
10	S	BP-SUBLET TO SUPPLY FRONT NUMBER PLATE	0263			80.00	
11	B	BP-MECH2 TO REMOVE AND INSTALL HEV INVERTER	BP63			288.00	
12	B	BP-MECH2 TO REMOVE AND REPLACE INTAKE MANIFOLD	BP63			288.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 10 Eunoo Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851			
			Document No. 0					
			Document Date 01/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	23/10/2024 8.00		01/11/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
13	1	T11212-37090 COVER, CYLINDER			1.00	279.50	30.00	195.65
14	2	T16400-37290 RADIATOR ASSY			1.00	2979.00	30.00	2085.30
15	3	L16711-37040 SHROUD, FAN			1.00	411.10	30.00	287.77
16	4	T16712-37051 SHROUD, FAN, NO.2			1.00	167.10	30.00	116.97
17	5	UG9010-47050 RADIATOR ASSY			1.00	1299.50	30.00	909.65
18	6	U17120-37054 MANIFOLD ASSY,			1.00	1437.50	30.00	1006.25
19	7	T17750-37070 INLET ASSY, AIR			1.00	335.10	30.00	234.57
20	8	T17700-37252 CLEANER ASSY, AIR			1.00	1582.40	30.00	1107.68
21	9	T52119-47969 COVER, FR BUMPER			1.00	855.40	30.00	598.78
22	0	T53395-47030 SEAL, HOOD TO FR END			1.00	141.40	30.00	98.98
23	1	T52115-47030 SUPPORT, FR BUMPER			1.00	104.50	30.00	73.15
24	2	S52161-0K040 PIECE, RR BUMPER			10.00	5.80	30.00	40.60
25	3	T53102-47180 GRILLE SUB-ASSY,			1.00	789.60	30.00	552.72
26	4	T53113-47060 GRILLE, RADIATOR,			1.00	207.40	30.00	145.18
27	5	T52611-47100 ABSORBER, FR BUMPER			1.00	110.20	30.00	77.14
28	6	T53111-47110 GRILLE, RADIATOR			1.00	672.20	30.00	470.54
29	7	S52161-0K040 PIECE, RR BUMPER			8.00	5.80	30.00	32.48
30	8	T53301-47070 HOOD SUB-ASSY			1.00	1277.10	30.00	893.97
31	9	T53801-47100 FENDER SUB-ASSY, FR			1.00	1400.50	30.00	980.35
32	0	T53866-47030 SEAL, FR FENDER TO			1.00	34.20	30.00	23.94
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
Amount Due								

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600				S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851			
				Document No. 0					
				Document Date 01/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	23/10/2024	8.00	01/11/2024	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
33	1	U53875-47061 LINER, FR FENDER, RH				1.00	262.80	30.00	183.96
34	2	T53510-47121 LOCK ASSY, HOOD				1.00	187.20	30.00	131.04
35	3	T53410-47160 HINGE ASSY, HOOD, RH				1.00	81.80	30.00	57.26
36	4	T53420-47160 HINGE ASSY, HOOD, LH				1.00	81.80	30.00	57.26
37	5	T53201-47050 SUPPORT SUB-ASSY,				1.00	2033.60	30.00	1423.52
38	6	T53293-47050 DEFLECTOR, RADIATOR				1.00	120.00	30.00	84.00
39	7	T53289-47041 COVER, RADIATOR				1.00	190.30	30.00	133.21
40	8	T56101-4F914 GLASS SUB-ASSY,				1.00	2237.60	30.00	1566.32
41	9	T75533-47060 MOULDING,				1.00	84.10	30.00	58.87
42	0	L56117-50140 DAM, WINDOW GLASS				1.00	40.10	30.00	28.07
43	1	L56115-30100 STOPPER, WINDSHIELD				1.00	6.40	30.00	4.48
44	2	T56116-22050 STOPPER, WINDSHIELD				1.00	6.20	30.00	4.34
45	3	T75310-33050 EMBLEM ASSY,				1.00	146.80	30.00	102.76
46	4	T81140-47660 UNIT ASSY, HEADLAMP,				1.00	3890.00	30.00	2723.00
47	5	T81070-47660 UNIT ASSY, HEADLAMP,				1.00	3890.00	30.00	2723.00
48	6	UG9110-47030 BRACKET ASSY,				1.00	422.60	30.00	295.82
49	7	U86510-48070 HORN ASSY, HIGH				1.00	186.60	30.00	130.62
50	8	T88460-47170 CONDENSER ASSY				1.00	2170.80	30.00	1519.56
51	9	T21000-20 SIKA 182010 SIKA TACK GO! (BLA				2.00	108.00	30.00	151.20
52	0	T21000-22 SIKA 207. G+P ADHESIVE PRIMER				1.00	200.00	30.00	140.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts		Less Amount Due		
					Labour				
					Sublet				
					Lubrication/Fluid				
					Others				

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851			
			Document No. 0					
			Document Date 01/11/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	23/10/2024 8.00		01/11/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
53	1	S08889-80102 COOLANT,SLLC&&&			2.00	108.00		216.00
54	2	S86520-06100 HORN ASSY, LOW PITCH			1.00	186.60	30.00	130.62
55	3	T16264-37170 HOSE, WATER BY-PASS,			1.00	49.00	30.00	34.30
56	4	T55708-47150 LOUVER SUB-ASSY,			1.00	916.70	30.00	641.69
57	5	U55810-47010 VENTILATOR ASSY,			1.00	59.10	30.00	41.37
58	6	T52618-47060 ABSORBER, FR BUMPER,			1.00	205.10	30.00	143.57
59	7	T53630-47060 CABLE ASSY, HOOD			1.00	76.40	30.00	53.48
60	8	T53341-47030 INSULATOR, HOOD			1.00	570.00	30.00	399.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 30,451.51	
					Parts 23,109.99		GST 9.00% 2,740.64	
					Labour 6,781.52			
					Sublet 560.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 33,192.15	