



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKQ 886R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEFORMED	\$1,850.00	\$1,850.00
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	\$260.00	\$0.00
1	FRONT BUMPER CENTER GRILLE	CRACKED	\$680.00	\$680.00
1	FRONT BUMPER DAY LIGHT RH	CRACKED	\$740.00	\$740.00
1	FRONT BUMPER DAY LIGHT LOWER GARNISH RH	NOT NECESSARY	\$488.00	\$0.00
1	FRONT BUMPER SENSOR RH	NOT NECESSARY	\$315.00	\$0.00
4	FRONT BUMPER SENSOR HOLDER @\$68.00	NOT NECESSARY	\$272.00	\$0.00
1	FRONT BUMPER SENSOR WIRE HARNESS	NOT NECESSARY	\$1,120.00	\$0.00
1	FRONT BUMPER TOP COVER GARNISH (CENTER)	DEFORMED	\$560.00	\$560.00
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	\$628.00	\$0.00
1	FRONT BUMPER FOG LAMP COVER RH	CUT	\$288.00	\$288.00
1	FRONT BUMPER LOWER GARNISH	NOT NECESSARY	\$182.00	\$0.00
1	FRONT BUMPER AIR VENT GARNISH RH	CRACKED	\$98.00	\$98.00
1	FRONT BUMPER AIR VENT INNER LOWER GARNISH RH	DAMAGED	\$87.00	\$87.00
1	FRONT BUMPER TOP COVER GARNISH (SIDE) RH	DEFORMED	\$430.00	\$430.00
1	FRONT BUMPER SPONGE	CRACKED	\$290.00	\$290.00
1	FRONT BUMPER SIDE BRACKET RH	NOT NECESSARY	\$120.00	\$0.00
1	FRONT BUMPER UPPER CORNER BRACKET RH	NOT NECESSARY	\$120.00	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$790.00	\$0.00
2	HEADLAMP @\$6,940.00	O/S CRACKED	\$13,880.00	\$3,840.00
2	HEADLAMP LOWER BRACKET @\$125.00	NOT NECESSARY	\$250.00	\$0.00
2	HEADLAMP RING RUBBER @\$240.00	O/S TORN	\$480.00	\$240.00
1	HEADLAMP NOZZLE RH	NOT NECESSARY	\$458.00	\$0.00
1	HEADLAMP NOZZLE COVER RH	NOT NECESSARY	\$138.00	\$0.00
1	FRONT FENDER COWLING RH	NOT NECESSARY	\$279.90	\$0.00
1	BONNET	DENTED	\$5,890.00	\$4,186.00
1	BONNET LOGO	NECESSARY	\$450.00	\$450.00
2	BONNET HINGE @\$200.00	NOT NECESSARY	\$400.00	\$0.00
2	BONNET LOCK @\$295.00	NOT NECESSARY	\$590.00	\$0.00
2	BONNET LOCK CATCHER @\$262.00	NOT NECESSARY	\$524.00	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BONNET INSULATOR	NOT NECESSARY	\$678.00	\$0.00
2	BONNET STOPPER @\$55.00	NOT NECESSARY	\$110.00	\$0.00
1	FRONT CENTER AIR GUARD	NOT NECESSARY	\$654.00	\$0.00
1	FRONT LOWER AIR GUARD	NOT NECESSARY	\$264.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$3,436.39)	(\$1,373.90)
			\$30,927.51	\$12,365.10

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	CRACKED	\$80.00	\$30.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$150.00	\$50.00
1	SET FRONT BUMPER NUMBER PLATE GARNISH CLIP (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET FRONT BUMPER DAY LIGHT LOWER GARNISH CLIP (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET FRONT BUMPER CENTER GRILLE CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	SET ENGINE UNDERCOVER CLIP (SN)	NOT NECESSARY	\$80.00	\$0.00
1	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	\$120.00	\$0.00
1	BONNET SEALANT (SN)	NOT NECESSARY	\$150.00	\$0.00
			\$800.00	\$80.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVING AND REPLACING PARTS	NOT NECESSARY	\$1,800.00	\$500.00
	SPRAY PAINTING TO AFFECTED AREA		\$1,600.00	\$500.00
	REFOCUS HEADLAMP BEAM		\$60.00	\$0.00
	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE RESETTING		\$480.00	\$80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC		\$680.00	\$250.00
			\$4,620.00	\$1,330.00

<b>GRAND TOTAL</b>			<b>\$36,347.51</b>	<b>\$13,775.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>\$11,000.00</b>
Report Ref No: CS/UOI24100350/Aqp3m4				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.