



# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 21.10.2024

TO : UOI MOTOR CLAIMS DEPTS  
VEHICLE NO : SKQ886R  
MODEL : PORSCHE MACAN  
DATE OF ACCIDENT : 15.10.2024  
TIME OF ACCIDENT : 16:25 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rebuild</i>	1	\$ 1,850.00	\$ 1,850.00
2	FRONT BUMPER NUMBER PLATE GARNISH <i>new</i>	1	\$ 260.00	\$ 260.00
3	FRONT BUMPER CENTER GRILLE <i>cracked</i>	1	\$ 680.00	\$ 680.00
4	FRONT BUMPER DAY LIGHT RH <i>cracked</i>	1	\$ 740.00	\$ 740.00
5	FRONT BUMPER DAY LIGHT LOWER GARNISH RH <i>at car</i>	1	\$ 488.00	\$ 488.00
6	FRONT BUMPER SENSOR RH <i>new</i>	1	\$ 315.00	\$ 315.00
7	FRONT BUMPER SENSOR HOLDER <i>new</i>	4	\$ 68.00	\$ 272.00
8	FRONT BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 1,120.00	\$ 1,120.00
9	FRONT BUMPER TOP COVER GARNISH (CENTER) <i>Rebuild</i>	1	\$ 560.00	\$ 560.00
10	FRONT BUMPER FOG LAMP RH <i>new</i>	1	\$ 628.00	\$ 628.00
11	FRONT BUMPER FOG LAMP COVER RH <i>ext</i>	1	\$ 288.00	\$ 288.00
12	FRONT BUMPER LOWER GARNISH <i>new</i>	1	\$ 182.00	\$ 182.00
13	FRONT BUMPER AIR VENT GARNISH RH <i>to be rebuild</i>	1	\$ 98.00	\$ 98.00
14	FRONT BUMPER AIR VENT INNER LOWER GARNISH RH	1	\$ 87.00	\$ 87.00
15	FRONT BUMPER TOP COVER GARNISH (SIDE) RH <i>Rebuild</i>	1	\$ 430.00	\$ 430.00
16	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 290.00	\$ 290.00
17	FRONT BUMPER SIDE BRACKET RH <i>new</i>	1	\$ 120.00	\$ 120.00
18	FRONT BUMPER UPPER CORNER BRACKET RH <i>new</i>	1	\$ 120.00	\$ 120.00
19	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 790.00	\$ 790.00
20	HEADLAMP <i>cracked RH</i>	2	\$ 6,940.00	\$ 13,880.00
21	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 125.00	\$ 250.00
22	HEADLAMP RING RUBBER <i>to be rebuild RH</i>	2	\$ 240.00	\$ 480.00

Handwritten notes and checkmarks on the right side of the table, including a total of 6940 and 240.

TO : UOI MOTOR CLAIMS DEPTS  
 VEHICLE NO : SKQ886R  
 MODEL : PORSCHE MACAN  
 DATE OF ACCIDENT : 15.10.2024  
 TIME OF ACCIDENT : 16:25 HOURS

23	HEADLAMP NOZZLER RH	1	\$ 458.00	\$ 458.00	+
24	HEADLAMP NOZZLER COVER RH	1	\$ 138.00	\$ 138.00	+
25	FRONT FENDER COWLING RH	1	\$ 279.90	\$ 279.90	+
26	BONNET	1	\$ 5,890.00	\$ 5,890.00	+
27	BONNET LOGO	1	\$ 450.00	\$ 450.00	+
28	BONNET HINGE	2	\$ 200.00	\$ 400.00	+
29	BONNET LOCK	2	\$ 295.00	\$ 590.00	+
30	BONNET LOCK CATCHER	2	\$ 262.00	\$ 524.00	+
31	BONNET INSULATOR	1	\$ 678.00	\$ 678.00	+
32	BONNET STOPPER	2	\$ 55.00	\$ 110.00	+
33	FRONT CENTER AIR GUARD	1	\$ 654.00	\$ 654.00	+
34	FRONT LOWER AIR GUARD	1	\$ 264.00	\$ 264.00	+

TOTAL PRICE \$ 34,363.90  
 LESS 10% \$ 3,436.39  
 SUB TOTAL PRICE \$ 30,927.51

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET)	1	\$ 150.00	\$ 150.00
3	FRONT BUMPER NUMBER PLATE GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
4	FRONT BUMPER DAY LIGHT LOWER GARNISH CLIP (SE	1	\$ 80.00	\$ 80.00
5	FRONT BUMPER CENTER GRILLE CLIP (SET)	1	\$ 60.00	\$ 60.00
6	ENGINE UNDERCOVER CLIP (SET)	1	\$ 80.00	\$ 80.00
7	BONNET INSULATOR CLIP	1	\$ 120.00	\$ 120.00
8	BONNET SEALANT	1	\$ 150.00	\$ 150.00

TOTAL \$ 800.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	500

TO : **UOI** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SKQ886R**  
 MODEL : **PORSCHE MACAN**  
 DATE OF ACCIDENT : 15.10.2024  
 TIME OF ACCIDENT : 16:25 HOURS

3	REFOCUS HEADLAMP BEAM	\$ 60.00	X
4	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE RESETTING	\$ 480.00	80
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	200

**TOTAL \$ 4,620.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 31,727.51  
 TOTAL LABOUR COST : \$ 4,620.00  
 TOTAL REPAIR COST : \$ 36,347.51

*Adrian S  
 w/s 22/10/24  
 04 pages*

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: