

TO : UOI MOTOR CLAIMS DEPTS
 VEHICLE NO : SKQ886R
 MODEL : PORSCHE MACAN
 DATE OF ACCIDENT : 15.10.2024
 TIME OF ACCIDENT : 16:25 HOURS

23	HEADLAMP NOZZLER RH	1	\$ 458.00	\$ 458.00	+
24	HEADLAMP NOZZLER COVER RH	1	\$ 138.00	\$ 138.00	+
25	FRONT FENDER COWLING RH	1	\$ 279.90	\$ 279.90	+
26	BONNET	1	\$ 5,890.00	\$ 5,890.00	4186
27	BONNET LOGO	1	\$ 450.00	\$ 450.00	-
28	BONNET HINGE	2	\$ 200.00	\$ 400.00	+
29	BONNET LOCK	2	\$ 295.00	\$ 590.00	+
30	BONNET LOCK CATCHER	2	\$ 262.00	\$ 524.00	+
31	BONNET INSULATOR	1	\$ 678.00	\$ 678.00	+
32	BONNET STOPPER	2	\$ 55.00	\$ 110.00	+
33	FRONT CENTER AIR GUARD	1	\$ 654.00	\$ 654.00	+
34	FRONT LOWER AIR GUARD	1	\$ 264.00	\$ 264.00	+

113739
1236540

TOTAL PRICE \$ 34,363.90
 LESS 10% \$ 3,436.39
 SUB TOTAL PRICE \$ 30,927.51

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00	30
2	FRONT BUMPER CLIP (SET)	1	\$ 150.00	\$ 150.00	50
3	FRONT BUMPER NUMBER PLATE GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00	+
4	FRONT BUMPER DAY LIGHT LOWER GARNISH CLIP (SE	1	\$ 80.00	\$ 80.00	+
5	FRONT BUMPER CENTER GRILLE CLIP (SET)	1	\$ 60.00	\$ 60.00	+
6	ENGINE UNDERCOVER CLIP (SET)	1	\$ 80.00	\$ 80.00	+
7	BONNET INSULATOR CLIP	1	\$ 120.00	\$ 120.00	+
8	BONNET SEALANT	1	\$ 150.00	\$ 150.00	+

80

TOTAL \$ 800.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	500

TO : UOI MOTOR CLAIMS DEPTS
 VEHICLE NO : SKQ886R
 MODEL : PORSCHE MACAN
 DATE OF ACCIDENT : 15.10.2024
 TIME OF ACCIDENT : 16:25 HOURS

3	REFOCUS HEADLAMP BEAM	\$ 60.00	X
4	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE RESETTING	\$ 480.00	80
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	250

TOTAL \$ 4,620.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,727.51
 TOTAL LABOUR COST : \$ 4,620.00
 TOTAL REPAIR COST : \$ 36,347.51

1330

Adrian
 2/5 22/10/24

04 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 13775.10
 4/5: MKIC

11k.