



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|----------------------|--------------------------|
| SINGAPORE PRISON SERVICE | | | Ref: | CS/SPS24100351/Knp3e2(N) |
| LOGISTICS BRANCH | | | Date: | 14/01/2025 |
| ATTN: SIOU YONG SIN ACE | | | Code: | SPS |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | PC 9550P | Veh. Inspected | SJG 92D | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | MHASPS06000188262 | Excess (\$) | 0.00 | |
| Assign From | SIOU YONG SIN ACE | Assign Date | 21/10/2024 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI LX2 PALISADE 3.5 AT SR | c.c | 3470 | |
| Engine No. | HIDDEN | Year of Reg. | 2021 | |
| Chassis No. | KMHR381CMMU317156 | Colour | METALLIC DARK PURPLE | |
| Odometer | 64582 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 265/40 R21 | PIRELLI | 8 mm | |
| L/H Front Tyre | 265/40 R21 | PIRELLI | 8 mm | |
| R/H Rear Tyre | 265/40 R21 | CONTINENTAL | 7 mm | |
| L/H Rear Tyre | 265/40 R21 | CONTINENTAL | 7 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR MIRROR. | | | | |
| DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 08/10/2024 | Inspection Date | 24/10/2024 | |
| Survey held at | SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 2 Working Days | |