

ASS. REC. BY:

REF:

SPS/

CS/SPS 24100351/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

20/12

1830.00

(Red. \$ 628, 25%)

Veh No:

STG 92D

Yr Regn:

OB 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A)

Wagon

Make:

Genesis

C.C.

3470

Colour

M. Black

A/C:

Insured / Std / Nil / NA

Sp. Reading

64582

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

KMHHR 3810mm 4 317156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rim or

Tyre Size:

F: Pir

265/40R21

R: Continental

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

J

mm

R/Bal.

7

mm

L/Bal.

P

mm

L/Bal.

7

mm

D.O.A.

8/10/24

D.O.I.

24/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rm N/S down mirror

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

2

1)

Date/Time, File Return to?

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LEE WEE SIONG ANTHONY

c/o 46 Lentor Plain
Singapore 786548

Date: 24/10/2024

QUANTITY	PARTICULARS	AMOUNT (\$)
1 pc	<u>RE: HYUNDAI PALISADE / SJG 92 D</u> MIRROR ASSY-OUTSIDE RR VIEW,LH <i>1850</i>	<i>cm</i> 2,360.00 ✓
	Sub-total	2,360.00
	Less 20%	472.00
	Sub-total	1,888.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	200.00 <i>for</i>
	To spray painting on affected areas.	220.00 <i>1201</i>
	To apply vinyl sticker wrap on affected areas.	150.00 ✓
	<i>Not Authorised</i> <i>Repair B4 paint</i> <i>2 days</i> <i>16mm</i> <i>24/10/24</i> <i>\$1830.00</i>	Total 2,458.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: