

ASS. REC. BY:

REF:

SPS/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Supreme

471 E

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.61 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STG 92D

Yr Regn:

08 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Wagon

Make:

Honda Genesis

C.C.

3470

Colour:

N. Black

P. Paper

Insured / Std / NI / NA

Sp. Reading

64582

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHR 3810 mma 317156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Pir

265/40R21

R: Continued

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

7

mm

L/Bal.

P

mm

L/Bal.

7

mm

D.O.A.

8/10/24

D.O.I.

24/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S down minor

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

F. P. M.

Others

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TOTAL

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LEE WEE SIONG ANTHONY
c/o 46 Lentor Plain
Singapore 786548

Date: 24/10/2024

QUANTITY	PARTICULARS	AMOUNT (\$)
1 pc	RE: HYUNDAI PALISADE / SJG 92 D	
	MIRROR ASSY-OUTSIDE RR VIEW,LH	2,360.00 ✓
	Sub-total	2,360.00
	Less 20%	472.00
	Sub-total	1,888.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	200.00 ✓
	To spray painting on affected areas.	220.00 ✓
	To apply vinyl sticker wrap on affected areas.	150.00 ✓
	<i>Not Authorised</i>	
	<i>Repairing</i>	
	<i>2 days</i>	
	<i>Humayun</i>	
	<i>28/10/24</i>	
	Total	2,458.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: