

Rajes (LKK Auto)

From: Huey Yon (LKKAuto)
Sent: Wednesday, October 23, 2024 2:27 PM
To: Yong Sin SLOW (PRIS)
Cc: Muhammad Fariz ZAKARIA (PRIS); assignments; SUR
Subject: RE: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Dear Ace,

According to repairer, the third party owner withdraw the claim from their workshop.

We will close the case without billing.

Dear assignment team,

Kindly assist to cancel the case in our system.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Huey Yon (LKKAuto)
Sent: Tuesday, 22 October 2024 10:16 AM
To: Yong Sin SLOW (PRIS) <SLOW_Yong_Sin@pris.gov.sg>
Cc: Muhammad Fariz ZAKARIA (PRIS) <Muhhammad_Fariz_ZAKARIA@pris.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Dear Ace,

We have checked with workshop, they still arrange appointment with TP owner for inspection the vehicle.

Dear Rajes,

Kindly assist.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yong Sin SLOW (PRIS) <SLOW_Yong_Sin@pris.gov.sg>
Sent: Tuesday, 22 October 2024 9:23 AM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Cc: Muhammad Fariz ZAKARIA (PRIS) <Muhhammad_Fariz_ZAKARIA@pris.gov.sg>
Subject: FW: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Hi Huey Yon,

As spoken, you may proceed to link up with Supreme Auto Services Pte Ltd workshop with details as provided below.

2. Do keep me updated on the date/time of the pre-repair assessment once you have arranged with the workshop.
3. The GIA report is attached for your reference.
4. Thanks.

Vehicle to be surveyed:	SJG92D
3rd Party Insured Vehicle:	Direct Asia Insurance Pte Ltd
Date of Accident:	8 Oct 2024
Location of Accident:	Simei Street 3
Type of Collision	Moving SPS bus (PC9550P) while travelling on a straight road (lane 2) brushed against stationary car (SJG92D) who was on lane 3 and encroaching a little into lane 2 waiting to perform U-turn. The car's left-wing mirror was damaged and came off due to impact.
Name of Workshop:	Supreme Auto Service Pte Ltd
Address of Survey Location:	Blk 176 Sin Ming Drive #02-01 Singapore 575271
Name of Contact Person:	Chew Wing Kit Dylan (64528211/96725547)
Date of Survey:	To be completed by Huey Yon
Name of Authorised Surveyor:	Ms Huey Yon



Siow Yong Sin Ace (Mr)

Staff Officer, Operations Logistics
Logistics and Finance Division/Logistics Branch
DID: (65) 6546 9489

Visit us at sps.gov.sg | Follow us on     



OUR NEXT BO
OF TRAN
Strengthen Heartware. Upgra

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error."

From: Yong Sin SIOW (PRIS) <SIOW_Yong_Sin@pris.gov.sg>

Sent: Tuesday, October 22, 2024 9:18 AM

To: Rajes (LKK Auto) <rajes@lkkauto.com>

Cc: Muhammad Fariz ZAKARIA (PRIS) <Muhammad_Fariz_ZAKARIA@pris.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Hi Rajes,

Noted with thanks. I will link up with Huey Yon accordingly.



Siow Yong Sin Ace (Mr)

Staff Officer, Operations Logistics

Logistics and Finance Division/Logistics Branch

DID: (65) 6546 9489

Visit us at sps.gov.sg | Follow us on



OUR NEXT BO
OF TRANS

Strengthen Heartware. Upgrade

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error."

From: Rajes (LKK Auto) <rajes@lkkauto.com>

Sent: Monday, October 21, 2024 4:25 PM

To: Yong Sin SIOW (PRIS) <SIOW_Yong_Sin@pris.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Muhammad Fariz ZAKARIA (PRIS) <Muhammad_Fariz_ZAKARIA@pris.gov.sg>

Subject: RE: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Dear Sir,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Please be informed that **Ms. Huey Yon** is the handler of this case who can be contacted at 6256 3561/
hueyyon@lkkauto.com

Best Regards,

Rajes | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yong Sin SIOW (PRIS) <SIOW_Yong_Sin@pris.gov.sg>

Sent: Monday, October 21, 2024 3:15 PM

To: assignments <assignments@lkkauto.com>

Cc: Muhammad Fariz ZAKARIA (PRIS) <Muhammad_Fariz_ZAKARIA@pris.gov.sg>

Subject: [Pre-Repair Assessment Service Required] For SJG92D @ Supreme Auto Service Pte Ltd Workshop

Dear LKK Auto,

SPS would like to engage your services for a pre-repair assessment check for SJG92D (private car) who was involved in a minor accident with our SPS bus with details as provided in the table below.

2. We will raise a PO (\$230.00) for this service.
3. For your assistance and confirmation on the date/time of the pre-repair assessment please.
4. Thanks.

Vehicle to be surveyed:	SJG92D
3rd Party Insured Vehicle:	Direct Asia Insurance Pte Ltd
Date of Accident:	8 Oct 2024
Location of Accident:	Simei Street 3
Type of Collision	Moving SPS bus (PC9550P) while travelling on a straight road (lane 2) brushed against stationary car (SJG92D) who was on lane 3 and encroaching a little into lane 2 waiting to perform U-turn. The car's left-wing mirror was damaged and came off due to impact.
Name of Workshop:	Supreme Auto Service Pte Ltd
Address of Survey Location:	Blk 176 Sin Ming Drive #02-01 Singapore 575271
Name of Contact Person:	Chew Wing Kit Dylan (64528211/96725547)
Date of Survey:	To be completed by LKK Auto
Name of Authorised Surveyor:	To be completed by LKK Auto



Siow Yong Sin Ace (Mr)

Staff Officer, Operations Logistics
Logistics and Finance Division/Logistics Branch
DID: (65) 6546 9489

Visit us at sps.gov.sg | Follow us on     



OUR NEXT BO
OF TRAN
Strengthen Heartware. Upgra

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error."