

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / QD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKK4109G Yr Regn: 2021 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 318i C.D. 1998

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 63798 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA70PY0608B99079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: 225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 22/10/24

Survey held at Bitrost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front x/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ECICS

COE Expiry :

Estimate given during : Yes (✓)
1st Survey : No ()

MV: 160K

PV: 94.4K

Nett: 65.6K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1) Date/Time, File Return to?

☐ : Final Report

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Format:

Report Form: _____

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SKK4109G

Make & Model: BMW 318i

Chassis number: WBA70DY0608B99079

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet <i>new</i>	1	\$ 1,709.00
2	Bonnet emblem <i>new</i>	1	\$ 78.00
3	Bonnet emblem lock clips <i>new</i>	1set	\$ 28.00
4	Front bumper <i>Delund</i>	1	\$ 1,367.00
5	Front bumper LH side retainer <i>?</i>	1	\$ 73.00
6	Front bumper RH side retainer <i>new</i>	1	\$ 73.00
7	Front bumper lower grille <i>?</i>	1	\$ 276.00
8	Front bumper LH side cover <i>lit</i>	1	\$ 83.00
9	Front bumper reinforcement <i>new</i>	1	\$ 607.00
10	Front bumper impact absorber	1	\$ 92.00
11	Front bumper lower reinforcement <i>new</i>	1	\$ 329.00
12	Front bumper LH side parking sensor <i>new</i>	1	\$ 382.00
13	Front bumper LH centre parking sensor <i>new</i>	1	\$ 382.00
14	Front bumper parking sensor holders <i>new</i>	4	\$ 44.00
15	Front bumper parking sensor rubber seal <i>1 piece new</i>	4	\$ 96.00
16	LH headlamp assy <i>crushed</i>	1	\$ 3,748.00
17	LH headlamp bracket <i>new</i>	1	\$ 96.00
18	Front LH sport rim <i>lit</i>	1	\$ 1,198.00
19	Front LH wheel bearing <i>?</i>	1	\$ 563.00
20	Front LH shock absorber <i>new</i>	1	\$ 622.00
21	Front LH lower arm <i>new</i>	1	\$ 506.00
22	Front shock absorber <i>new</i>	1	\$ 629.00

\$ 12,981.00
 Parts less 5% \$ 649.05
 Total: \$ 12,331.95

No.	Special Nett Items	Qty	Amount S\$
1	Bonnet body wrap sticker <i>new</i>	1	\$ 900.00
2	Front bumper body wrap sticker <i>new</i>	1	\$ 850.00
3	Front bumper parking sensor body wrap stickers <i>new</i>	2	\$ 30.00
4	Front LH tyre <i>3.0</i>	1	\$ 580.00
5	Brake fluid <i>3.0</i>	1	\$ 85.00

--	--	--	--

Total: \$ 2,445.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,300.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 60.00
5	Remove and replace front bumper parking sensors and holders	\$ 150.00
6	Recoding and program headlamps assy	\$ 950.00
7	Test drive and adjust wheel alignment system	\$ 120.00
8	Remove and replace front undercarriage parts to assist repair	\$ 550.00

Total: \$ 3,110.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 12,331.95
Special Nett: \$ 2,445.00
Labour: \$ 3,110.00
Total: \$ 17,886.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adam

1/5 22/10/24

0427p