

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKV6168P  
Accident Date : 16-Oct-2024

Our Ref : 024203 (CHINA) / CHAN

SIM SU WOON  
BLK 918 HOUGANG AVE 9  
#13-38  
Singapore 530918

No. : 07186

Date : 18-Oct-2024

PAGE : 1

*NOT Authorised*

*NOT Authorised*

*11/10/24 @ 30000*

*Payment After Pain*

*6 day*

## ESTIMATED COST OF REPAIR FOR HONDA FIT SMG1973U

1 pc Front n/s door  
1 pc Front n/s door frame tape(set)  
1 pc Front n/s door lower rubber  
1 pc Front n/s door glass regulator gear  
1 pc Rear n/s door  
1 pc Rear n/s door frame tape(set)  
1 pc Rear n/s door lower rubber  
2 pcs Rear n/s door hinge *lower dis @ S\$ 41.50*  
1 pc Rear n/s door checker  
1 pc Rear n/s door glass regulator gear  
1 pc N/s rocker panel

*R* 894.60 ✓  
*na* 46.60 ✓  
*in* 18.50 X  
*dis* 426.50 ✓

*R* 783.50 ✓  
*na* 25.40 ✓  
*in* 16.50 X  
*in* 83.00 ✓  
*in* 44.50 X  
*R* 189.20 ✓

*R* 266.50 ✓

2,794.80

Less 20% : 558.96

2,235.84

To remove roof lining, front and rear seats, trim board and carpet

120.00 *Pol*

To apply undersealing

80.00 ✓

To putty and spray replaced parts

900.00 *Pol*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 *650*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to fluctuation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S\$ 4,135.84

Singapore Dollars Four Thousand One Hundred and Thirty Five and Cents Eighty Four Only

Acknowledged by Repairer

Signature:

Date: