

AXIS88 AUTO PTE LTD

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936

*Not Authorised
his
name
25/10/24
d/s \$3000
2 days.*

VEHICLE NUMBER: SNQ7132B
MAKE & MODEL: E200
DOA: 16/10/2024
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

nett item

PARTS	QTY	PRICE (\$)	REMARKS
Front Bumper <i>cut/line</i>	1	\$ 2,778.90	✓ 1778.90
Front left fender <i>2</i>	1	\$ 1,680.00	X
Front bumper retainer <i>11</i>	1	\$ 298.00	X
Front bumper bracket <i>11</i>	1	\$ 95.00	X
Front left rim <i>cut/replace</i>	1	\$ 2,560.00	✓ 1500
Front left absorber <i>11</i>	1	\$ 1,150.00	X
Front left lower arm <i>11</i>	1	\$ 665.00	X
Front left knuckle arm <i>11</i>	1	\$ 1,315.00	X
		<i>10%</i>	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
Front bumper clips <i>11</i>	1 set	\$ 50.00	✓ 5/11
Sub Total		\$ 50.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
CHECK WIRING		\$150.00	20
REMOVE AND REFIX FRONT UNDERCARRAIGE		\$150.00	11 X
ALIGNMENT		\$150.00	60
REMOVE AND REFIX PARKING SENSOR		\$100.00	30
LABOUR CHARGE KNOCK DENTS CUT WELDING AND RENEW PARTS		\$ 1,200.00	250
RESPRAY PAINTING		\$ 1,000.00	400
Sub Total		\$ 2,750.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: