


# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 24.06.2024

TO : **INCOME** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLZ3460G**  
MODEL : MIT-ATTRAGE  
DATE OF ACCIDENT : 22.06.2024  
TIME OF ACCIDENT : 23:30 HOURS

2018

MMB5TA13AJH 001930

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                   | QTY | UNIT LIST PRICE | TOTAL NETT PRICE |
|-----|-----------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT BUMPER <i>Distorted</i>                 | 1   | \$ 666.00       | \$ 666.00        |
| 2   | FRONT BUMPER LOWER SPOILER <i>new</i>         | 1   | \$ 1,868.20     | \$ 1,868.20      |
| 3   | FRONT BUMPER LOWER GRILLE <i>new</i>          | 1   | \$ 186.00       | \$ 186.00        |
| 4   | FRONT BUMPER FOG LAMP <i>gap</i>              | 2   | \$ 393.00       | \$ 786.00        |
| 5   | FRONT BUMPER FOG LAMP COVER <i>new</i>        | 2   | \$ 120.00       | \$ 240.00        |
| 6   | FRONT BUMPER TOP COVER GARNISH <i>new</i>     | 1   | \$ 103.00       | \$ 103.00        |
| 7   | FRONT BUMPER FOG LAMP COVER CHROME <i>new</i> | 2   | \$ 162.00       | \$ 324.00        |
| 8   | FRONT BUMPER SIDE RETAINER <i>new</i>         | 2   | \$ 28.00        | \$ 56.00         |
| 9   | FRONT BUMPER REINFORCEMENT <i>Distorted</i>   | 1   | \$ 259.00       | \$ 259.00        |
| 10  | FRONT BUMPER TOWING COVER <i>new</i>          | 1   | \$ 28.60        | \$ 28.60         |
| 11  | FRONT RADIATOR GRILLE <i>new</i>              | 1   | \$ 525.00       | \$ 525.00        |
| 12  | FRONT GRILLE LOGO <i>new</i>                  | 1   | \$ 39.00        | \$ 39.00         |
| 13  | HEADLAMP <i>new</i>                           | 2   | \$ 656.00       | \$ 1,312.00      |
| 14  | BONNET <i>Distorted</i>                       | 1   | \$ 629.00       | \$ 629.00        |
| 15  | BONNET STOPPER <i>new</i>                     | 2   | \$ 22.50        | \$ 45.00         |
| 16  | BONNET INSULATOR <i>Completed</i>             | 1   | \$ 285.60       | \$ 285.60        |
| 17  | BONNET LOCK <i>new</i>                        | 1   | \$ 64.00        | \$ 64.00         |
| 18  | BONNET LOCK CABLE <i>new</i>                  | 1   | \$ 86.00        | \$ 86.00         |
| 19  | BONNET HINGE <i>Best</i>                      | 2   | \$ 52.00        | \$ 104.00        |
| 20  | HORN <i>new</i>                               | 1   | \$ 99.00        | \$ 99.00         |
| 21  | RADIATOR <i>Distorted</i>                     | 1   | \$ 872.00       | \$ 872.00        |

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLZ3460G**  
 MODEL : **MIT-ATTRAGE**  
 DATE OF ACCIDENT : 22.06.2024  
 TIME OF ACCIDENT : 23:30 HOURS

|    |                                            |   |             |             |                         |
|----|--------------------------------------------|---|-------------|-------------|-------------------------|
| 22 | RADIATOR SIDE GARNISH <i>Crushed</i>       | 2 | \$ 68.00    | \$ 136.00   | <i>42</i>               |
| 23 | RADIATOR TOP HOSE <i>new</i>               | 1 | \$ 86.00    | \$ 86.00    | <i>+</i>                |
| 24 | RADIATOR MOUNTING <i>new</i>               | 3 | \$ 36.00    | \$ 108.00   | <i>+</i>                |
| 25 | RADIATOR FAN COWLING <i>Crushed</i>        | 1 | \$ 186.00   | \$ 186.00   | <i>✓</i>                |
| 26 | RADIATOR FAN MOTOR <i>new</i>              | 1 | \$ 385.00   | \$ 385.00   | <i>+</i>                |
| 27 | RADIATOR FAN BLADE <i>new</i>              | 1 | \$ 85.00    | \$ 85.00    | <i>+</i>                |
| 28 | RADIATOR SPARE TANK <i>new</i>             | 1 | \$ 78.00    | \$ 78.00    | <i>+</i>                |
| 29 | WASHER TANK <i>new</i>                     | 1 | \$ 135.00   | \$ 135.00   | <i>+</i>                |
| 30 | INTAKE MANIFOLD <i>Crushed</i>             | 1 | \$ 1,423.00 | \$ 1,423.00 | <i>✓</i>                |
| 31 | INTAKE MANIFOLD HOSE <i>new</i>            | 1 | \$ 155.00   | \$ 155.00   | <i>+</i>                |
| 32 | AIR CLEANER <i>new</i>                     | 1 | \$ 1,325.00 | \$ 1,325.00 | <i>+</i>                |
| 33 | AIR CLEANER DUCT <i>new</i>                | 1 | \$ 97.30    | \$ 97.30    | <i>✓</i>                |
| 34 | FRONT FENDER <i>Distorted</i>              | 2 | \$ 479.00   | \$ 958.00   | <i>✓</i>                |
| 35 | FRONT FENDER TOP GARNISH <i>new</i>        | 2 | \$ 82.00    | \$ 164.00   | <i>+</i>                |
| 36 | FRONT FENDER INNER GARNISH <i>new</i>      | 2 | \$ 96.00    | \$ 192.00   | <i>+</i>                |
| 37 | FRONT FENDER COWLING <i>new</i>            | 2 | \$ 149.00   | \$ 298.00   | <i>+</i>                |
| 38 | FRONT FENDER SIDE CHROME <i>new</i>        | 2 | \$ 10.00    | \$ 20.00    | <i>+</i>                |
| 39 | FRONT WIPER SIDE GARNISH <i>new</i>        | 2 | \$ 46.00    | \$ 92.00    | <i>+</i>                |
| 40 | FRONT SUPPORT PANEL <i>Crushed</i>         | 1 | \$ 580.00   | \$ 580.00   | <i>✓</i>                |
| 41 | FRONT SUPPORT LOWER APRON PANEL <i>new</i> | 1 | \$ 388.60   | \$ 388.60   | <i>+</i>                |
| 42 | AIRCON PIPE <i>new</i>                     | 1 | \$ 268.20   | \$ 268.20   | <i>+</i>                |
| 43 | AIR CON CONDENSER <i>Dented</i>            | 1 | \$ 1,121.00 | \$ 1,121.00 | <i>✓</i>                |
| 44 | AIR GUARD (UPPER) <i>gap</i>               | 1 | \$ 78.50    | \$ 78.50    | <i>+</i>                |
| 45 | AIR GUARD (LOWER) <i>gap</i>               | 2 | \$ 68.90    | \$ 137.80   | <i>+</i>                |
| 46 | THROTTLE BODY <i>gap</i>                   | 1 | \$ 695.70   | \$ 695.70   | <i>+</i>                |
| 47 | THROTTLE BODY HORE <i>gap</i>              | 1 | \$ 98.00    | \$ 98.00    | <i>+</i>                |
| 48 | FUSE BOX C/W WIRE HARNESS <i>✓</i>         | 1 | \$ 1,432.00 | \$ 1,432.00 | <i>+</i>                |
| 49 | FRONT DOOR <i>Repair</i>                   | 2 | \$ 899.00   | \$ 1,798.00 | <i>+</i>                |
| 50 | FRONT DOOR BLACK STICKER <i>new</i>        | 2 | \$ 68.00    | \$ 136.00   | <i>+</i>                |
| 51 | SIDE SKIRT LH <i>new</i>                   | 1 | \$ 865.30   | \$ 865.30   | <i>+</i>                |
| 52 | FRONT DRIVER SEAT <i>Repair (Best)</i>     | 1 | \$ 1,896.30 | \$ 1,896.30 | <i>200 local Repair</i> |
| 53 | REAR BUMPER <i>Distorted</i>               | 1 | \$ 708.00   | \$ 708.00   | <i>800 (sw)</i>         |
| 54 | REAR BUMPER LOWER SPOILER <i>Crushed</i>   | 1 | \$ 1,643.00 | \$ 1,643.00 | <i>20</i>               |
| 55 | REAR BUMPER REFLECTOR <i>2 new RH</i>      | 2 | \$ 20.00    | \$ 40.00    |                         |

: **INCOME** MOTOR CLAIMS DEPTS  
: **SLZ3460G**  
: MIT-ATTRAGE  
: 22.06.2024  
: 23:30 HOURS

| QTY | DESCRIPTION                      | UNIT | PRICE       | TOTAL       | REMARKS |
|-----|----------------------------------|------|-------------|-------------|---------|
| 56  | REAR BUMPER INNER CORNER GARNISH | 2    | \$ 68.00    | \$ 136.00   |         |
| 57  | REAR BUMPER SIDE RETAINER        | 2    | \$ 26.00    | \$ 52.00    |         |
| 58  | TAIL LAMP                        | 2    | \$ 276.00   | \$ 552.00   |         |
| 59  | TAIL LAMP PANEL                  | 2    | \$ 198.00   | \$ 396.00   |         |
| 60  | REAR FENDER                      | 2    | \$ 897.00   | \$ 1,794.00 |         |
| 61  | REAR FENDER INNER PANEL RH       | 1    | \$ 765.00   | \$ 765.00   |         |
| 62  | REAR FENDER DRAIN PANEL          | 2    | \$ 130.00   | \$ 260.00   |         |
| 63  | REAR FENDER INNER COWLING        | 2    | \$ 45.00    | \$ 90.00    |         |
| 64  | REAR FENDER INNER TRIM           | 2    | \$ 158.00   | \$ 316.00   |         |
| 65  | REAR DOOR RH                     | 1    | \$ 1,009.00 | \$ 1,009.00 |         |
| 66  | REAR DOOR BLACK STICKER RH       | 1    | \$ 86.00    | \$ 86.00    |         |
| 67  | REAR DOOR INNER TRIM RH          | 1    | \$ 867.30   | \$ 867.30   |         |
| 68  | REAR DOOR INNER LOCK RH          | 1    | \$ 290.00   | \$ 290.00   |         |
| 69  | REAR DOOR WEATHER STRIP RH       | 1    | \$ 129.00   | \$ 129.00   |         |
| 70  | REAR WINDSCREEN                  | 1    | \$ 986.10   | \$ 986.10   |         |
| 71  | BOOT LID                         | 1    | \$ 828.00   | \$ 828.00   |         |
| 72  | BOOT LID SPOILER                 | 1    | \$ 552.00   | \$ 552.00   |         |
| 73  | BOOT LID OUTER MOULDING (CHROME) | 1    | \$ 318.00   | \$ 318.00   |         |
| 74  | BOOT LID OUTER LOCK BUTTON       | 1    | \$ 258.60   | \$ 258.60   |         |
| 75  | BOOT LID LOGO                    | 1    | \$ 41.00    | \$ 41.00    |         |
| 76  | BOOT LID EMBLEM 'ATTRAGE'        | 1    | \$ 38.00    | \$ 38.00    |         |
| 77  | BOOT LID EMBLEM 'MIVEC'          | 1    | \$ 75.00    | \$ 75.00    |         |
| 78  | BOOT LID HINGE                   | 2    | \$ 192.00   | \$ 384.00   |         |
| 79  | BOOT LID STOPPER                 | 4    | \$ 19.00    | \$ 76.00    |         |
| 80  | BOOT LID TOP LOCK                | 1    | \$ 206.00   | \$ 206.00   |         |
| 81  | BOOT LID LOWER LOCK              | 1    | \$ 255.00   | \$ 255.00   |         |
| 82  | BOOT LID WEATHER STRIP           | 1    | \$ 148.00   | \$ 148.00   |         |
| 83  | BOOT LID DETECTOR                | 1    | \$ 110.00   | \$ 110.00   |         |
| 84  | BOOT LID DETECTOR WIRE HARNESS   | 1    | \$ 385.60   | \$ 385.60   |         |
| 85  | BOOT LID BUZZLE                  | 1    | \$ 95.00    | \$ 95.00    |         |
| 86  | BOOT LID BUZZLE BRACKET          | 1    | \$ 35.00    | \$ 35.00    |         |
| 87  | REAR END PANEL TOP GARNISH       | 1    | \$ 70.00    | \$ 70.00    |         |
| 88  | REAR END PANEL                   | 1    | \$ 402.00   | \$ 402.00   |         |
| 89  | REAR END PANEL AIR VENT          | 1    | \$ 29.00    | \$ 29.00    |         |

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLZ3460G**  
 MODEL : **MIT-ATTRAGE**  
 DATE OF ACCIDENT : 22.06.2024  
 TIME OF ACCIDENT : 23:30 HOURS

|     |                                          |   |    |        |    |        |    |
|-----|------------------------------------------|---|----|--------|----|--------|----|
| 90  | REAR END PANEL AIR VENT COVER <i>new</i> | 1 | \$ | 39.00  | \$ | 39.00  | +  |
| 91  | REAR FLOOR PANEL <i>Rys</i>              | 1 | \$ | 906.00 | \$ | 906.00 | +  |
| 92  | REAR FLOOR PANEL TOP BOARD <i>Torn</i>   | 1 | \$ | 185.00 | \$ | 185.00 | ✓  |
| 93  | REAR FLOOR SIDE PANEL RH <i>Rys</i>      | 1 | \$ | 385.00 | \$ | 385.00 | +  |
| 94  | REAR CHASSIS MEBER RH <i>Rys</i>         | 1 | \$ | 810.00 | \$ | 810.00 | +  |
| 95  | REAR SPARE TYRE BOLT <i>3/4"</i>         | 1 | \$ | 37.00  | \$ | 37.00  | +  |
| 96  | REAR SPEAKER PANEL <i>↓</i>              | 1 | \$ | 857.30 | \$ | 857.30 | +  |
| 97  | REAR EXHAUST PIPE <i>Bent</i>            | 1 | \$ | 571.00 | \$ | 571.00 | ✓  |
| 98  | REAR EXHAUST MOUNTING <i>new</i>         | 2 | \$ | 28.00  | \$ | 56.00  | +  |
| 99  | REAR EXHAUST INSULATOR <i>new</i>        | 1 | \$ | 234.00 | \$ | 234.00 | +  |
| 100 | REAR EXHAUST GASKET <i>n</i>             | 1 | \$ | 68.00  | \$ | 68.00  | 42 |

1573190

1415871

S.N: 1000

TOTAL PRICE \$ 42,570.00  
 LESS 10% \$ 4,257.00  
**SUB TOTAL PRICE \$ 38,313.00**

SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                            | QTY | UNIT S/NETT | TOTAL S/NETT |    |
|-----|--------------------------------------------------------|-----|-------------|--------------|----|
| 1   | FRONT NUMBER PLATE <i>Bent</i>                         | 1   | \$ 120.00   | \$ 120.00    | 50 |
| 2   | FRONT BUMPER CLIP (SET) <i>new</i>                     | 1   | \$ 80.00    | \$ 80.00     | 30 |
| 3   | FRONT RADIATOR GRILLE CIP (SET) <i>new</i>             | 1   | \$ 60.00    | \$ 60.00     | 20 |
| 4   | FRONT FENDER COWLING CLIPS (SET) <i>new</i>            | 1   | \$ 60.00    | \$ 60.00     | +  |
| 5   | BONNET SEALANT <i>new</i>                              | 1   | \$ 80.00    | \$ 80.00     | +  |
| 6   | FRONT SUPPORT PANEL SEALANT <i>new</i>                 | 1   | \$ 80.00    | \$ 80.00     | +  |
| 7   | FRONT SIDE GARNISH CLIP <i>new</i>                     | 1   | \$ 60.00    | \$ 60.00     | +  |
| 8   | RADIATOR COOLANT <i>new</i>                            | 1   | \$ 80.00    | \$ 80.00     | 40 |
| 9   | REAR NUMBER PLATE <i>new</i>                           | 1   | \$ 80.00    | \$ 80.00     | +  |
| 10  | REAR BUMPER CLIP (SET) <i>new</i>                      | 1   | \$ 80.00    | \$ 80.00     | 30 |
| 11  | BOOT LID LOGO EMBLEM 'C&C' <i>new</i>                  | 1   | \$ 180.00   | \$ 180.00    | 50 |
| 12  | BOOT LID OUTER MOULDING (CHROME) CLIP (SET) <i>new</i> | 1   | \$ 30.00    | \$ 30.00     | 20 |
| 13  | TAIL LAMP CLIP (SET) <i>new</i>                        | 1   | \$ 60.00    | \$ 60.00     | +  |
| 14  | TAIL LAMP PANEL SEALANT <i>new</i>                     | 2   | \$ 80.00    | \$ 160.00    | +  |
| 15  | REAR DOOR INNER TRIM CLIP <i>new</i>                   | 1   | \$ 80.00    | \$ 80.00     | +  |
| 16  | REAR FENDER SEALANT <i>new</i>                         | 2   | \$ 150.00   | \$ 300.00    | 60 |
| 17  | REAR FENDER INNER COWLING CLIP (SET) <i>new</i>        | 1   | \$ 80.00    | \$ 80.00     | +  |

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLZ3460G**  
 MODEL : **MIT-ATTRAGE**  
 DATE OF ACCIDENT : 22.06.2024  
 TIME OF ACCIDENT : 23:30 HOURS

|    |                                             |   |           |           |           |
|----|---------------------------------------------|---|-----------|-----------|-----------|
| 18 | REAR WINDSCREEN INNER SEAL <i>3 per</i>     | 1 | \$ 60.00  | \$ 60.00  | <i>30</i> |
| 19 | REAR WINDSCREEN SEALANT <i>4 per</i>        | 1 | \$ 80.00  | \$ 80.00  | <i>40</i> |
| 20 | REAR WINDSCREEN SOLAR FILM <i>new</i>       | 1 | \$ 200.00 | \$ 200.00 | <i>+</i>  |
| 21 | REAR END PANEL INSULATION SEAL <i>new</i>   | 1 | \$ 150.00 | \$ 150.00 | <i>60</i> |
| 22 | REAR FLOOR PANEL INSULATION SEAL <i>new</i> | 1 | \$ 350.00 | \$ 350.00 | <i>+</i>  |
| 23 | TRIANGLE BREAKDOWN SIGN <i>new</i>          | 1 | \$ 180.00 | \$ 180.00 | <i>+</i>  |
| 24 | REVERSE SENSOR (SET) <i>new</i>             | 1 | \$ 220.00 | \$ 220.00 | <i>20</i> |
| 25 | REVERSE CAMERA <i>new</i>                   | 1 | \$ 480.00 | \$ 480.00 | <i>+</i>  |

*630*

**TOTAL \$ 3,390.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

| S/N | JOB DESCRIPTION                                         | PRICE       | ADJUSTED COST |
|-----|---------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVING AND REPLACING PARTS             | \$ 1,800.00 | <i>1000</i>   |
| 2   | SPRAY PAINTING TO AFFECTED AREA                         | \$ 1,800.00 | <i>1200</i>   |
| 3   | WIRING CHECK                                            | \$ 180.00   | <i>30</i>     |
| 4   | REMOVE AND REFIX THROTTLE BODY & MANIFOLD               | \$ 250.00   | <i>150</i>    |
| 5   | REMOVE AND REFIX DRIVER SEAT                            | \$ 120.00   | <i>60</i>     |
| 6   | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS | \$ 120.00   | <i>60</i>     |
| 7   | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST     | \$ 80.00    | <i>60</i>     |
| 8   | REFOCUS HEADLAMP BEAM                                   | \$ 60.00    | <i>+</i>      |

*2560*

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                          | PRICE       | ADJUSTED COST |
|-----|--------------------------------------------------------------------------|-------------|---------------|
| 1   | TO PANEL BEAT, WELD, CUT, GRAZE, KNOCK STRAIGHTEN, ADJUST AFFECTED PARTS | \$ 2,400.00 | <i>1400</i>   |
| 2   | TO PUTTY, SPRAY PAINT POLISH, WAX                                        | \$ 1,800.00 | <i>1200</i>   |

TO : **INCOME** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLZ3460G**  
 MODEL : **MIT-ATTRAGE**  
 DATE OF ACCIDENT : 22.06.2024  
 TIME OF ACCIDENT : 23:30 HOURS

|    |                                                                                                |           |      |
|----|------------------------------------------------------------------------------------------------|-----------|------|
| 3  | TO SPRAY TUFF COAT                                                                             | \$ 250.00 | 80   |
| 4  | WIRING, BULB CHECKING                                                                          | \$ 180.00 | 30   |
| 5  | REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR                                               | \$ 350.00 | 60   |
| 6  | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 180.00 | X    |
| 7  | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | \$ 80.00  | 50   |
| 8  | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                                           | \$ 80.00  | 50   |
| 9  | TRANSFER REAR DOOR MECHANISM                                                                   | \$ 80.00  | 60   |
| 10 | REMOVE AND REFIX REAR WINDSCREEN                                                               | \$ 120.00 | ✓    |
| 11 | REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT                                    | \$ 80.00  | X    |
| 12 | REMOVE AND REFIX FRONT AND REAR BUMPER LOWER SPOILER AND SIDE SKIRT                            | \$ 450.00 | X    |
| 13 | REMOVE AND REFIX EXHUAUST                                                                      | \$ 180.00 | 60.  |
| 14 | REAR CHASSIS ALIGNMENT                                                                         | \$ 250.00 | X    |
| 15 | REMOVE AND REFIX OFF-PECK SEAL                                                                 | \$ 120.00 | X 60 |
| 16 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | X    |

3170

**TOTAL \$ 11,190.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 41,703.00  
 TOTAL LABOUR COST : \$ 11,190.00  
 TOTAL REPAIR COST : \$ 52,893.00

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

Adrian L  
 2/s 25/06/24.  
 18 Days

total: 21518.71

2/s 17.2K

17.2K