


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 21.10.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBH5442J**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 10.10.2024
TIME OF ACCIDENT : 14:00 HOURS

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Defect</i>	1	\$ 1,480.00	\$ 1,480.00
2	TAILGATE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 324.00	\$ 324.00
4	TAILGATE WEATHERSTRIP <i>ton</i>	1	\$ 395.00	\$ 395.00
5	TAILGATE WEATHERSTRIP PROTECTOR <i>Best</i>	1	\$ 485.00	\$ 485.00
6	TAILGATE INNER LOCK <i>new</i>	1	\$ 420.00	\$ 420.00
7	TAILGATE LOWER LOCK <i>new</i>	1	\$ 45.00	\$ 45.00
8	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 240.00	\$ 240.00
9	TAILGATE REVERSE CAMERA <i>new</i>	1	\$ 1,314.00	\$ 1,314.00
10	TAIL LAMP <i>2x cracked</i>	2	\$ 380.00	\$ 760.00
11	TAILLAMP LOWER GARNISH <i>new</i>	2	\$ 298.00	\$ 596.00
12	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
13	REAR BUMPER <i>Defect</i>	1	\$ 479.00	\$ 479.00
14	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
15	REAR END PANEL (EXTEND) <i>Repair</i>	1	\$ 295.00	\$ 295.00
16	REAR END PANEL (INNER) <i>Repair</i>	1	\$ 871.00	\$ 871.00
17	REAR END PANEL (OUTER) <i>Defect</i>	1	\$ 597.00	\$ 597.00
18	REAR FLOOR PANEL MAT <i>3x1</i>	1	\$ 796.00	\$ 796.00
19	REAR FLOOR PANEL <i>new</i>	1	\$ 1,960.00	\$ 1,960.00
20	REAR SPARE TYRE HOLDER BRACKET <i>3x1</i>	1	\$ 380.00	\$ 380.00
21	REAR SPARE TYRE HOLDER BOLT <i>new</i>	1	\$ 60.00	\$ 60.00

285

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBH5442J**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.10.2024
 TIME OF ACCIDENT : 14:00 HOURS

22	TAILGATE STICKER "TOYOTA" <i>new</i>	1	\$ 68.50	\$ 68.50 <i>40</i>
23	TAILGATE STICKER "HIACE" <i>new</i>	1	\$ 63.80	\$ 63.80 <i>45</i>

4211

3158.25

TOTAL PRICE \$ 11,949.30
 LESS 25% \$ 2,987.33
SUB TOTAL PRICE \$ 8,961.98

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
4	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00 <i>15</i>
5	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
6	TAILGATE OUTER GARNISH CLIP <i>new</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
7	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
8	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
9	REAR FLOOR BOARD (WOODEN) <i>new</i>	1	\$ 1,800.00	\$ 1,800.00 <i>X</i>
10	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
11	REAR END PANEL (INNER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
12	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
13	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00 <i>+</i>
14	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00 <i>20</i>

375

TOTAL \$ 3,340.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,200.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>700</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBH5442J**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.10.2024
 TIME OF ACCIDENT : 14:00 HOURS

4	TRANSFER TAILGATE MECHAISM	\$ 80.00	60
5	REMOVE AND REFIX REAR FLOOR BOARD	\$ 350.00	X
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
8	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
9	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

1710

TOTAL \$ 5,190.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,301.98
 TOTAL LABOUR COST : \$ 5,190.00
 TOTAL REPAIR COST : \$ 17,491.98

Adrian Lj
 L/S 22/10/24
 06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Be Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 5243.25
 L/S: 4.2K ✓