



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100357/Aqh3e2
75 BRAS BASAH ROAD	Date:	11/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 1509T	Veh. Inspected	SMW 7637S
Policy No.	-	Coverage	0
Claim No.	MT/1300684-001	Excess	\$0.00
Assign From	SHAFAWATI	Assign Date	22/10/2024

### 2. Vehicle Details

Make & Model	MERCEDES BENZ CLA180	C.C	1595
Engine No.	27091030944561	Year of Reg.	20/09/2016
Chassis No.	WDD1173422N354519	Colour	SILVER
Odometer	105660 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40 R18	PIRELLI	6
L/H Front Tyre	225/40 R18	PIRELLI	6
R/H Rear Tyre	225/40 R18	PIRELLI	6
L/H Rear Tyre	225/40 R18	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/10/2024	Inspection Date	22/10/2024 (16:56)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days