

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE	CE LTD	Ref:	CS/INC24100358/Avh3m4	
75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	22/11/2024	
INCOME CENTRES	SINGAPORE 189557	Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNS 4628Y	Veh. Inspected	SLB 8890S	
Policy No.	-	Coverage	0	
Claim No.	MT/1300535-002	Excess	\$0.00	
Assign From	ASTER QUEK	Assign Date	22/10/2024	
2. Vehicle Details				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	L15B4027593	Year of Reg.	26/04/2016	
Chassis No.	RU11107588	Colour	RED	
Odometer	307439 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	215/60R16	GITI	6	
L/H Front Tyre	215/60R16	GITI	6	
R/H Rear Tyre	215/60R16	GITI	6	
J				
L/H Rear Tyre	215/60R16	GITI	6	
	215/60R16 Description of		6	
L/H Rear Tyre 4.		of Damages	6	
L/H Rear Tyre 4.	Description of Description of DAMAGES AT THE REAR PORTION	of Damages	6	
L/H Rear Tyre 4. THE VEHICLE SUSTAIN	Description of Description of DAMAGES AT THE REAR PORTION	of Damages	6	
L/H Rear Tyre 4. THE VEHICLE SUSTAINI DAMAGES SEE DETAILS	Description o ED DAMAGES AT THE REAR PORTION S.	of Damages	22/10/2024 (15:32)	
L/H Rear Tyre 4. THE VEHICLE SUSTAINI DAMAGES SEE DETAILS 5.	Description of ED DAMAGES AT THE REAR PORTIONS. General Info 20/10/2024 N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB	of Damages N. formation		
L/H Rear Tyre 4. THE VEHICLE SUSTAINI DAMAGES SEE DETAILS 5. Accident Date Survey held at	Description of ED DAMAGES AT THE REAR PORTIONS. General Info 20/10/2024 N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921	of Damages N. formation Inspection Date		
L/H Rear Tyre 4. THE VEHICLE SUSTAINI DAMAGES SEE DETAILS 5. Accident Date Survey held at	Description of ED DAMAGES AT THE REAR PORTIONS. General Into 20/10/2024 N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 Remains	of Damages N. formation Inspection Date		
L/H Rear Tyre 4. THE VEHICLE SUSTAINS DAMAGES SEE DETAILS 5. Accident Date Survey held at 5a. A) THE INSPECTION WA	Description of ED DAMAGES AT THE REAR PORTIONS. General Info 20/10/2024 N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921	formation Inspection Date arks JUDICE" BASIS.	22/10/2024 (15:32)	

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days