

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ROZALIE BIN JUMALUDIN
109 ANG MO KIO AVE 4 #12-20
SINGAPORE 560109

Contact : 90600414

TP / NC
Vezel

TAX INVOICE

Repair Code : CLM18429

Date in : 21/10/2024

Vehicle Num. : SLB8890S

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11107588/L15B4027593

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	463.70	✓ 463.70
REAR BUMPER LOWER COVER <i>Dented</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>Cracked</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>Scratched</i>	2	195.00	✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>Scratched</i>	2	23.00	+ 46.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>Cracked</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR <i>Cracked</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	98.00	✓ 98.00
REAR FENDER INNER TRIM GARNISH L/R <i>Cracked</i>	2	295.00	✓ 590.00
REAR FLOOR JACK PANEL <i>Scratched</i>	1	95.00	+ 95.00
REAR FLOOR PANEL <i>Cracked</i>	1	662.20	✓ 662.20
REAR FLOOR PANEL COMPARTMENT SPONGE TRAY <i>Cracked</i>	1	485.30	✓ 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Dented</i>	1	430.30	✓ 430.30
REAR TAILGATE <i>Dented</i>	1	953.30	✓ 953.30
REAR TAILGATE 'VEZEL' EMBLEM <i>Scratched</i>	1	56.20	✓ 56.20
REAR TAILGATE DAMPER L/R <i>Scratched</i>	2	180.00	+ 360.00
REAR TAILGATE HINGES L/R <i>Scratched</i>	2	50.00	+ 100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ROZALIE BIN JUMALUDIN
109 ANG MO KIO AVE 4 #12-20
SINGAPORE 560109

Contact : 90600414

TAX INVOICE

Repair Code : CLM18429
Date in : 21/10/2024
Vehicle Num. : SLB8890S
Model : HONDA VEZEL 1.5X CVT
Chassis/Eng# : RU11107588/L15B4027593

REAR TAILGATE INNER PULL GARNISH	new	1	153.40	+	153.40
REAR TAILGATE INNER SIDE GARNISH L/R	new	2	38.20	+	76.40
REAR TAILGATE INNER TRIM GARNISH	Cracked	1	180.00	✓	180.00
REAR TAILGATE MECHANISM LOCK	Damaged	1	180.00	✓	180.00
REAR TAILGATE MECHANISM LOCK STRIKER	new	1	27.50	+	27.50
REAR TAILGATE NUMBER PLATE LAMP L/R	new	2	38.50	+	77.00
REAR TAILGATE OUTER GARNISH	new	1	220.00	+	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	new	1	25.00	+	25.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	new	2	18.50	+	37.00
REAR TAILGATE WEATHER STRIP	torn	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN INNER SEAL	2 new	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN MOULDING	2 new	2	50.00	✓	100.00
Subtotal before discount					7,096.20
Percentage discount 20%					1,419.24
Sub-total 1					5,676.96
REAR BUMPER CLIPS - SET	new	1	50.00	50	50.00
REAR BUMPER REVERSE SENSOR	Damaged	1	280.00	280	280.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	new	2	30.00	+	60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ROZALIE BIN JUMALUDIN
109 ANG MO KIO AVE 4 #12-20
SINGAPORE 560109

Contact : 90600414

TAX INVOICE

Repair Code : CLM18429
Date in : 21/10/2024
Vehicle Num. : SLB8890S
Model : HONDA VEZEL 1.5X CVT
Chassis/Eng# : RU11107588/L15B4027593

REAR NUMBER PLATE	1	25.00	+	25.00
REAR NUMBER PLATE HOLDER	1	50.00	-	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS L/R	1	60.00	+	60.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	40.00	+	40.00
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	✓	60.00
Subtotal before discount				625.00
Percentage discount 0%				0.00
Sub-total 2				625.00
Parts-total				6,301.96

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1200 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	60 100.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	2,490.00
Parts & Labour Total	8,791.96

LKK Auto Consultants hence notify the Repairer of the following:


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey must be resurveyed and is subject to final approval from insurance company

*** This is a computer-generated document which requires no signature.***

Acknowledged by Repairer
Signature:
Date:

Adm L
2/s 22/10/24
06 Dmy
Supplementary: 1420.48
total: 8793.60
L/S : 71C ✓



Email: sales@n51.com.sg

SINGAPORE 560109

Chassis/Eng#: RU11107588/L15B4027593

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR TAILGATE REFLECTOR L/R <i>cont'd</i>	L	2	\$ 413.20	\$ 826.40
2	REAR TAILLAMP L/R <i>cont'd</i>	L	2	\$ 474.60	\$ 949.20
	Sub total before discount:				\$ 1,775.60
	Percentage discount 20%:				\$ 355.12
	Sub-total :				\$ 1,420.48
	Parts Total:				\$ 1,420.48

Adm. L.
L/s 23/10/24.

Supplementary: 1420.48