



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SFL 268K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR LH DOOR	DENTED	\$2,847.50	\$2,847.50
1	REAR LH DOOR CHECKER	NOT NECESSARY	\$151.70	\$0.00
1	REAR LH DOOR HINGES (BOTTOM)	NOT NECESSARY	\$145.60	\$0.00
1	REAR LH DOOR HINGES (TOP)	NOT NECESSARY	\$145.60	\$0.00
1	REAR LH DOOR INNER TRIM BOARD	NOT NECESSARY	\$741.20	\$0.00
1	REAR LH DOOR LOWER CHROME MOULDING	NOT NECESSARY	\$196.80	\$0.00
1	REAR LH DOOR OUTER CHROME MOULDING	NOT NECESSARY	\$176.40	\$0.00
1	REAR LH DOOR OUTER CHROME MOULDING (FRAME)	NOT NECESSARY	\$113.20	\$0.00
1	REAR LH DOOR OUTER HANDLE	CUT	\$217.60	\$217.60
1	REAR LH DOOR OUTER HANDLE INNER BRACKET	NOT NECESSARY	\$197.52	\$0.00
1	REAR LH DOOR WEATHER STRIP	NOT NECESSARY	\$187.40	\$0.00
	LESS 10.00% DISCOUNT		(\$512.05)	(\$306.51)
			\$4,608.47	\$2,758.59

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE		\$100.00	\$60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$600.00	\$250.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$500.00	\$200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$80.00	\$0.00
			\$1,280.00	\$510.00

GRAND TOTAL			\$5,888.47	\$3,268.59
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,600.00
--	---	--	--	-------------------

Report Ref No: CS/INC24100359/Avh3m4

TOTAL FOR SPARE PARTS: \$ 4,608.47 \$ 2,758.59
TOTAL FOR LABOUR : \$ 1,280.00 \$ 510.00
TOTAL REPAIR COST: \$ 5,888.47 \$ 3,268.59



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.