

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TP INC  
 Veron.

EMMANUEL DUNCAN CHUA  
 10 LORONG BIAWAK  
 SINGAPORE 358772

## TAX INVOICE

Repair Code : CLM18427

Date in : 21/10/2024

Vehicle Num. : SFL268K

Model : SKODA SUPERB L&K 2.0 TSI (A)

Chassis/Eng# : TMBBD7NP1K7032560/CHH300851

Contact : 93861902

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR LH DOOR <i>Dented</i>	1	2847.50	✓ 2,847.50
REAR LH DOOR CHECKER <i>3 pcs</i>	1	151.70	+ 151.70
REAR LH DOOR HINGES (BOTTOM)	1	145.60	+ 145.60
REAR LH DOOR HINGES (TOP)	1	145.60	+ 145.60
REAR LH DOOR INNER TRIM BOARD <i>3 pcs</i>	1	741.20	+ 741.20
REAR LH DOOR LOWER CHROME MOULDING <i>3 pcs</i>	1	196.80	+ 196.80
REAR LH DOOR OUTER CHROME MOULDING	1	176.40	+ 176.40
REAR LH DOOR OUTER CHROME MOULDING (FRAME) <i>1 pc</i>	1	113.20	+ 113.20
REAR LH DOOR OUTER HANDLE <i>1 pc</i>	1	217.60	✓ 217.60
REAR LH DOOR OUTER HANDLE INNER BRACKET <i>1 pc</i>	1	197.52	+ 197.52
REAR LH DOOR WEATHER STRIP <i>1 pc</i>	1	187.40	+ 187.40
Subtotal before discount			5,120.52
Percentage discount 10%			512.05
<b>Sub-total 1</b>			<b>4,608.47</b>
<b>Parts-total</b>			<b>5,120.52</b>

### LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

*60 100.00*  
*250 300 600.00*  
*200 500.00*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

EMMANUEL DUNCAN CHUA  
10 LORONG BIAWAK  
SINGAPORE 358772

Contact : 93861902

**TAX INVOICE**

Repair Code : CLM18427  
Date in : 21/10/2024  
Vehicle Num. : SFL268K  
Model : SKODA SUPERB L&K 2.0 TSI (A)  
Chassis/Eng# : TMBBD7NP1K7032560/CHH300851

To apply anti-rust chemical on repaired and replaced panel.

		80.00
<b>Labour Total</b>	510	<b>1,280.00</b>
<b>Parts &amp; Labour Total</b>		<b>6,400.52</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 2

Admin L  
L/S 22/10/24  
03 days

total: 3268.59

L/S: 2.6K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: