

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automobile	
MS	INCOME INSURANCE LTD		Ref:	CS/INC24100361/Avh3e2	
	75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	22/11/2024	
			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 4341X	Veh. Inspected	GBD 150E	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1300247-002	Excess	\$0.00	
	Assign From	AZHARI AFIDI	Assign Date	22/10/2024	
2.	Vehicle Details				
	Make & Model	TOYOTA DYNA	C.C	2982	
	Engine No.	1KD2371821	Year of Reg.	17/04/2014	
	Chassis No.	KDY2318014811	Colour	SILVER	
	Odometer	235164 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/75 R15C	KENDA	6	
	L/H Front Tyre	195/75 R15C	KENDA	6	
	R/H Rear Tyre	155 R13C	APLUS	6	
	L/H Rear Tyre	155 R13C	APLUS	6	
4.	Description of Damages				
		NED DAMAGES AT THE FRONT O/S F	PORTION.		
	IAGES SEE DETAI				
5.	General Information				
	Accident Date 17/10/2024 Inspection Date 22/10/2024 (15:26)				
	Survey held at N-51 AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.		Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate D	ays of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days