

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

1/8 8 6900  
5 days

not Authorized  
merans  
22/10/24  
Zehphel Heng

VEHICLE No: SMP 5456Y

## LKK Auto Consultants hence notify

the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts before repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1PC	TAILGATE	R		\$4,215.00	X
1PC	TAILGATE REAR LOGO	11		\$158.00	X
1PC	TAILGATE 'SKODA' EMBLEM	SUC		\$125.00	X
1PC	TAILGATE 'KODIAQ' EMBLEM	SUC		\$115.00	X
1PC	TAILGATE WEATHERSTRIP	SUC		\$495.00	X
1PC	TAILGATE INNER LOCK	11		\$655.00	X
1PC	REAR BUMPER TOP	22/10/24	3100.00	\$3,800.00	/
1PC	REAR BUMPER LOWER	21.5	1122.00	\$3,200.00	/
1PC	REAR BUMPER TOP BLACK CENTRE GARNISH	22/10/24	285.00	\$580.00	/
2PCS	REAR BUMPER LAMPS @\$215.00	11		\$430.00	X
2PCS	REAR BUMPER SIDE HOLDERS @\$148.00	11		\$296.00	X
1PC	REAR BUMPER SPONGE	20.1	231.00	\$366.00	/
1PC	REAR BUMPER REINFORCEMENT	NF		\$1,415.00	X
1PC	REAR BUMPER INNER TOP RETAINER	one	250.00	\$445.00	/
4PCS	REAR BUMPER PDC SENSORS @\$250.00	malfunction	215 x 2 = 430	\$1,000.00	22/10/24
1PC	REAR BUMPER PDC SENSOR WIRE	11		\$366.00	X
1PC	REAR BUMPER UNDER LOWER COVER	22/10/24	292.00	\$520.00	/
1SET	REAR BUMPER CLIPS	11		\$50.00	/
1PC	REAR END PANEL	22/10/24	856.00	\$1,400.00	/
1PC	REAR END PANEL TOP GARNISH	11		\$421.00	X
1PC	REAR FENDER OUTER PROTECTOR N/S	22/10/24	445.00	\$455.00	/
1PC	REAR EXHAUST ASSY	R		\$3,215.00	X
1PC	REAR EXHAUST MOUNTING	11		\$60.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$425.00	X
1PC	TAILLAMP N/S	one	690.00	\$980.00	/
1PC	REAR BLIND SPOT SENSOR UNIT	SUC		\$2,100.00	X
				\$27,287.00	

102

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$100.00	30
TO TRANSFER TAILGATE MECHANISM	11	\$120.00 X
TO DISMANTLE & REFIX REAR TAILGATE GLASS	11	\$150.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00 60
TO DISMANTLE & REPLACED REAR EXHAUST	11	\$180.00 X
TO SPRAY PROOFING		\$100.00 30
TO RESET & REPROGRAMME SYSTEM		\$180.00 50
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,200.00 600
TO PUTTY & SPRAY PAINTING		\$1,500.00 700
TOTAL	\$30,987.00	

2 7951  
10%  
715590