





# QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA  
 CHASSIS NO.: JM6BP2SAAK1102406  
 ENGINE NO.: P520634937  
 REG NO.: SMW8885K  
 REGN DATE: 12/10/2020

PAGE NO.: 1  
 DOCUMENT NO.: 2826  
 DOCUMENT DATE: 19/10/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV:  
 CSP/OP CODE: Lee Yao Sheng  
 DEPT: 1  
 WIP NO.: 16709  
 REF. NO.: DS/SMW8885K/2048  
 DATE IN: 18/10/2024  
 EXT. WTY: 11/10/2025  
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
NOTES	SMW8885K -TP Claim -MS First -DOA:17.10.24				0.00	0
SUB	TO REMOVE & REPLACE REAR BUMPER & END PANEL. ?			792	3,960.00	S
	AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT ? ,END PANEL & BOOTLID. X			1134	3,780.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	320.00	S
SUB	TO SUPPLY NUMBER PLATE. cm ✓				70.00	S
SUB	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			?	180.00	S
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			396?	792.00	S
SUB	TO REMOVE & INSTALL REAR EXHAUST ASSY.				792.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.			X	250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	250.00	S

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



# QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA  
 CHASSIS NO.: JM6BP2SAAK1102406  
 ENGINE NO.: P520634937  
 REG NO.: SMW8885K  
 REGN DATE: 12/10/2020

PAGE NO.: 3  
 DOCUMENT NO.: 2826  
 DOCUMENT DATE: 19/10/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV:  
 CSP/OP CODE: Lee Yao Sheng  
 DEPT: I  
 WIP NO.: 16709  
 REF. NO.: DS/SMW8885K/204  
 DATE IN: 18/10/2024  
 EXT. WTY: 11/10/2025  
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status		Gross amount	GST Code
				SGD	SGD		
BCJH-50-260	REINF.,REAR BUMPER BP <i>bt</i>	1.00	621.53	STOCK	621.53	S	
BCPV-67-UC5	RETAINER FRT SENSOR DM <i>n</i>	1.00	30.26	STOCK	30.26	S	
BCPT-67-UC5	RETAINER FRT SENSOR DM <i>n</i>	1.00	30.26	STOCK	30.26	S	
BOJ8-67-UC6	BRACKET B/SENSOR BPM <i>n</i>	2.00	26.89	STOCK	53.78	S	
BOY1-67-RC0A	CAMERA-BACK MONITOR BP <i>?</i>	1.00	1,164.83	*NO STOCK	1,164.83	S	
BOJ8-67-UC1	E4 SENSOR <del>FRT</del> BUMPER BP <i>(REAR)</i>	<del>1</del> 1.00	217.88	STOCK	871.52	S	
BOJ6-67-UC5	E4 RETAINER BP <i>X</i>	1.00	66.93	STOCK	66.93	S	
BOJ5-67-UC5	E4 RETAINER SENSOR BP <i>X</i>	1.00	66.93	STOCK	66.93	S	
BCKA-50-2B1A	PLATE SET LHR BUMPER BP <i>?</i>	1.00	115.14	STOCK	115.14	S	
BCKA-50-2A1A	PLATE SET RHR BUMPER BP <i>X</i>	1.00	115.14	STOCK	115.14	S	
BCWC-67-A20A	CORD RR BUMPER BP <i>?</i>	1.00	543.56	STOCK	543.56	S	
BCKA-50-EM1	TAPE,PROTECTOR <i>n</i>	3.00	7.42	STOCK	22.26	S	
BOJ8-51-160A	LAMP(L),RR COMB BP CLASSIC <i>?</i>	1.00	864.10	STOCK	864.10	S	
K123-51-039	GROMMET <i>X</i>	4.00	2.79	STOCK	11.16	S	
GA7B-51-146	GROMMET,SCREW-R.COMB <i>X</i>	6.00	2.53	STOCK	15.18	S	
BCJH-51-184	COVER LHR COMB BP <i>X</i>	1.00	14.84	STOCK	14.84	S	
BCJH-51-3G0B	LAMP(L),TRUNK LID SN BP <i>X</i>	1.00	561.85	STOCK	561.85	S	
EG21-51-146	FASTENER <i>X</i>	2.00	5.57	STOCK	11.14	S	
BCJH-51-3H8	GASKET,LAMP-LIFT GATE BP <i>X</i>	2.00	22.68	STOCK	45.36	S	
BCJH-51-721	ORNAMENT SN REAR BP <i>X</i>	1.00	39.62	STOCK	39.62	S	

This is only an estimate from our visual inspection and should there be more damages found during the process of work you will then be informed for your approval before proceeding with the repairs.

Please note that should you decide not to proceed with the repairs "a service quotation fee" with a maximum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Europe Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 6369 3003, BRN: 199103859N, GST Regn. No.: M90364005A

Branches & Service Centres:

3, Lida Close Singapore 408605

Sales Tel: 6395 8668 Service Tel: 6395 8899

Sales Fax: 6346 7000 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159075

Sales Tel: 6603 6718 Service Tel: 6603 6728

Sales Fax: 6476 7073 Service Fax: 6476 7417



# QUOTATION

**CODE:** F0001  
**CUSTOMER:** MS FIRST CAPITAL INSURANCE LTD  
**ADDRESS:** 16 RAFFLES QUAY #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
**ATTN:** MOTOR CLAIM DEPT  
**CONTACT NO.:** 6507 3848  
**MODEL:** MAZDA3 4DR 1.5 AT M-HYBRID CLA  
**CHASSIS NO.:** JM6BP2SAAK1102406  
**ENGINE NO.:** P520634937  
**REG NO.:** SMW8885K  
**REGN DATE:** 12/10/2020

**PAGE NO.:** 4  
**DOCUMENT NO.:** 2826  
**DOCUMENT DATE:** 19/10/2024  
**POS ID:** 12  
**PRINTED BY:** Lee Yao Sheng  
**SERVICE ADV:**  
**CSP/OP CODE:** Lee Yao Sheng  
**DEPT:** I  
**WIP NO.:** 16709  
**REF. NO.:** DS/SMW8885K/2048  
**DATE IN:** 18/10/2024  
**EXT. WTY:** 11/10/2025  
**MILEAGE:** 0

**DESCRIPTION:** Body repair

Item	Description	Qty.	Unit Price	Stk/Status		Gross amount	GST Code
				SGD	STOCK		
BCJH-51-771A	ORNAMENT RR SDN BP X	1.00	48.72	48.72	STOCK	48.72	S
11-M-HYBRID	EMBLEM RR M-HYBRID BP X	1.00	36.70	36.70	STOCK	36.70	S
BCYM-70-75Z	PANEL, REAR END BP ?	1.00	793.05	793.05	STOCK	793.05	S
BCJH-68-89XB	TRIM, TRUNK END BP X	1.00	79.32	79.32	STOCK	79.32	S
BCJH-68-894B	BEZEL, LOCK BP X	1.00	14.84	14.84	STOCK	14.84	S
BCJH-68-81XA	MAT(C) (110X110) BP X	1.00	671.34	671.34	STOCK	671.34	S
BCJH-68-8MYB	SUB TRUNK, ROOM RH BP X	1.00	246.54	246.54	STOCK	246.54	S
BCJH-68-8MZA	SUB TRUNK, ROOM LH BP X	1.00	201.03	201.03	STOCK	201.03	S
BCJH-56-451D	INSULATOR, HEAT BP X	1.00	67.85	67.85	STOCK	67.85	S
PY1C-40-100G	SILENCER, MAIN BP/BR X	1.00	1,704.51	1,704.51	*NO STOCK	1,704.51	S
PY1E-40-061B	RUBBER HANGER BP/DM ?	4.00	32.62	130.48	STOCK	130.48	S
PE23-40-305	GASKET EXHAUST KH m	1.00	27.23	27.23	STOCK	27.23	S
P5L2-40-600A	PIPE, MIDDLE CAT BP ?	1.00	2,080.51	2,080.51	STOCK	2,080.51	S
P549-40-305	GASKET ?	1.00	13.91	13.91	STOCK	13.91	S

*Repair*  
*4 deep*  
*22/10/24*  
*Rey b4*  
*permt*

	GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-			24,173.78	2,175.64	26,349.42
Surcharge	S	9.00%	24,173.78	2,175.64	0.00	0.00	0.00
Labour							
Menus							
<b>Amount Due</b>					<b>24,173.78</b>	<b>2,175.64</b>	<b>26,349.42</b>

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a maximum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

CASH / NETS / AMEX / VISA / MASTER / CHEQUE

Date: \_\_\_\_\_ Customer signature \_\_\_\_\_

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Authorised signature \_\_\_\_\_




## Mazda 3 Mild Hybrid 1.5A Classic

**\$88,800** Instalment \$1,004/mth

Apply for 2.48% loan

Shortlist

Get Warranty



### Overview Financial Photo Research

Depreciation	\$13,790 / year
Reg. Date	30-Oct-2020 (6yrs 6days COE left)
Manufactured	2019
Mileage	59,200 km (14.9k / year)
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	\$682 / year
Power	88.0 kW (118 bhp) <a href="#">View specs of the Mazda 3 Sedan Mild Hybrid (2019)</a>
Curb Weight	1,385 kg
Fuel Type	Petrol-Electric
COE	\$37,334
OMV	\$21,163
ARF	\$11,629
Dereg Value	\$31,194 as of today

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	013Z
Vehicle Details	
Vehicle No.:	SMW8885K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4DR 1.5 AT M-HYBRID CLASSIC
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	P520634937
Chassis No.:	JM6BP2SAAK1102406
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$21,303.00
Original Registration Date:	12 Oct 2020
First Registration Date:	12 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$11,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2030
PARF Rebate Amount:	\$8,868.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,534.00
COE Rebate Amount:	\$21,795.00
<b>Total Rebate Amount:</b>	<b>\$30,663.00</b>
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Oct 2024

OK