



# QUOTATION

CODE: F0001  
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
ADDRESS: 16 RAFFLES QUAY  
#42-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN:MOTOR CLAIM DEPT  
CONTACT NO.: 6507 3848  
MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA  
CHASSIS NO.: JM6BP2SAAK1102406  
ENGINE NO.: P520634937  
REG NO.: SMW8885K  
REGN DATE: 12/10/2020

PAGE NO.: 1  
DOCUMENT NO.: 2826  
DOCUMENT DATE: 19/10/2024  
POS ID:12  
PRINTED BY: Lee Yao Sheng  
SERVICE ADV:  
CSP/OP CODE: Lee Yao Sheng  
DEPT: I  
WIP NO.: 16709  
REF. NO.: DS/SMW8885K/2048  
DATE IN: 18/10/2024  
EXT. WTY: 11/10/2025  
MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	SMW8885K -TP Claim -MS First -DOA:17.10.24				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER & END PANEL. AND ALL ACCIDENT AFFECTED AREA.				3,960.00	S
SUB	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT ,END PANEL & BOOTLID.				3,780.00	S
SUB	TO TRANSFER REVERSE SENSORS.				330.00	S
SUB	TO SUPPLY NUMBER PLATE.				70.00	S
SUB	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING				180.00	S
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.				792.00	S
SUB	TO REMOVE & INSTALL REAR EXHAUST ASSY.				792.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.				250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				250.00	S

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

**ZOOM-ZOOM**

Showrooms & Service Centres :  
5 Ubi Close Singapore 408605      23 Leng Kee Road Singapore 159095  
Sales Tel: 6395 8888    Service Tel: 6395 8899    Sales Tel: 6603 6118    Service Tel: 6603 6128  
Sales Fax: 68461700    Service Fax: 6744 9402    Sales Fax: 6476 7073    Service Fax: 6476 7417



# QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA  
 CHASSIS NO.: JM6BP2SAAK1102406  
 ENGINE NO.: P520634937  
 REG NO.: SMW8885K  
 REGN DATE: 12/10/2020

PAGE NO.: 2  
 DOCUMENT NO.: 2826  
 DOCUMENT DATE: 19/10/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV:  
 CSP/OP CODE: Lee Yao Sheng  
 DEPT: I  
 WIP NO.: 16709  
 REF. NO.: DS/SMW8885K/2048  
 DATE IN: 18/10/2024  
 EXT. WTY: 11/10/2025  
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				300.00	S
SUB	SUNDRIES.				50.00	S
BCKA-50-221A	BREAR BUMPER BP	1.00	1,143.51	*NO STOCK STOCK	1,143.51	S
B45A-56-146A	FASTENER	8.00	2.36	*NO STOCK	18.88	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	STOCK	9.44	S
BCKA-50-0Z1	GROMMET,SCREW	4.00	2.36	STOCK	9.44	S
BOJ8-51-5M0	REFLECTOR LHR REFLEX SN BP	1.00	43.33	STOCK	43.33	S
BOJ8-51-5L0	REFLECTOR RHR REFLEX SN BP	1.00	43.33	STOCK	43.33	S
BCKA-50-EL1	BB COVER LHR TOWING HOOK BP	1.00	39.62	STOCK	39.62	S
BCKA-50-EK1	BBCOVER RHR TOWING HOOK BP	1.00	39.62	STOCK	39.62	S
BCKA-50-C51C	COVER,UNDER-REAR BP	1.00	72.57	STOCK	72.57	S
BCKA-50-290	STAY,RR BUMPER BP	1.00	105.45	STOCK	105.45	S
BCKA-50-2C0A	PLATE SET RR BUMPER BP	1.00	257.58	STOCK	257.58	S
BCKA-50-2J1	RETAINER LHR BUMPER BP	1.00	40.21	STOCK	40.21	S
BCKA-50-2H1	RETAINER RHR BUMPER BP	1.00	40.21	STOCK	40.21	S
BCKA-50-350	SHIELD LHR SPLASH BP	1.00	95.75	STOCK	95.75	S
GRT6-56-375	NUT CLIP	2.00	1.86	STOCK	3.72	S
BEPN-50-340	SHIELD RHR SPLASH BP	1.00	71.06	STOCK	71.06	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64		4.64	S

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

**ZOOM-ZOOM**

Showrooms & Service Centres :  
 5 Ubi Close Singapore 408605      23 Leng Kee Road Singapore 159095  
 Sales Tel: 6395 8888    Service Tel: 6395 8899    Sales Tel: 6603 6118    Service Tel: 6603 6128  
 Sales Fax: 68461700    Service Fax: 6744 9402    Sales Fax: 6476 7073    Service Fax: 6476 7417



# QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
 CONTACT NO.: 6507 3848  
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA  
 CHASSIS NO.: JM6BP2SAAK1102406  
 ENGINE NO.: P520634937  
 REG NO.: SMW8885K  
 REGN DATE: 12/10/2020

PAGE NO.: 3  
 DOCUMENT NO.: 2826  
 DOCUMENT DATE: 19/10/2024  
 POS ID: 12  
 PRINTED BY: Lee Yao Sheng  
 SERVICE ADV:  
 CSP/OP CODE: Lee Yao Sheng  
 DEPT: I  
 WIP NO.: 16709  
 REF. NO.: DS/SMW8885K/2048  
 DATE IN: 18/10/2024  
 EXT. WTY: 11/10/2025  
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
			SGD		SGD	
BCJH-50-260	REINF.,REAR BUMPER BP	1.00	621.53	STOCK	621.53	S
BCPV-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	STOCK	30.26	S
BCPT-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	STOCK	30.26	S
BOJ8-67-UC6	BRACKET B/SENSOR BP	2.00	26.89	STOCK	53.78	S
BOY1-67-RC0A	CAMERA-BACK MONITOR BP	1.00	1,164.83	*NO STOCK	1,164.83	S
BOJ8-67-UC1	E4 SENSOR FRT BUMPER BP	4.00	217.88	STOCK	871.52	S
BOJ6-67-UC5	E4 RETAINER BP	1.00	66.93	STOCK	66.93	S
BOJ5-67-UC5	E4 RETAINER SENSOR BP	1.00	66.93	STOCK	66.93	S
BCKA-50-2B1A	PLATE SET LHR BUMPER BP	1.00	115.14	STOCK	115.14	S
BCKA-50-2A1A	PLATE SET RHR BUMPER BP	1.00	115.14	STOCK	115.14	S
BCWC-67-A20A	CORD RR BUMPER BP	1.00	543.56	STOCK	543.56	S
BCKA-50-EM1	TAPE,PROTECTOR	3.00	7.42	STOCK	22.26	S
BOJ8-51-160A	LAMP(L),RR COMB BP CLASSIC	1.00	864.10	STOCK	864.10	S
K123-51-039	GROMMET	4.00	2.79	STOCK	11.16	S
GA7B-51-146	GROMMET,SCREW-R.COMB	6.00	2.53	STOCK	15.18	S
BCJH-51-184	COVER LHR COMB BP	1.00	14.84	STOCK	14.84	S
BCJH-51-3G0B	LAMP(L),TRUNK LID SN BP	1.00	561.85	STOCK	561.85	S
EG21-51-146	FASTENER	2.00	5.57	STOCK	11.14	S
BCJH-51-3H8	GASKET,LAMP-LIFT GATE BP	2.00	22.68	STOCK	45.36	S
BCJH-51-721	ORNAMENT SN REAR BP	1.00	39.62	STOCK	39.62	S

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

**ZOOM-ZOOM**

Showrooms & Service Centres :  
 5 Ubi Close Singapore 408605      23 Leng Kee Road Singapore 159095  
 Sales Tel: 6395 8888    Service Tel: 6395 8899    Sales Tel: 6603 6118    Service Tel: 6603 6128  
 Sales Fax: 68461700    Service Fax: 6744 9402    Sales Fax: 6476 7073    Service Fax: 6476 7417



# QUOTATION

**CODE:** F0001  
**CUSTOMER:** MS FIRST CAPITAL INSURANCE LTD  
**ADDRESS:** 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
**CONTACT NO.:** 6507 3848  
**MODEL:** MAZDA3 4DR 1.5 AT M-HYBRID CLA  
**CHASSIS NO.:** JM6BP2SAAK1102406  
**ENGINE NO.:** P520634937  
**REG NO.:** SMW8885K  
**REGN DATE:** 12/10/2020

**PAGE NO.:** 4  
**DOCUMENT NO.:** 2826  
**DOCUMENT DATE:** 19/10/2024  
**POS ID:** 12  
**PRINTED BY:** Lee Yao Sheng  
**SERVICE ADV:**  
**CSP/OP CODE:** Lee Yao Sheng  
**DEPT:** I  
**WIP NO.:** 16709  
**REF. NO.:** DS/SMW8885K/2048  
**DATE IN:** 18/10/2024  
**EXT. WTY:** 11/10/2025  
**MILEAGE:** 0

**DESCRIPTION:** Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
			SGD		SGD	
BCJH-51-771A	ORNAMENT RR SDN BP	1.00	48.72	STOCK	48.72	S
11-M-HYBRID	EMBLEM RR M-HYBRID BP	1.00	36.70	STOCK	36.70	S
BCYM-70-75Z	PANEL,REAR END BP	1.00	793.05	STOCK	793.05	S
BCJH-68-89XB	TRIM,TRUNK END BP	1.00	79.32	STOCK	79.32	S
BCJH-68-894B	BEZEL,LOCK BP	1.00	14.84	STOCK	14.84	S
BCJH-68-81XA	MAT(C) (110X110) BP	1.00	671.34	STOCK	671.34	S
BCJH-68-8MYB	SUB TRUNK,ROOM RH BP	1.00	246.54	STOCK	246.54	S
BCJH-68-8MZA	SUB TRUNK,ROOM LH BP	1.00	201.03	STOCK	201.03	S
BCJH-56-451D	INSULATOR,HEAT BP	1.00	67.85	STOCK	67.85	S
PY1C-40-100G	SILENCER,MAIN BP/BR	1.00	1,704.51	*NO STOCK	1,704.51	S
PY1E-40-061B	RUBBER HANGER BP/DM	4.00	32.62	STOCK	130.48	S
PE23-40-305	GASKET EXHAUST KH	1.00	27.23	STOCK	27.23	S
P5L2-40-600A	PIPE,MIDDLE CAT BP	1.00	2,080.51	STOCK	2,080.51	S
P549-40-305	GASKET	1.00	13.91		13.91	S

		* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	13,419.78	O	-					
Surcharge	0.00	S	9.00%	24,173.78	2,175.64			
Labour	10,754.00							
Menus	0.00							
<b>Gross</b>						<b>24,173.78</b>	<b>2,175.64</b>	<b>26,349.42</b>
<b>Less: Deposit**</b>						<b>0.00</b>	<b>0.00</b>	<b>0.00</b>
<b>Amount Due</b>						<b>24,173.78</b>	<b>2,175.64</b>	<b>26,349.42</b>

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*\*Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE  
No.

Date: \_\_\_\_\_

Customer signature \_\_\_\_\_

Authorised signature \_\_\_\_\_

**TRANS EUROKARS** Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147  
 Eurokars Group Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

**ZOOM-ZOOM**

**Showrooms & Service Centres :**  
 5 Ubi Close Singapore 408605      23 Leng Kee Road Singapore 159095  
 Sales Tel: 6395 8888    Service Tel: 6395 8899    Sales Tel: 6603 6118    Service Tel: 6603 6128  
 Sales Fax: 68461700    Service Fax: 6744 9402    Sales Fax: 6476 7073    Service Fax: 6476 7417