



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
CHASSIS NO.: JM6BP2SAAK1102406
ENGINE NO.: P520634937
REG NO.: SMW8885K
REGN DATE: 12/10/2020

PAGE NO.: 1
DOCUMENT NO.: 2826
DOCUMENT DATE: 19/10/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 16709
REF. NO.: DS/SMW8885K/2044
DATE IN: 18/10/2024
EXT. WTY: 11/10/2025
MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
		SGD			SGD	
NOTES	SMW8885K -TP Claim -MS First -DOA:17.10.24				0.00	0
SUB	TO REMOVE & REPLACE REAR BUMPER & END PANEL. ?		1584	792	3,960.00	S
	AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT ? ,END PANEL & BOOTLID. X		1890	1134	3,780.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO SUPPLY NUMBER PLATE. cm ✓				70.00	S
SUB	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			X11?	180.00	S
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.				396? 792.00	S
SUB	TO REMOVE & INSTALL REAR EXHAUST ASSY.				792.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.				nn X 250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				150 250.00	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN, 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
CHASSIS NO.: JM6BP2SAAK1102406
ENGINE NO.: P520634937
REG NO.: SMW8885K
REGN DATE: 12/10/2020


PAGE NO.: 2
DOCUMENT NO.: 2826
DOCUMENT DATE: 19/10/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 16709
REF. NO.: DS/SMW8885K/2048
DATE IN: 18/10/2024
EXT. WTY: 11/10/2025
MILEAGE: 0

DESCRIPTION: Body repair


Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				250 300.00	S
SUB	SUNDRIES.				20 50.00	S
BCKA-50-221AB	REAR BUMPER BP <i>ton</i>	1.00	1,143.51	*NO STOCK	1,143.51	S
B45A-56-146A	FASTENER <i>an</i>	8.00	2.36	*NO STOCK	18.88	S
BHN1-50-0Z1A	GROMMET, SCREW <i>an</i>	4.00	2.36	STOCK	9.44	S
BCKA-50-0Z1	GROMMET, SCREW <i>an</i>	4.00	2.36	STOCK	9.44	S
BOJ8-51-5M0	REFLECTOR LHR REFLEX SN BP <i>7 x suc</i>	1.00	43.33	STOCK	43.33	S
BOJ8-51-5L0	REFLECTOR RHR REFLEX SN BP <i>an</i>	1.00	43.33	STOCK	43.33	S
BCKA-50-EL1	BB COVER LHR TOWING HOOK BP <i>mis</i>	1.00	39.62	STOCK	39.62	S
BCKA-50-EK1	BB COVER RHR TOWING HOOK BP <i>mis</i>	1.00	39.62	STOCK	39.62	S
BCKA-50-C51C	COVER, UNDER-REAR BP <i>de</i>	1.00	72.57	STOCK	72.57	S
BCKA-50-290	STAY, RR BUMPER BP <i>7 x suc</i>	1.00	105.45	STOCK	105.45	S
BCKA-50-2C0A	PLATE SET RR BUMPER BP <i>7 x suc</i>	1.00	257.58	STOCK	257.58	S
BCKA-50-2J1	RETAINER LHR BUMPER BP <i>7 x suc</i>	1.00	40.21	STOCK	40.21	S
BCKA-50-2H1	RETAINER RHR BUMPER BP <i>7 x suc</i>	1.00	40.21	STOCK	40.21	S
BCKA-50-350	SHIELD LHR SPLASH BP <i>an</i>	1.00	95.75	STOCK	95.75	S
GRT6-56-375	NUT CLIP <i>an</i>	2.00	1.86	STOCK	3.72	S
BEPN-50-340	SHIELD RHR SPLASH BP <i>an</i>	1.00	71.06	STOCK	71.06	S
DFR5-50-251	BRACKET, BUMPER SKYACTIV <i>7 x suc</i>	1.00	4.64	STOCK	4.64	S

This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

Take note that should you decide not to proceed with the repairs "a service quotation fee" with a maximum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office: Trans Eurocars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 6369 3003, BRN: 199103859N, GST Regn. No.: M90364003A



Showrooms & Service Centres:
 510B, Clive Singapore 408605
 Sales Tel: 6395 8558 Service Tel: 6395 8899
 Sales Fax: 6466 7700 Service Fax: 6744 9402
 23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020

PAGE NO.: 3
 DOCUMENT NO.: 2826
 DOCUMENT DATE: 19/10/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV: Lee Yao Sheng
 CSP/OP CODE: Lee Yao Sheng
 DEPT: I
 WIP NO.: 16709
 REF. NO.: DS/SMW8885K/2044
 DATE IN: 18/10/2024
 EXT. WTY: 11/10/2025
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price		Stk/Status	Gross GST	
			SGD	SGD		amount	Code
BCJH-50-260	REINF., REAR BUMPER BP <i>bt</i>	1.00	621.53		STOCK	621.53	S
BCPV-67-UC5	RETAINER FRT SENSOR DM <i>n</i>	1.00	30.26		STOCK	30.26	S
BCPT-67-UC5	RETAINER FRT SENSOR DM <i>n</i>	1.00	30.26		STOCK	30.26	S
BOJ8-67-UC6	BRACKET B/SENSOR BPA <i>n</i>	2.00	26.89		STOCK	53.78	S
BOY1-67-RC0A	CAMERA-BACK MONITOR BP <i>? x su</i>	1.00	1,164.83		NO STOCK	1,164.83	S
BOJ8-67-UC1	E4 SENSOR EXT BUMPER BP <i>CREAR ? x su</i>	1.00	217.88		STOCK	871.52	S
BOJ6-67-UC5	E4 RETAINER BP <i>X n</i>	1.00	66.93		STOCK	66.93	S
BOJ5-67-UC5	E4 RETAINER SENSOR BP <i>X n</i>	1.00	66.93		STOCK	66.93	S
BCKA-50-2B1A	PLATE SET LHR BUMPER BP <i>X n</i>	1.00	115.14		STOCK	115.14	S
BCKA-50-2A1A	PLATE SET RHR BUMPER BP <i>X n</i>	1.00	115.14		STOCK	115.14	S
BCWC-67-A20A	CORD RR BUMPER BP <i>? n</i>	1.00	543.56		STOCK	543.56	S
BCKA-50-EM1	TAPE, PROTECTOR <i>n</i>	3.00	7.42		STOCK	22.26	S
BOJ8-51-160A	LAMP(L), RR COMB BP CLASSIC <i>? x su</i>	1.00	864.10		STOCK	864.10	S
K123-51-039	GROMMET <i>X n</i>	4.00	2.79		STOCK	11.16	S
GA7B-51-146	GROMMET, SCREW-R.COMB <i>X n</i>	6.00	2.53		STOCK	15.18	S
BCJH-51-184	COVER LHR COMB BP <i>X n</i>	1.00	14.84		STOCK	14.84	S
BCJH-51-3G0B	LAMP(L), TRUNK LID SN BP <i>X n</i>	1.00	561.85		STOCK	561.85	S
EG21-51-146	FASTENER <i>X n</i>	2.00	5.57		STOCK	11.14	S
BCJH-51-3H8	GASKET, LAMP-LIFT GATE BP <i>X n</i>	2.00	22.68		STOCK	45.36	S
BCJH-51-721	ORNAMENT SN REAR BP <i>X n</i>	1.00	39.62		STOCK	39.62	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a maximum of \$185.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No. M90364005A

EDITH-ZOOM!

23 Leng Kee Road Singapore 159095 Sales Tel: 6295 8888 Service Tel: 6395 8899 Sales Fax: 6446 7073 Service Fax: 6744 9402	23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 6476 7073 Service Fax: 6476 7417
---	---



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020

PAGE NO.: 4
 DOCUMENT NO.: 2826
 DOCUMENT DATE: 19/10/2024
 POS ID: 12
 PRINTED BY: Lee Yao Sheng
 SERVICE ADV: Lee Yao Sheng
 CSP/OP CODE: 1
 DEPT: 1
 WIP NO.: 16709
 REF. NO.: DS/SMW8885K/2048
 DATE IN: 18/10/2024
 EXT. WTY: 11/10/2025
 MILEAGE: 0

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BCJH-51-771A	ORNAMENT RR SDN BP <i>X 17</i>	1.00	48.72	STOCK	48.72	S
11-M-HYBRID	EMBLEM RR M-HYBRID BP <i>X 17</i>	1.00	36.70	STOCK	36.70	S
BCYM-70-75Z	PANEL, REAR END BP <i>? x size</i>	1.00	793.05	STOCK	793.05	S
BCJH-68-89XB	TRIM, TRUNK END BP <i>X 17</i>	1.00	79.32	STOCK	79.32	S
BCJH-68-894B	BEZEL, LOCK BP <i>X 17</i>	1.00	14.84	STOCK	14.84	S
BCJH-68-81XA	MAT(C) (110X110) BP <i>X 17</i>	1.00	671.34	STOCK	671.34	S
BCJH-68-8MYB	SUB TRUNK, ROOM RH BP <i>X 17</i>	1.00	246.54	STOCK	246.54	S
BCJH-68-8MZA	SUB TRUNK, ROOM LH BP <i>X 17</i>	1.00	201.03	STOCK	201.03	S
BCJH-56-451D	INSULATOR, HEAT BP <i>X 17</i>	1.00	67.85	STOCK	67.85	S
PY1C-40-100C	SILENCER, MAIN BP/BR <i>See photo? 22/10/24</i>	1.00	1,704.51	*NO STOCK	1,704.51	S
PY1E-40-061B	RUBBER HANGER BP/DM <i>? x size</i>	4.00	32.62	STOCK	130.48	S
PE23-40-305	GASKET EXHAUST KH <i>m</i>	1.00	27.23	STOCK	27.23	S
P5L2-40-600A	PIPE, MIDDLE CAT BP <i>? x size</i>	1.00	2,080.51	STOCK	2,080.51	S
P549-40-305	GASKET <i>? x size</i>	1.00	13.91	STOCK	13.91	S

Repair
4 days
Rey by paint

	GST Code	Rate	Service/Goods	GST
Parts	O	-	13,419.78	-
Surcharge	S	9.00%	24,173.78	2,175.64
Labour			10,754.00	
Menus			0.00	

	Before GST	GST	Total
Gross	24,173.78	2,175.64	26,349.42
Less: Deposit**	0.00	0.00	0.00
Amount Due	24,173.78	2,175.64	26,349.42

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Deposit to invoice No. _____

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
 No.

Date: _____ Customer signature _____ Acknowledged by Repairer _____ Authorised signature _____

TRANS EUROKARS Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN: 199103859H, G.P. No. M90364005A

Zoom-Zoom Showrooms & Service Centres:
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6646 1700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020


PAGE NO.: 2
 DOCUMENT NO.: 2914
 DOCUMENT DATE: 20/11/2024
 POS ID: 12
 PRINTED BY: Moo Wen Zheng
 SERVICE ADV:
 CSP/OP CODE: Moo Wen Zheng
 DEPT: I
 WIP NO.: 16709
 REF. NO.: DS/SMW8885K/2044
 DATE IN: 25/10/2024
 EXT. WTY: 11/10/2025
 MILEAGE: 66,103

DESCRIPTION: Body repair


Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BCKA-50-C51C	COVER,UNDER-REAR BP	1.00	72.57	*ISSUED	72.57	S
BCJH-50-260	REINF.,REAR BUMPER BP	1.00	621.53	*ISSUED	621.53	S
BCPV-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	*ISSUED	30.26	S
BCPT-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	*ISSUED	30.26	S
BOJ8-67-UC6	BRACKET B/SENSOR BP	2.00	26.89	*ISSUED	53.78	S
BCKA-50-EM1	TAPE,PROTECTOR	3.00	7.42	*ISSUED	22.26	S
PY1C-40-100G	SILENCER,MAIN BP/BR <i>bt</i>	1.00	1,704.51	*ISSUED	1,704.51	S
PE23-40-305	GASKET EXHAUST KH <i>ne</i>	1.00	27.23	*ISSUED	27.23	S
BOJ8-67-UC1 E4	SENSOR FRT BUMPER BP <i>new</i>	1.00	217.88	*ISSUED	217.88	S
BOJ8-51-26YA	LAMP, LICENSE BP <i>com</i>	1.00	130.31	*ISSUED	130.31	S
KD45-67-6NYA	CLIP,ANTENNA <i>m</i>	1.00	2.36	*ISSUED	2.36	S
KD47-67-6NXA	ANTENNA,LF S/ACTIV <i>com</i>	1.00	119.35	*ISSUED	119.35	S
BOJ8-51-5M0	REFLECTOR LHR REFLEX SN BP <i>sc</i>	1.00	43.33	*ISSUED	43.33	S
BCKA-50-290	STAY,RR BUMPER BP <i>ne</i>	1.00	105.45	*ISSUED	105.45	S
BCKA-50-2COA	PLATE SET RR BUMPER BP <i>bt</i>	1.00	257.58	*ISSUED	257.58	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV <i>m</i>	1.00	4.64	*ISSUED	4.64	S
BCKA-50-2B1A	PLATE SET LHR BUMPER BP <i>bt</i>	1.00	115.14	*ISSUED	115.14	S
PY1E-40-061B	RUBBER HANGER BP/DM <i>ne</i>	1.00	32.62	*ISSUED	32.62	S
P5L2-40-600A	PIPE,MIDDLE CAT BP <i>bt</i>	1.00	2,080.51	*ISSUED	2,080.51	S
P549-40-305	GASKET <i>m</i>	1.00	13.91	*ISSUED	13.91	S

"This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Easirkars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3603, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A



Branches & Service Centres :
 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899
 23 Leng Kee Road Singapore 159095 Sales Tel: 6403 6118 Service Tel: 6603 6128
 Sales Fax: 6846 1759 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417