



Finalization QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020

PAGE NO.: 1
 DOCUMENT NO.: 2914
 DOCUMENT DATE: 20/11/2024
 POS ID:12
 PRINTED BY: Moo Wen Zheng
 SERVICE ADV:
 CSP/OP CODE: Moo Wen Zheng
 DEPT: I
 WIP NO.: 16709
 REF. NO.: DS/SMW8885K/2048
 DATE IN: 25/10/2024
 EXT. WTY: 11/10/2025
 MILEAGE: 66,103

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
NOTES	TP CLAIM - FIRST CAPITAL DOA 17/10/2024				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER & END PANEL AND ALL ACCIDENT AFFECTED AREA.				1,584.00	S
SUB	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT ,END PANEL & BOOTLID.				1,890.00	S
SUB	TO TRANSFER REVERSE SENSORS.				180.00	S
SUB	TO SUPPLY NUMBER PLATE.				70.00	S
SUB	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.				396.00	S
SUB	TO REMOVE & INSTALL REAR EXHAUST ASSY.				792.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIO				150.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WO				250.00	S
SUB	SUNDRIES.				20.00	S
	BCKA-50-221ABREAR BUMPER BP	1.00	1,143.51	*ISSUED	1,143.51	S
	B45A-56-146A FASTENER	8.00	2.36	*ISSUED	18.88	S
	BHN1-50-0Z1A GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
	BCKA-50-0Z1 GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
	BCKA-50-EL1 BB COVER LHR TOWING HOOK BP	1.00	39.62	*ISSUED	39.62	S
	BCKA-50-EK1 BBCOVER RHR TOWING HOOK BP	1.00	39.62	*ISSUED	39.62	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :
 5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN:MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020

PAGE NO.: 2
 DOCUMENT NO.: 2914
 DOCUMENT DATE: 20/11/2024
 POS ID: 12
 PRINTED BY: Moo Wen Zheng
 SERVICE ADV:
 CSP/OP CODE: Moo Wen Zheng
 DEPT: I
 WIP NO.: 16709
 REF. NO.: DS/SMW8885K/2048
 DATE IN: 25/10/2024
 EXT. WTY: 11/10/2025
 MILEAGE: 66,103

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
BCKA-50-C51C	COVER,UNDER-REAR BP	1.00	72.57	*ISSUED	72.57	S
BCJH-50-260	REINF.,REAR BUMPER BP	1.00	621.53	*ISSUED	621.53	S
BCPV-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	*ISSUED	30.26	S
BCPT-67-UC5	RETAINER FRT SENSOR DM	1.00	30.26	*ISSUED	30.26	S
BOJ8-67-UC6	BRACKET B/SENSOR BP	2.00	26.89	*ISSUED	53.78	S
BCKA-50-EM1	TAPE,PROTECTOR	3.00	7.42	*ISSUED	22.26	S
PY1C-40-100G	SILENCER,MAIN BP/BR	1.00	1,704.51	*ISSUED	1,704.51	S
PE23-40-305	GASKET EXHAUST KH	1.00	27.23	*ISSUED	27.23	S
BOJ8-67-UC1 E4	SENSOR FRT BUMPER BP	1.00	217.88	*ISSUED	217.88	S
BOJ8-51-26YA	LAMP, LICENSE BP	1.00	130.31	*ISSUED	130.31	S
KD45-67-6NYA	CLIP,ANTENNA	1.00	2.36	*ISSUED	2.36	S
KD47-67-6NXA	ANTENNA,LF S/ACTIV	1.00	119.35	*ISSUED	119.35	S
BOJ8-51-5M0	REFLECTOR LHR REFLEX SN BP	1.00	43.33	*ISSUED	43.33	S
BCKA-50-290	STAY,RR BUMPER BP	1.00	105.45	*ISSUED	105.45	S
BCKA-50-2C0A	PLATE SET RR BUMPER BP	1.00	257.58	*ISSUED	257.58	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64	*ISSUED	4.64	S
BCKA-50-2B1A	PLATE SET LHR BUMPER BP	1.00	115.14	*ISSUED	115.14	S
PY1E-40-061B	RUBBER HANGER BP/DM	1.00	32.62	*ISSUED	32.62	S
P5L2-40-600A	PIPE,MIDDLE CAT BP	1.00	2,080.51	*ISSUED	2,080.51	S
P549-40-305	GASKET	1.00	13.91		13.91	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
 5 Ubi Close Singapore 408605
 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Fax: 68461700 Service Fax: 6744 9402
 23 Leng Kee Road Singapore 159095
 Sales Tel: 6603 6118 Service Tel: 6603 6128
 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
 ADDRESS: 16 RAFFLES QUAY
 #42-01
 HONG LEONG BUILDING
 SINGAPORE 048581
 ATTN: MOTOR CLAIM DEPT
 CONTACT NO.: 6507 3848
 MODEL: MAZDA3 4DR 1.5 AT M-HYBRID CLA
 CHASSIS NO.: JM6BP2SAAK1102406
 ENGINE NO.: P520634937
 REG NO.: SMW8885K
 REGN DATE: 12/10/2020

PAGE NO.: 3
 DOCUMENT NO.: 2914
 DOCUMENT DATE: 20/11/2024
 POS ID: 12
 PRINTED BY: Moo Wen Zheng
 SERVICE ADV: Moo Wen Zheng
 CSP/OP CODE: I
 DEPT: 16709
 WIP NO.: DS/SMW8885K/2048
 REF. NO.: 25/10/2024
 DATE IN: 11/10/2025
 EXT. WTY: 66,103
 MILEAGE:

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-					
Surcharge	S	9.00%	12,277.99	1,105.02	12,277.99	1,105.02	13,383.01
Labour							
Menus							
Gross					12,277.99	1,105.02	13,383.01
Less: Deposit**					0.00	0.00	0.00
Amount Due					12,277.99	1,105.02	13,383.01

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date: _____

Customer signature _____

Authorised signature _____

TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
 Eurokars Group Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417