

Date: 21/10/2024
Vehicle No: SNQ6598Y
Model: BYD SEAL
Chassis: LGXXCF6CD0P2166145
Reg. Year: 2024

Not Authorized
Murray Alta Pairy
4 day
Q 2763.50

Third Party Insurer: MSIG
Third Party Veh No: SMT8924Y
Date of Accident: 20/10/2024
Estimator: JONATHAN
Surveyor:

P# 2678

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER			REPAIR \$ 1,040.00 ✓
	LHR FENDER FIX GLASS			REPAIR
	LHR FENDER			REPAIR
	LHR DOOR			\$ 640.00 ✓
	LHR DOOR WINDOW GLASS			\$ 320.00 ✓
	LHR DOOR EXT. TRIM PANEL			\$ 65.00 ✓
	LHR WHEEL COVER			\$ 2,430.00 X
	LHR RIM			
			SUB TOTAL	\$ 4,495.00
			Less 10%	\$ 449.50
			PARTS TOTAL	\$ 4,045.50

2065
- 10%
1858.5

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	LHR FIX GLASS SEALANT			\$ 30.00 ✓
	LHS LIVERY			\$ 800.00 X
			S/N TOTAL	\$ 830

LABOUR CHARGES:

To remove, replace, repair, readjust & refix Side affected areas	\$ 400.00 200
To perform wiring checks on electrical systems	\$ 30.00 15
To remove, putty, repair, sand and respray affected areas	\$ 600.00 ✓
To remove, replace & refix bumper sensors	\$ 30.00 X
To remove, replace & reinstall Door inner mechanisms	\$ 30.00 X
To remove, refix & replace Side Quarter Glass	\$ 80.00 60

PARTS: 1858.5
LHR: 830
LABOUR: 875
TOTAL: 3563.5

LABOUR TOTAL	\$ 1,170.00
TOTAL	\$ 6,045.50

JONATHAN