

REF: CS/LIP24100367/Avh3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in \_\_\_\_\_ vehicle No: \_\_\_\_\_

at \_\_\_\_\_

of \_\_\_\_\_

Insured: SKA 1551J

Policy No: \_\_\_\_\_

Claims No: AVS24/3263

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLC2159E Yr Regn: 2016, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan X-Trail o.d. 1997

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 186196 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1JANT32Z00C2026

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60R18

R: 225/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Tower

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 10/10/2024 D.O.I. 22/10/24

Survey held at TSV

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Pisat o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Liberty
21/7/25	Adrian confirmed LS \$4600 (Red 11,461.95, 71%) COE Expiry!
	Estimate given during: Yes (✓) 1st Survey: No ( )
	MV: 331C
	PV: 20.6K
	Nett: 12.4K
	A57A

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2)

Report Format:

Region: \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Inve (\$)

Survey Fee:

Transportation:

B + RS: \$

Photos

Others


TCL Pro Selection Pte Ltd  
 Block 1 Kaki Bukit Ave 6  
 #01-06 Autobay@Kaki Bukit  
 Singapore 417883

SLC2159E Nissan X trail

No	Qty	Parts Description	Condition	Estimated Parts Price
1	1	Front bumper assy <i>Delud</i>		\$ 1,680.00 ✓
2	1	Front bumper reinforcement <del>new</del> <i>Delud</i>		\$ 495.00 ✓
3	2	Front bumper bracket <i>new</i>		\$ 86.00 +
4	2	Front bumper retainer <i>new</i>		\$ 88.00 +
5	1	Front bumper right fog lamp garnish <i>Delud</i>		\$ 167.00 ✓
6	1	Front bumper lower lip <i>New</i>		\$ 1,250.00 +
7	1	Front bumper lower chrome moulding <i>new</i>		\$ 850.00 ✓
8	1	Front right fog lamp <i>Delud</i>		\$ 288.00 ✓
9	1	Front grille assy <i>Delud</i>		\$ 385.00 ✓
10	1	Front grille chrome moulding <i>new</i>		\$ 285.00 +
11	1	Front grille emblem <i>new</i>		\$ 88.00 ✓
12	1	Front right fender <i>Reps</i>		\$ 1,267.00 ✓
13	1	Front right fender inner cowling <i>new</i>		\$ 215.00 +
14	1	Front right fender protector <i>Delud</i>		\$ 195.00 -
15	1	Front bonnet assy		\$ 2,655.00 +
16	1	Front support panel top cover		\$ 175.00 +
17	1	Front support panel assy		\$ 1,456.00 +
18	1	Front bonnet lock		\$ 225.00 +
19	2	Front right HID headlamp <i>Delud</i>		\$ 6,450.00 ✓
20	1	Front right HID headlamp module <i>New</i>		\$ 687.00 +
21	4	Front support panel rubber stopper <i>new</i>		\$ 38.00 +
				\$ 19,025.00
Less 10%				\$ 1,902.50
				\$ 17,122.50
<u>Special Nett Items</u>				
1	12	Front bumper clips <i>new</i>		\$ 60.00 <i>30</i>
2	4	Front grille clips <i>new</i>		\$ 30.00 <i>20</i>
3	1	Front no plate with garnish <i>new</i>		\$ 100.00 +
4	6	Front right fender inner cowling clips <i>new</i>		\$ 30.00 +
5	6	Front right fender protector clips <i>new</i>		\$ 30.00 <i>20</i>
6	6	Front support panel top cover clips <i>new</i>		\$ 30.00 +
				\$ 280.00
<b>Total parts</b>				\$ 17,402.50

\$ 3465.10 per Pcs ✓

22) Front inner sponge bumper *Delud* \$ 382.50 ✓  
 23) Wiper tank *Delud* \$ 415.50 ✓

**Pro Selection Pte Ltd**  
**Block 1 Kaki Bukit Ave 6**  
**#01-06 Autobay@Kaki Bukit**  
**Singapore 417883**

**SLC2159E Nissan X trail**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front left damaged parts.	\$ 1,400.00 400
2	To putty and spray painting front right portion.	\$ 1,400.00 600
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front lock mechanism.	\$ 80.00 x
5	To apply anti rust proofing to front right affected area.	\$ 120.00 30
6	Towing service.	\$ 100.00 x
<b>Total labour :</b>		<b>\$ 3,150.00</b>

**Total parts : \$ 17,402.50**  
**Total labour : \$ 3,150.00**  
**Total repair cost : \$ 20,552.50**

*Adrian Lij*  
 1/s 22/10/24

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature:  
 Date: