

TCL Pro Selection Pte Ltd
Block 1 Kaki Bukit Ave 6
#01-06 Autobay@Kaki Bukit
Singapore 417883

SLC2159E Nissan X trail

No	Qty	Parts Description	Condition	Estimated Parts Price
1	1	Front bumper assy <i>Behind</i>		\$ 1,680.00 ✓
2	1	Front bumper reinforcement new <i>Darked</i>		\$ 495.00 + ✓
3	2	Front bumper bracket <i>new</i>		\$ 86.00 +
4	2	Front bumper retainer <i>new</i>		\$ 88.00 +
5	1	Front bumper right fog lamp garnish <i>curled</i>		\$ 167.00 ✓
6	1	Front bumper lower lip <i>new</i>		\$ 1,250.00 +
7	1	Front bumper lower chrome moulding <i>new</i>		\$ 850.00 ✓
8	1	Front right fog lamp <i>curled</i>		\$ 288.00 ✓
9	1	Front grille assy <i>curled</i>		\$ 385.00 ✓
10	1	Front grille chrome moulding <i>new</i>		\$ 285.00 +
11	1	Front grille emblem <i>new</i>		\$ 88.00 ✓
12	1	Front right fender <i>Right</i>		\$ 1,267.00 ✓
13	1	Front right fender inner cowling <i>new</i>		\$ 215.00 +
14	1	Front right fender protector <i>Behind</i>		\$ 195.00 -
15	1	Front bonnet assy		\$ 2,655.00 +
16	1	Front support panel top cover		\$ 175.00 +
17	1	Front support panel assy		\$ 1,456.00 +
18	1	Front bonnet lock		\$ 225.00 +
19	2	Front right HID headlamp <i>curled</i>		\$ 6,450.00 ✓
20	1	Front right HID headlamp module <i>new</i>		\$ 687.00 +
21	4	Front support panel rubber stopper <i>new</i>		\$ 38.00 +
				\$ 19,025.00
Less 10%				\$ 1,902.50
				\$ 17,122.50

Special Nett Items

1	12	Front bumper clips <i>new</i>	\$ 60.00 30
2	4	Front grille clips <i>new</i>	\$ 30.00 20
3	1	Front no plate with garnish <i>new</i>	\$ 100.00 +
4	6	Front right fender inner cowling clips <i>new</i>	\$ 30.00 +
5	6	Front right fender protector clips <i>new</i>	\$ 30.00 20
6	6	Front support panel top cover clips <i>new</i>	\$ 30.00 +
			\$ 280.00

Total parts

\$ 17,402.50

22) Front inner sponge bumper *curled*

\$ 382.50 ✓

23) Wiper tank *Behind*

\$ 415.50 ✓

Pro Selection Pte Ltd
Block 1 Kaki Bukit Ave 6
#01-06 Autobay@Kaki Bukit
Singapore 417883

SLC2159E Nissan X trail

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front left damaged parts.	\$ 1,400.00 400
2	To putty and spray painting front right portion.	\$ 1,400.00 600
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front lock mechanism.	\$ 80.00 x
5	To apply anti rust proofing to front right affected area.	\$ 120.00 30
6	Towing service.	\$ 100.00 x
Total labour :		\$ 3,150.00

Total parts : \$ 17,402.50
Total labour : \$ 3,150.00
Total repair cost : \$ 20,552.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
1/s 22/10/24