

ASS. REC. BY:

REF:

AG2 /

CS/AG124100368/knp3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 7832A

Yr Regn:

06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Priente

C.C.

Wagon 1496

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

441847

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NHP170

7109583

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Dun

185/60R15

R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

20/10/24

D.O.I.

23/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got B2

8/11 112m @ 12,000 Carpal (Red, \$ 22020.40, 64%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

11

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 034J

### Vehicle Details

Vehicle No.: SMC7832A  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 21 Oct 2024  
Vehicle Make: TOYOTA  
Vehicle Model: SIENTA HYBRID 1.5G CVT  
Primary Colour: Brown  
Manufacturing Year: 2017  
Engine No.: 1NZ8394417  
Chassis No.: NHP1707109583  
Maximum Power Output: 73.0 kW (97 bhp)  
Open Market Value: \$24,078.00  
Original Registration Date: 23 Jul 2018  
First Registration Date: 23 Jul 2018  
Transfer Count: 1  
Actual ARF Paid: \$25,710.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 22 Jul 2028  
PARF Rebate Amount: \$16,711.00

### Intended COE Rebate Details

COE Expiry Date: 22 Jul 2028  
COE Category: E - Open - all except motorcycle  
COE Period(Years): 10  
QP Paid: \$31,001.00  
COE Rebate Amount: \$9,381.00  
**Total Rebate Amount: \$26,092.00**

### Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 21 Oct 2024

OK



Budget Direct Insurance  
190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924

Attn: Motor Claim Dept

CHASSIS : NHP1707109583

# Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive  
#02-05 Sin Ming Autocare  
Singapore 575721  
Tel : 6455 0600 | Fax : 6455 6192  
Website: www.autocare.com.sg  
GST Reg. No: 20-0210033-N

*NOT Withain  
11 Day \$12,000p  
Return After Rain*

## ESTIMATE

VEHICLE NO: SMC7832A

MAKE/MODEL: TOYOTA SIENTA

DOA: 20.10.24

*11 days*

| No.        | Descriptions                      | Qty           | Unit Price | Amount S\$                  |
|------------|-----------------------------------|---------------|------------|-----------------------------|
| LIST ITEM: |                                   |               |            |                             |
| 1          | FRONT GRILLE <i>870.50</i>        | 1             | 1,215.20   | <i>CN</i> 1,215.20 <i>—</i> |
| 2          | FRONT GRILLE EMBLEM               | 1             | 80.60      | <i>na</i> 80.60 <i>—</i>    |
| 3          | HEAD LAMP LH                      | <i>mjcm</i> 1 | 1,551.30   | 1,551.30 <i>—</i>           |
| 4          | HEAD LAMP RH                      | 1             | 1,551.30   | 1,551.30 <i>—</i>           |
| 5          | FRONT BUMPER CENTRE GRILLE        | 1             | 185.30     | <i>na</i> 185.30 <i>—</i>   |
| 6          | FRONT BUMPER SPONGE               | 1             | 110.20     | <i>na</i> 110.20 <i>—</i>   |
| 7          | FRONT BUMPER REINFORCEMENT        | 1             | 552.30     | <i>na</i> 552.30 <i>—</i>   |
| 8          | BONNET                            | 1             | 940.70     | <i>na</i> 940.70 <i>—</i>   |
| 9          | BONNET HINGE LH                   | 1             | 92.50      | <i>na</i> 92.50 <i>—</i>    |
| 10         | BONNET HINGE RH                   | 1             | 92.50      | <i>na</i> 92.50 <i>—</i>    |
| 11         | LOWER BONNET LOCK                 | 1             | 129.90     | <i>na</i> 129.90 <i>—</i>   |
| 12         | BONNET LOCK CABLE                 | 1             | 76.10      | <i>na</i> 76.10 <i>X</i>    |
| 13         | FRONT BUMPER TOP BEAM             | 1             | 122.40     | <i>na</i> 122.40 <i>—</i>   |
| 14         | WIPER GARNISH                     | 1             | 385.30     | <i>na</i> 385.30 <i>X</i>   |
| 15         | BONNET INSULATOR CLIP             | 1             | 5.50       | <i>na</i> 5.50 <i>X</i>     |
| 16         | FRONT BUMPER                      | 1             | 527.10     | <i>na</i> 527.10 <i>—</i>   |
| 17         | FRONT BUMPER CLIPS                | 10            | 5.50       | <i>na</i> 55.00 <i>—</i>    |
| 18         | FRONT SUPPORT PANEL <i>891.60</i> | 1             | 1,571.40   | <i>na</i> 1,571.40 <i>—</i> |
| 19         | FRONT SUPPORT PANEL TOP GARNISH   | 1             | 178.90     | <i>na</i> 178.90 <i>X</i>   |
| 20         | SUPPORT PANEL TOP GARNISH CLIPS   | 10            | 5.50       | <i>na</i> 55.00 <i>X</i>    |
| 21         | HEAD LAMP PANEL LH                | 1             | 109.40     | <i>na</i> 109.40 <i>—</i>   |
| 22         | HEAD LAMP PANEL RH                | 1             | 109.40     | <i>na</i> 109.40 <i>—</i>   |
| 23         | AIR CON CONDENSER <i>1298.60</i>  | 1             | 1,886.70   | <i>na</i> 1,886.70 <i>—</i> |
| 24         | RADIATOR <i>1899.60</i>           | 1             | 3,571.20   | <i>na</i> 3,571.20 <i>—</i> |
| 25         | RADIATOR FAN MOTOR                | 1             | 919.70     | <i>na</i> 919.70 <i>X</i>   |
| 26         | RADIATOR FAN COWLING              | 1             | 469.50     | <i>na</i> 469.50 <i>X</i>   |
| 27         | REAR TAIL LAMP RH                 | 1             | 625.30     | <i>na</i> 625.30 <i>X</i>   |
| 28         | REAR TAIL LAMP LH                 | 1             | 625.30     | <i>na</i> 625.30 <i>X</i>   |
| 29         | REAR BUMPER                       | 1             | 489.60     | <i>mjcm</i> 489.60 <i>—</i> |
| 30         | REAR BUMPER SIDE GARNISH LH       | 1             | 178.90     | <i>na</i> 178.90 <i>X</i>   |
| 31         | REAR BUMPER SIDE GARNISH RH       | 1             | 178.90     | <i>na</i> 178.90 <i>X</i>   |
| 32         | REAR WHEEL BEARING                | 1             | 1,193.40   | <i>na</i> 1,193.40 <i>X</i> |
| 33         | REAR BUMPER SIDE RETAINER LH      | 1             | 152.80     | <i>na</i> 152.80 <i>X</i>   |
| 34         | REAR FENDER SIDE GARNISH LH       | 1             | 178.90     | <i>na</i> 178.90 <i>X</i>   |
| 35         | REAR BUMPER REFLECTOR RH          | 1             | 83.40      | <i>na</i> 83.40 <i>—</i>    |
| 36         | REAR BUMPER REFLECTOR LH          | 1             | 83.40      | <i>na</i> 83.40 <i>X</i>    |
| 37         | REAR ABSORBER                     | 1             | 304.80     | <i>na</i> 304.80 <i>X</i>   |
| 38         | REAR TAIL GATE LOCK <i>359.40</i> | 1             | 647.90     | <i>na</i> 647.90 <i>—</i>   |
| 39         | REAR TAIL GATE <i>1401.20</i>     | 1             | 1,726.80   | <i>na</i> 1,726.80 <i>—</i> |

- 40 REAR TAIL GATE CENTRE GARNISH  
41 REAR TAIL GATE LOGO  
42 REAR TAIL GATE EMBLEM (HYBRID)  
43 REAR TAIL GATE WIPER MOTOR **655**  
44 REAR TAIL GATE WIPER ARM  
45 REAR TAIL GATE WIPER ARM COVER  
46 REAR END PANEL  
47 REAR END PANEL TOP GARNISH  
48 REAR BUMPER REVERSE SENSOR  
49 REAR BOOT LID RUBBER  
50 REAR TAIL GATE TRIM  
51 REAR NUMBER PLATE LAMP RH  
52 REAR NUMBER PLATE LAMP LH  
53 REAR TAIL GATE OPEN HOLDER  
54 REAR TAIL GATE WINDSCREEN SEAL

|                      |          |                |                  |               |
|----------------------|----------|----------------|------------------|---------------|
| 1                    | 262.80   | <i>mgcm</i>    | 262.80           | <i>✓</i>      |
| 1                    | 93.90    | <i>na</i>      | 93.90            | <i>✓</i>      |
| 1                    | 72.10    | <i>na</i>      | 72.10            | <i>✓</i>      |
| 1                    | 1,066.30 | <i>na</i>      | 1,066.30         | <i>✓</i>      |
| 1                    | 130.00   | <i>na</i>      | 130.00           | <i>X</i>      |
| 1                    | 33.30    | <i>na</i>      | 33.30            | <i>✓</i>      |
| 1                    | 661.40   | <i>na</i>      | 661.40           | <i>✓</i>      |
| 1                    | 203.30   | <i>mgcm</i>    | 203.30           | <i>✓</i>      |
| 1                    | 380.60   | <i>nd/shcy</i> | 380.60           | <i>2 coin</i> |
| 1                    | 515.30   | <i>na</i>      | 515.30           | <i>X</i>      |
| 1                    | 162.00   | <i>na</i>      | 162.00           | <i>X</i>      |
| 1                    | 91.50    | <i>na</i>      | 91.50            | <i>X</i>      |
| 1                    | 91.50    | <i>cm</i>      | 91.50            | <i>✓</i>      |
| 1                    | 249.30   | <i>na</i>      | 249.30           | <i>X</i>      |
| 1                    | 80.00    | <i>na</i>      | 80.00            | <i>30.50</i>  |
| Sub Total (\$\$) :   |          |                | 27,107.10        |               |
| Discount (0%) :      |          |                | -                |               |
| Total Parts (\$\$) : |          |                | <u>27,107.10</u> |               |

**258**

**SPECIAL NETT ITEMS:**

- 1 FRONT NUMBER PLATE  
2 FRONT NUMBER PLATE HOLDER  
3 REAR NUMBER PLATE  
4 REAR NUMBER PLATE HOLDER  
5 RADIATOR COOLER  
6 SEALANT

|                    |       |           |               |               |
|--------------------|-------|-----------|---------------|---------------|
| 1                  | 50.00 | <i>na</i> | 50.00         | <i>45.50</i>  |
| 1                  | 30.00 | <i>na</i> | 30.00         | <i>✓</i>      |
| 1                  | 50.00 | <i>na</i> | 50.00         | <i>X</i>      |
| 1                  | 30.00 | <i>na</i> | 30.00         | <i>X</i>      |
| 1                  | 50.00 | <i>na</i> | 50.00         | <i>✓</i>      |
| 1                  | 50.00 | <i>na</i> | 50.00         | <i>40.50</i>  |
| Sub Total (\$\$) : |       |           | <u>260.00</u> | <u>260.00</u> |

**LABOUR:**

- 1 TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY  
2 TO PUTTY/APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION  
3 TO APPLY RUST PROOFING ON REPAIRED,REPLACE PANEL  
4 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS  
5 TO CALIBRATION PROGRAMMING CHECK & RESET  
6 TOP UP GAS  
7 TO CHECK WIRING FUNCTIONS

|                       |          |                                  |
|-----------------------|----------|----------------------------------|
| 1                     | 2,300.00 | <i>1200</i>                      |
| 2                     | 1,800.00 | <i>1000</i>                      |
| 3                     | 150.00   | <i>900</i>                       |
| 4                     | 150.00   | <i>1200</i>                      |
| 5                     | 280.00   | <i>X</i>                         |
| 6                     | 80.00    | <i>✓</i>                         |
| 7                     | 80.00    | <i>400</i>                       |
| Total Labour (\$\$) : |          | <u>4,840.00</u>                  |
| Total Amount (\$\$) : |          | <u>31,947.10</u> <i>34020.40</i> |



for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Sin Ming Autocare BFG Pte Ltd**

176 Sin Ming Drive  
#02-05 Sin Ming Autocare  
Singapore 575721  
Tel : 6455 0600 | Fax : 6455 6192  
Website: www.autocare.com.sg  
GST Reg. No: 20-0210033-N

Budget Direct Insurance  
190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924

Attn: Motor Claim Dept

CHASSIS : NHP1707109583

**ESTIMATE**

VEHICLE NO: **SMC7832A**  
MAKE/MODEL: **TOYOTA SIENTA**  
DOA: **20.10.24**

| No.                      | Descriptions                    | Qty | Unit Price | Amount S\$                  |
|--------------------------|---------------------------------|-----|------------|-----------------------------|
| LIST ITEM: SUPPLEMENTARY |                                 |     |            |                             |
| 1                        | REAR BUMPER CENTRE GARNISH      | 1   | 262.80     | <i>Sm</i> 262.80 <i>X</i>   |
| 2                        | FRONT BRACE PANEL <i>145.30</i> | 1   | 183.40     | <i>R</i> 183.40 <i>✓</i>    |
| 3                        | FRONT APPROACHING SPEAKER       | 1   | 301.50     | <i>cm</i> 301.50 <i>✓</i>   |
| 4                        | FRONT HORN                      | 1   | 85.60      | <i>del</i> 85.60 <i>✓</i>   |
| 4                        | HYBRID COOLER <i>759.60</i>     | 1   | 1,240.00   | <i>pu</i> 1,240.00 <i>✓</i> |
| Sub Total (S\$) :        |                                 |     |            | 2,073.30                    |
| Discount (0%)            |                                 |     |            | -                           |
| Total Parts (S\$) :      |                                 |     |            | <u>2,073.30</u>             |



for Sin Ming Autocare BFG Pte Ltd