



Budget Direct Insurance
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

Attn: Motor Claim Dept

CHASSIS : NHP1707109583

Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

*NOT Withheld
11 days \$12,000
Recovery After Repair*

ESTIMATE

VEHICLE NO: SMC7832A

MAKE/MODEL: TOYOTA SIENTA

DOA: 20.10.24

11 days

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	FRONT GRILLE <i>870.50</i>	1	1,215.20	<i>C'm</i> 1,215.20 <i>—</i>
2	FRONT GRILLE EMBLEM	1	80.60	<i>na</i> 80.60 <i>—</i>
3	HEAD LAMP LH	<i>m/cmt</i> 1	1,551.30	1,551.30 <i>✓</i>
4	HEAD LAMP RH	<i>"</i> 1	1,551.30	1,551.30 <i>✓</i>
5	FRONT BUMPER CENTRE GRILLE	1	185.30	<i>na</i> 185.30 <i>✓</i>
6	FRONT BUMPER SPONGE	1	110.20	<i>sm</i> 110.20 <i>X</i>
7	FRONT BUMPER REINFORCEMENT	1	552.30	<i>na</i> 552.30 <i>X</i>
8	BONNET	1	940.70	<i>na</i> 940.70 <i>—</i>
9	BONNET HINGE LH	1	92.50	<i>DIY</i> 92.50 <i>✓</i>
10	BONNET HINGE RH	1	92.50	<i>DIY</i> 92.50 <i>✓</i>
11	LOWER BONNET LOCK	1	129.90	<i>na</i> 129.90 <i>✓</i>
12	BONNET LOCK CABLE	1	76.10	<i>sm</i> 76.10 <i>X</i>
13	FRONT BUMPER TOP BEAM	1	122.40	<i>na</i> 122.40 <i>✓</i>
14	WIPER GARNISH	1	385.30	<i>sm</i> 385.30 <i>X</i>
15	BONNET INSULATOR CLIP	1	5.50	<i>na</i> 5.50 <i>X</i>
16	FRONT BUMPER	1	527.10	<i>na</i> 527.10 <i>✓</i>
17	FRONT BUMPER CLIPS	10	5.50	<i>na</i> 55.00 <i>✓</i>
18	FRONT SUPPORT PANEL <i>891.60</i>	1	1,571.40	<i>na</i> 1,571.40 <i>—</i>
19	FRONT SUPPORT PANEL TOP GARNISH	1	178.90	<i>na</i> 178.90 <i>X</i>
20	SUPPORT PANEL TOP GARNISH CLIPS	10	5.50	<i>na</i> 55.00 <i>X</i>
21	HEAD LAMP PANEL LH	1	109.40	<i>DIY</i> 109.40 <i>✓</i>
22	HEAD LAMP PANEL RH	1	109.40	<i>DIY</i> 109.40 <i>✓</i>
23	AIR CON CONDENSER <i>1298.60</i>	1	1,886.70	<i>na</i> 1,886.70 <i>✓</i>
24	RADIATOR <i>1899.60</i>	1	3,571.20	<i>na</i> 3,571.20 <i>✓</i>
25	RADIATOR FAN MOTOR	1	919.70	<i>sm</i> 919.70 <i>X</i>
26	RADIATOR FAN COWLING	1	469.50	<i>sm</i> 469.50 <i>X</i>
27	REAR TAIL LAMP RH	1	625.30	<i>sm</i> 625.30 <i>X</i>
28	REAR TAIL LAMP LH	1	625.30	<i>sm</i> 625.30 <i>X</i>
29	REAR BUMPER	1	489.60	<i>m/cmt</i> 489.60 <i>✓</i>
30	REAR BUMPER SIDE GARNISH LH	1	178.90	<i>na</i> 178.90 <i>X</i>
31	REAR BUMPER SIDE GARNISH RH	1	178.90	<i>na</i> 178.90 <i>X</i>
32	REAR WHEEL BEARING	1	1,193.40	<i>na</i> 1,193.40 <i>X</i>
33	REAR BUMPER SIDE RETAINER LH	1	152.80	<i>sm</i> 152.80 <i>X</i>
34	REAR FENDER SIDE GARNISH LH	1	178.90	<i>sm</i> 178.90 <i>X</i>
35	REAR BUMPER REFLECTOR RH	1	83.40	<i>na</i> 83.40 <i>—</i>
36	REAR BUMPER REFLECTOR LH	1	83.40	<i>sm</i> 83.40 <i>X</i>
37	REAR ABSORBER	1	304.80	<i>sm</i> 304.80 <i>X</i>
38	REAR TAIL GATE LOCK <i>359.40</i>	1	647.90	<i>na</i> 647.90 <i>✓</i>
39	REAR TAIL GATE <i>1401.20</i>	1	1,726.80	<i>na</i> 1,726.80 <i>✓</i>

40	REAR TAIL GATE CENTRE GARNISH	1	262.80	mgcm	262.80	✓
41	REAR TAIL GATE LOGO	1	93.90	na	93.90	✓
42	REAR TAIL GATE EMBLEM (HYBRID)	1	72.10	na	72.10	✓
43	REAR TAIL GATE WIPER MOTOR	1	1,066.30	na	1,066.30	✓
44	REAR TAIL GATE WIPER ARM	1	130.00	na	130.00	X
45	REAR TAIL GATE WIPER ARM COVER	1	33.30	na	33.30	✓
46	REAR END PANEL	1	661.40	na	661.40	✓
47	REAR END PANEL TOP GARNISH	1	203.30	mgcm	203.30	✓
48	REAR BUMPER REVERSE SENSOR	1	380.60	nd/shet	380.60	200in
49	REAR BOOT LID RUBBER	1	515.30	na	515.30	X
50	REAR TAIL GATE TRIM	1	162.00	na	162.00	X
51	REAR NUMBER PLATE LAMP RH	1	91.50	na	91.50	X
52	REAR NUMBER PLATE LAMP LH	1	91.50	cm	91.50	✓
53	REAR TAIL GATE OPEN HOLDER	1	249.30	na	249.30	X
54	REAR TAIL GATE WINDSCREEN SEAL	1	80.00	na	80.00	305in
			Sub Total (S\$) :		27,107.10	
			Discount (0%)		-	
			Total Parts (S\$) :		<u>27,107.10</u>	

SPECIAL NETT ITEMS:

1	FRONT NUMBER PLATE	1	50.00	na	50.00	45in
2	FRONT NUMBER PLATE HOLDER	1	30.00		30.00	
3	REAR NUMBER PLATE	1	50.00	na	50.00	X
4	REAR NUMBER PLATE HOLDER	1	30.00	na	30.00	X
5	RADIATOR COOLER	1	50.00	na	50.00	✓
6	SEALANT	1	50.00	na	50.00	405in
			Sub Total (S\$) :		<u>260.00</u>	<u>260.00</u>

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	2,300.00	120d
2	TO PUTTY/APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	1,800.00	1000l
3	TO APPLY RUST PROOFING ON REPAIRED,REPLACE PANEL	150.00	90l
4	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	150.00	120l
5	TO CALIBRATION PROGRAMMING CHECK & RESET	280.00	X
6	TOP UP GAS	80.00	✓
7	TO CHECK WIRING FUNCTIONS	80.00	40l
		Total Labour (S\$) :	<u>4,840.00</u>

Total Amount (S\$) : 31,947.10



for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Sin Ming Autocare BFG Pte Ltd**

176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

Budget Direct Insurance
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

Attn: Motor Claim Dept

CHASSIS : NHP1707109583

ESTIMATE

VEHICLE NO: **SMC7832A**
MAKE/MODEL: **TOYOTA SIENTA**
DOA: **20.10.24**

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM: SUPPLEMENTARY				
1	REAR BUMPER CENTRE GARNISH	1	262.80	<i>Sm</i> 262.80 ✓
2	FRONT BRACE PANEL <i>145.30</i>	1	183.40	<i>Bt</i> 183.40 ✓
3	FRONT APPROACHING SPEAKER	1	301.50	<i>cm</i> 301.50 ✓
4	FRONT HORN	1	85.60	<i>del</i> 85.60 ✓
4	HYBRID COOLER <i>759.60</i>	1	1,240.00	<i>pu</i> 1,240.00 ✓
Sub Total (S\$) :				2,073.30
Discount (0%)				-
Total Parts (S\$) :				<u>2,073.30</u>



for Sin Ming Autocare BFG Pte Ltd