

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

CHWA

Owner : Teo Boon (81777781)

Accident Date : 09-Oct-24

Vehicle No : FBS5174A (COE: 180521-170531)

Yamaha Xmax

Vehicle Model : ABS CVT

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fork assy <i>SVC</i>	\$ 980.00 <i>X</i>
1	Front Fork under bracket <i>SU</i>	\$ 398.00 <i>X</i>
1	Front fork upper bracket <i>SU</i>	\$ 280.00 <i>X</i>
1	Front sport rim <i>CUT</i>	\$520 650.00 <i>/</i>
1	Front brake disc <i>11</i>	\$ 220.00 <i>X</i>
1	Front rim shaft <i>SU</i>	\$ 75.00 <i>X</i>
1	Headlamp (LED) <i>SU</i>	\$ 1,380.00 <i>X</i>
1	Side mirror <i>CUT</i>	\$120 240.00 <i>/</i>
1	Handle-bar <i>SU</i>	\$ 235.00 <i>X</i>
1	Handle-bar balancer set <i>11</i>	\$ 150.00 <i>X</i>
1	Hand grip (1 set) <i>11</i>	\$ 70.00 <i>X</i>
1	Brake levers - R/H <i>CUT</i>	\$110 280.00 <i>/</i>
1	Front cowling inner panel (1 set) <i>CUT</i>	\$260 340.00 <i>/</i>
1	Front cover <i>CUT</i>	\$ 195.00 <i>/</i>
2	Footstep panels <i>CUT 015</i>	\$165 370.00 <i>/</i>
1	Air filter cover <i>11</i>	\$ 260.00 <i>X</i>
1	Belt cover <i>11</i>	\$ 210.00 <i>X</i>
1	Exhaust assy <i>DO/BUT</i>	1100 \$ 2,980.00 <i>/</i>
1	Exhaust protector <i>CUT</i>	\$ 150.00 <i>/</i>
1	Rear footrest (1 set) <i>SU</i>	\$ 185.00 <i>X</i>
1	Main stand <i>11</i>	\$ 168.00 <i>X</i>
1	Side stand <i>11</i>	\$ 108.00 <i>X</i>
1	Fairing cover (1 set) <i>CUT</i>	280 \$ 1,320.00 <i>/</i>
		\$ 11,244.00
	Less 10%	\$ 1,124.40
		\$ 10,119.60

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Teo Boon (81777781)

Accident Date : 09-Oct-24

Vehicle No : FBS5174A (COE: 180521-170531)

Vehicle Model : Yamaha Xmax
ABS CVT

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	17	\$	38.00	X
2	Fork oils	17	\$	50.00	X
2	Fork oil seals	11	\$	78.00	X
1	Steering cone (1 set)	11	\$	150.00	X
1	Rear box	617	\$	420.00	300
1	Rear box bracket	17	\$	180.00	X
1	"X MAX" emblem	111	\$	120.00	80
				\$	1,036.00

S/No. Labour

1	To provide towing service (LOD) S\$70.00	refer LOD	\$	X	-
2	To check wiring and reset headlamp focusing		\$	11	80.00 X
3	To provide labour		\$		620.00 300
4	To repair body frame		\$	11	580.00 X
				\$	1,280.00

Grand Total

\$ 12,435.60

Singapore Dollars: Twelve Thousand Four Hundred Thirty-Five and Cents: Sixty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 3600
100
3240
380
300
3920
202
3136