

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	le Des Experts En	Automobile
/IS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24100370/Aqp3e2
	(BUDGET DIRECT	INSURANCE)	Date:	15/11/2024
		PPING CENTRE SINGAPORE 239924	Code:	AGI
1.		Policy Particulars :- 1	HIRD PARTY CLAI	М
	Insured Veh.	SLV 9960L	Veh. Inspected	GBL 1377U
	Policy No.	P10511892R03	Coverage	0
	Claim No.	C10032330/KR	Excess	\$0.00
	Assign From	KAVIDHA RAJAN	Assign Date	21/10/2024
2.		Vehicle	Details	
	Make & Model	TOYOTA HIACE	C.C	2754
	Engine No.	1GD8675348	Year of Reg.	24/03/2021
	Chassis No.	GDH2012016798	Colour	WHITE
	Odometer	92545 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	195 R15C	BRIDGESTONE	6
	L/H Front Tyre	195 R15C	BRIDGESTONE	6
	R/H Rear Tyre	195 R15C	BRIDGESTONE	6
	L/H Rear Tyre	195 R15C	BRIDGESTONE	6
4.		Description	of Damages	
ΉE	VEHICLE SUSTAIN	IED DAMAGES AT THE REAR PORTIO	N.	
ΑN	IAGES SEE DETAIL	.S.		
5.		General Information		
	Accident Date	18/10/2024	Inspection Date	22/10/2024
	Survey held at	A-TEC AUTOMOTIVE PTE LTD - 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a.		Rem	arks	
		AS CONDUCTED ON A"WITHOUT PRE		

**Estimate Days of Repair**