

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24100371/Anh3m4(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	05/02/2025	
	ATTN: EILEEN LEI	≣		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBB 5629U	Veh. Inspected	k	SMK 5703K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1300647-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		22/10/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ GLA180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDC1569422J603736	Colour		GREY	
	Odometer	64623 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/50R18	PIRELLI		6 mm	
	L/H Front Tyre	235/50R18	PIRELLI		6 mm	
	R/H Rear Tyre	235/50R18	PIRELLI		6 mm	
	L/H Rear Tyre	235/50R18	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
		- 17 (I LO)				
5.	5. General Information					
	Accident Date	18/10/2024	Inspect Date /	Time	22/10/2024 (06:55 PM)	
	Survey held at	KT MOTORWERK	-			
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					