

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No: 533734628

DATE : 22.10.2024

TO : NTUC
VEHICLE NO : SMK5703K
MODEL : MERCEDES BENZ GLA180 URBAN
CHASSIS : WDC1569422J6037368
DATE/TIME ACCIDENT : 18.10.2024
DATE OF REG : 2019 APRIL

Hui Rong

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Deformed</i>	1	\$ 1,316.60	\$ 1,316.60
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 79.80	\$ 159.60
3	REAR BUMPER LOWER GARNISH (BLACK) <i>Dehd</i>	1	\$ 660.70	\$ 660.70
4	REAR BUMPER LOWER CHROME <i>cracked</i>	1	\$ 1,143.30	\$ 1,143.30
5	REAR BUMPER TOW COVER <i>new</i>	1	\$ 49.20	\$ 49.20
6	REAR BUMPER TOP CHROME MOULDING <i>Dehd</i>	1	\$ 297.20	\$ 297.20
7	REAR BUMPER LOWER BRACKET <i>cracked</i>	2	\$ 81.10	\$ 162.20
8	REAR BUMPER CENTRE GUIDE <i>cracked</i>	1	\$ 198.50	\$ 198.50
9	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 720.90	\$ 720.90
10	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 268.10	\$ 1,072.40
11	REAR BUMPER SENSOR HOLDER <i>New</i>	4	\$ 25.00	\$ 100.00
12	REAR BUMPER SENSOR WIRE HARNESS <i>ton</i>	1	\$ 322.50	\$ 322.50
13	REAR END PANEL <i>Dented</i>	1	\$ 1,553.50	\$ 1,553.50
14	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 308.40	\$ 308.40
15	TAILLAMP <i>Cracked</i>	2	\$ 843.80	\$ 1,687.60
16	TAILGATE <i>Dented</i>	1	\$ 2,662.70	\$ 2,662.70
17	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 71.90	\$ 143.80
18	TAILGATE LOCK <i>Damaged</i>	1	\$ 362.20	\$ 362.20
19	TAILGATE WEATHERSTRIPE <i>ton</i>	1	\$ 288.90	\$ 288.90
20	TAILGATE CAMERA <i>2 New</i>	1	\$ 2,003.90	\$ 2,003.90
21	TAILGATE CAMERA BRACKET <i>New</i>	1	\$ 11.90	\$ 11.90
22	TAILGATE INNER TRIM BOARD <i>cracked</i>	1	\$ 489.60	\$ 489.60
23	TAILGATE LAMP <i>cracked</i>	2	\$ 677.50	\$ 1,355.00
24	TAILGATE OUTER MOULDING <i>cracked</i>	1	\$ 289.70	\$ 289.70
25	TAILGATE INNER LOWER COVER <i>cracked</i>	1	\$ 297.90	\$ 297.90
26	TAILGATE GLASS C/W MOULDING <i>New</i>	1	\$ 812.90	\$ 812.90
27	MERCEDES BENZ LOGO <i>2 New</i>	1	\$ 78.70	\$ 78.70
28	GLA180 WORDING <i>New</i>	1	\$ 112.20	\$ 112.20
29	REAR FENDER INNER TRIM BOARD <i>Not New</i>	2	\$ 785.60	\$ 1,571.20

536.20

280

TO : NTUC
 VEHICLE NO : SMK5703K
 MODEL : MERCEDES BENZ GLA180 URBAN
 CHASSIS : WDC1569422J6037368
 DATE/TIME ACCIDENT : 18.10.2024
 DATE OF REG : 2019 APRIL

30	REAR FENDER ARC GARNISH <i>Cracked.</i>	2	\$ 277.80	\$ 555.60	✓
31	SPARE TYRE PANEL <i>Repair</i>	1	\$ 1,358.80	\$ 1,358.80	X.
32	SPARE TYRE TOP BOARD <i>Dented</i>	1	\$ 698.30	\$ 698.60	✓
33	REAR EXHAUST PIPE <i>Dented</i>	1	\$ 2,195.20	\$ 2,195.20	✓
34	REAR EXHAUST PIPE MOUNTING <i>Not rec</i>	1	\$ 69.40	\$ 69.40	X
35	REAR EXHAUST PIPE GASKET <i>Not rec</i>	1	\$ 40.20	\$ 40.20	✓
36	REAR EXHAUST PIPE HEAT SHIELD <i>Crumpled.</i>	1	\$ 315.60	\$ 315.60	✓
37	REAR EXHAUST TAIL PIPE <i>Dented</i>	2	\$ 306.60	\$ 613.20	✓
38	REAR EXHAUST TAIL PIPE BRACKET <i>Cracked</i>	2	\$ 134.10	\$ 268.20	✓

19911.10
 17919.99

TOTAL PRICE \$ 26,348.00
 LESS 10% \$ 2,634.80
 SUB TOTAL PRICE \$ 23,713.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00	✓
	REAR NUMBER PLATE HOLDER <i>Dented</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR BUMPER CLIP (SET) <i>3 per</i>	1	\$ 50.00	\$ 50.00	✓
3	REAR END PANEL SEALANT <i>rec</i>	1	\$ 60.00	\$ 60.00	✓
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>rec</i>	1	\$ 20.00	\$ 20.00	✓
5	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>rec</i>	1	\$ 30.00	\$ 30.00	✓
6	TAILGATE INNER LOWER COVER CLIPS (SET) <i>rec</i>	1	\$ 20.00	\$ 20.00	✓
7	TAILGATE GLASS SEALANT <i>rec</i>	1	\$ 60.00	\$ 60.00	✓
8	CYCLE & CARRIAGE LOGO <i>rec</i>	1	\$ 45.00	\$ 45.00	✓
9	REAR FENDER INNER TRIM BOARD CLIPS (SET) <i>rec</i>	2	\$ 50.00	\$ 100.00	X
10	REAR FENDER ARC GARNISH CLIPS (SET) <i>rec</i>	2	\$ 20.00	\$ 40.00	✓
11	SPARE TYRE PANEL SEALANT <i>Not rec</i>	1	\$ 60.00	\$ 60.00	X

TOTAL \$ 595.00

385

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 150.00	60
4	WIRING CHECK ON TAILAMP	\$ 100.00	30

TO : NTUC
 VEHICLE NO : SMK5703K
 MODEL : MERCEDES BENZ GLA180 URBAN
 CHASSIS : WDC1569422J6037368
 DATE/TIME ACCIDENT : 18.10.2024
 DATE OF REG : 2019 APRIL

5	TO REMOVE REAR BUMPER SENSOR	\$ 100.00	50.
6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	60
7	TRANSFER BOOTLID MECHANISM	\$ 150.00	80.
8	TO REMOVE TAILGATE ^{camera} CAMERA	\$ 100.00	50
9	TO REMOVE TAILGATE VIDEO RECORDER	\$ 100.00	50.
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 150.00	80
12	REAR CHASSIS ALIGNMENT	\$ 250.00	x
13	REMOVE AND REFIX TAILGATE GLASS	\$ 180.00	120
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	150

2230

TOTAL

\$5,510.00

Total: 20534.99.

TOTAL PARTS COST : \$ 24,308.20
 TOTAL LABOUR COST : \$ 5,510.00
 TOTAL REPAIR COST : \$ 29,818.20

2/s: 16.4K.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: