

# ADVANCE AUTO GARAGE

|               |                     |          |
|---------------|---------------------|----------|
| TO            | : CHINA TAIPING     | 18/10/24 |
| VEHICLE NO    | : SGS1188C (2016)   | Yan.     |
| VEHICLE MODEL | : BMW 740Li         |          |
| CHASSIS NO    | : WBA7E22000G651237 |          |

## CLAIM DETAILS: PARTS

|    | ITEMS                                              | QTY | UNIT PRICE  | TOTAL       |         |
|----|----------------------------------------------------|-----|-------------|-------------|---------|
| 1  | FRONT FENDER <i>Repair</i>                         | 1   | \$ 1,089.00 | \$ 1,089.00 | +       |
| 2  | FRONT FENDER INNER SHIELD <i>new</i>               | 1   | \$ 288.00   | \$ 288.00   | +       |
| 3  | FRONT DOOR <i>Dented</i>                           | 1   | \$ 2,539.00 | \$ 2,539.00 | ✓       |
| 4  | FRONT DOOR LOCK <i>Not nec</i>                     | 1   | \$ 498.00   | \$ 498.00   | +       |
| 5  | FRONT DOOR WEATHERSTRIPE <i>new</i>                | 1   | \$ 320.00   | \$ 320.00   | ✓       |
| 6  | FRONT DOOR LOWER PROTECTOR <i>new</i>              | 1   | \$ 198.00   | \$ 198.00   | ✓       |
| 7  | FRONT DOOR WING MIRROR <i>Dented</i>               | 1   | \$ 1,241.00 | \$ 1,241.00 | ✓       |
| 8  | FRONT DOOR WING MIRROR COVER <i>Dented</i>         | 1   | \$ 119.00   | \$ 119.00   | ✓       |
| 9  | FRONT DOOR WING MIRROR <i>Signal lamp new</i>      | 1   | \$ 132.00   | \$ 132.00   | +       |
| 10 | FRONT DOOR WING MIRROR GLASS <i>new</i>            | 1   | \$ 585.00   | \$ 585.00   | +       |
| 11 | REAR DOOR <i>Punctured</i>                         | 1   | \$ 2,698.00 | \$ 2,698.00 | ✓       |
| 12 | REAR DOOR LOCK <i>Not nec</i>                      | 1   | \$ 489.00   | \$ 489.00   | +       |
| 13 | REAR DOOR WEATHERSTRIPE <i>new</i>                 | 1   | \$ 341.00   | \$ 341.00   | ✓       |
| 14 | REAR DOOR LOWER PROTECTOR <i>new</i>               | 1   | \$ 190.00   | \$ 190.00   | ✓       |
| 15 | ROCKER PANEL OUTER SKIRTING <i>Dented</i>          | 1   | \$ 890.00   | \$ 890.00   | ✓       |
| 16 | ROCKER PANEL OUTER SKIRTING BRACKET <i>Cracked</i> | 1   | \$ 165.00   | \$ 165.00   | ✓       |
| 17 | REAR FENDER <i>Repair</i>                          | 1   | \$ 3,391.00 | \$ 3,391.00 | +       |
| 18 | REAR WINDSCREEN C/W MOULDING <i>new</i>            | 1   | \$ 1,840.00 | \$ 1,840.00 | +       |
| 19 | REAR BUMPER <i>Torn</i>                            | 1   | \$ 1,858.00 | \$ 1,858.00 | ✓       |
| 20 | REAR BUMPER SIDE HOLDER <i>new</i>                 | 1   | \$ 169.00   | \$ 169.00   | +       |
| 21 | REAR WHEEL RIM <i>ut</i>                           | 1   | \$ 1,850.00 | \$ 1,850.00 | 800(SN) |
| 22 | REAR SHOCK ABSORBER <i>?</i>                       | 1   | \$ 6,852.00 | \$ 6,852.00 | X       |
| 23 | REAR LOWER ARM                                     | 1   | \$ 896.00   | \$ 896.00   | X       |
| 24 | REAR CONTROL ARM                                   | 1   | \$ 865.00   | \$ 865.00   | X       |
| 25 | REAR KNUCKLE ARM                                   | 1   | \$ 1,755.00 | \$ 1,755.00 | +       |
| 26 | REAR WHEEL HUB                                     | 1   | \$ 385.00   | \$ 385.00   | +       |
| 27 | REAR WHEEL HUB BEARING <i>Not nec</i>              | 1   | \$ 288.00   | \$ 288.00   | +       |

TOTAL PRICE: \$ 31,931.00  
 LESS ~~5%~~ 10% \$ 1,596.55  
 SUB TOTAL PRICE: \$ 30,334.45

10559  
 950310  
 SN: 600

## SPECIAL NETT ITEMS

|   | ITEMS                                          | QTY   | UNIT PRICE | TOTAL     |   |
|---|------------------------------------------------|-------|------------|-----------|---|
| 1 | FRONT FENDER INNER SHIELD CLIPS <i>Not nec</i> | 1 SET | \$ 30.00   | \$ 30.00  | + |
| 2 | ROCKER PANEL OUTER SKIRTING CLIPS <i>new</i>   | 1 SET | \$ 50.00   | \$ 50.00  | ✓ |
| 3 | REAR WINDSCREEN SEALANT <i>Not nec</i>         | 1     | \$ 60.00   | \$ 60.00  | + |
| 4 | REAR TYRE <i>Not nec</i>                       | 1     | \$ 450.00  | \$ 450.00 | + |
| 5 | REAR BUMPER CLIPS <i>new</i>                   | 1 SET | \$ 50.00   | \$ 50.00  | ✓ |

TOTAL: \$ 640.00

100

# LABOUR

|        | JOB                                    | PRICE       | ADJUSTED COST | APPROVED |
|--------|----------------------------------------|-------------|---------------|----------|
| 1      | PANEL BEATING, REMOVE AND REFIT PARTS  | \$ 1,600.00 | 800           |          |
| 2      | SPRAY PAINTING TO AFFECTED AREA        | \$ 4,600.00 | 1000          |          |
| 3      | WIRING CHECK                           | \$ 100.00   | 30            |          |
| 4      | TO APPLY TUFF COAT                     | \$ 150.00   | 40            |          |
| 5      | TO REMOVE REVERSE SENSOR               | \$ 100.00   | 50            |          |
| 6      | TO TRANSFER FRONT & REAR DOOR FITTINGS | \$ 300.00   | 120           |          |
| 7      | TO REMOVE REAR WINDSCREEN              | \$ 180.00   | X             |          |
| 8      | TO REMOVE UPHOLSTERY                   | \$ 150.00   | X             |          |
| 9      | TO DISMANTLE REAR UNDERCARRIAGE        | \$ 380.00   | X             |          |
| 10     | TO PERFORM WHEEL ALIGNMENT             | \$ 150.00   | 80            |          |
| 11     | TO PERFORM DIAGNOSTIC TEST             | \$ 250.00   | 120           |          |
| TOTAL: |                                        | \$ 4,960.00 | 2840          |          |

## ESTIMATE REPORT

TOTAL PARTS COST: \$ 30,974.45

TOTAL LABOUR COST: \$ 4,960.00

TOTAL REPAIR COST: \$ 35,934.45

total: 12443.10

c/s: 9.91c

07 days

9,900

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: