

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNK 7405X

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	FRONT BUMPER	DENTED	\$1,210.30	\$963.00		
1	FRONT BUMPER SIDE GRILLE -LH	TORN	\$380.90	\$285.00		
1	FRONT BUMPER LOWER GRILLE -CTR	NOT NECESSARY	\$190.60	\$0.00		
1	FRONT BUMPER LED LIGHT -LH	CRACKED	\$585.20	\$585.20		
2	FRONT BUMPER SIDE RETAINER -R/L @\$45.50	NOT NECESSARY	\$91.00	\$0.00		
1	FRONT BUMPER REINFORCEMENT	DENTED/BENT	\$420.60	\$420.60		
1	FRONT FENDER -LH	TO REPAIR SEE LABOUR	\$580.60	\$0.00		
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	\$154.20	\$0.00		
1	FRONT FENDER INNER PANEL	TO REPAIR SEE LABOUR	\$460.50	\$0.00		
1	FRONT GRILLE	NOT NECESSARY	\$380.60	\$0.00		
1	FRONT HEADLAMP -LH	HOLDER CRACKED	\$1,872.70	\$1,872.70		
1	FRONT HEADLAMP LOWER BRACKET	CRACKED	\$89.60	\$89.60		
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	\$580.90	\$0.00		
	LESS 20.00% DISCOUNT		(\$1,399.54)	(\$843.22)		
			\$5,598.16	\$3,372.88		
	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00		
			\$50.00	\$30.00		
	Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
	TO CHECK FRONT ELECTRICAL WIRING		\$50.00	\$20.00		
	TO TUFF KOTE	NOT NECESSARY	\$60.00	\$0.00		
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$800.00	\$580.00		
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER -LH, FRONT FENDER INNER PANEL AND FRONT SUPPORT PANEL		\$800.00	\$400.00		
			\$1,710.00	\$1,000.00		
	GRAND TOTAL	\$7,358.16	\$4,402.88			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	\$3,500.00
Report Ref No: CS/FCI24100374/Uqp3m4	

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.