

JC Motor Consultancy

UEN No: 53383584D // Email: jcmotorconsultancy@gmail.com

Not Authorized
for
more
22/10/24
1/5 \$4500/
Telephone After Repair
4 days.

Vehicle number: SLA5170L

Vehicle Made & Model: CITROEN CH

Qty	List Items	Amount \$
1	Rear door - RH <i>but/needed</i>	2,150.00 ✓
1	Rear door glass outer moulding - Top <i>neu</i>	186.00 ✓
1	Rear door glass outer moulding - Lower <i>neu</i>	192.00 ✓
1	Rear door glass run channel <i>^^</i>	286.00 X
1	Rear door w/strip <i>^^</i>	226.00 X
1	Rear door checker <i>SCC</i>	115.00 X
2	Rear door hinges @ 135 <i>^^</i>	270.00 X
1	Rear door insulation <i>^^</i>	132.00 X
1	Rear door inner trim board <i>^^</i>	685.00 X
1	Rear fender - RH <i>~</i>	1,560.00 X
1	Rear shock absorber - RH <i>^^</i>	282.00 X
1	Rear wheel hub bearing - RH <i>^^</i>	512.00 X
1	Front door - RH <i>~</i>	2,260.00 X
1	Front door glass outer moulding - Top <i>^^</i>	196.00 X
1	Front door glass outer moulding - Lower <i>^^</i>	212.00 X
1	Front door glass run channel <i>^^</i>	292.00 X
1	Front door w/strip <i>^^</i>	226.00 X
1	Front door insulation <i>^^</i>	132.00 X
1	Side sill panel - RH <i>on/but</i>	1,155.00 ✓
Sub-total		11,069.00
Less 10%		1,106.90
Total List		9,962.10

Vehicle number: SLA5170L

Vehicle Make & Model: CITROEN CH

Special Nett Items

1	Rear sport wheel - RH	wooped	650.00	550
1	Rear tyre - RH	suc	280.00	X
Total Special Nett			<u>930.00</u>	

Labour charges

To check wheel alignment	120.00	60
To remove, refix rear undercarriage	200.00	X
To remove, refix front/rear interior trims to assist repair	120.00	60
To respray undercoating	100.00	50
To respray painting and etc.	1,200.00	800
Panel beating, cut, weld, remove & replacing above parts	1,500.00	800
Total Labour	<u>3,240.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 14,132.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 3683
102
331470
550
1770
56347
202
4507