

ESTIMATE OF REPAIR

Hui Rong

Veh# : SLX5253K

Model:

MERCEDES BENZ

Accident Date : 22/6/2024

16/3/2018

Location : PIE (CHANGI) BEFORE CTE EXIT

3P:

SML4953L (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	2 pcs	Front headlamp R/L <i>LH Canted</i>	9,308.00	3304.	
2	1 pc	Front grille upper bracket <i>canted</i>	345.60	✓	
3	1 pc	Front grille <i>canted</i>	211.90	✓	
4	1 pc	Front grille outer garnish <i>canted</i>	312.00	✓	
5	2 pcs	Front grille outer garnish moulding <i>canted</i>	384.80	✓	
6	1 pc	Front grille Logo <i>canted</i>	178.00	✓	
7	1 pc	Front grille Logo base bracket <i>new</i>	96.20	+	
8	1 pc	Front grille inner air guide garnish <i>new</i>	175.50	+	
9	1 pc	Front bumper <i>Replaced</i>	2,207.40	1750	
10	1 pc	Front bumper reinforcement <i>new</i>	621.40	+	
11	2 pcs	Front bumper side retainer R/L <i>new</i>	194.20	+	
12	1 pc	Front bumper inner sponge <i>canted</i>	234.00	✓	
13	1 pc	Front bumper no. plate bracket garnish <i>Replaced</i>	170.30	✓	
14	2 pcs	Front bumper parking sensor <i>new</i>	488.00	+	
15	2 pcs	Front bumper parking sensor 'O' ring <i>new</i>	26.00	+	
16	6 pcs	Front bumper parking sensor holder bracket <i>new</i>	180.00	+	
17	1 pc	Front bumper center grille <i>new</i>	171.60	+	
18	2 pcs	Front bumper side grille cover R/L <i>new</i>	172.80	+	
19	1 pc	Front bumper tow hook cover <i>new</i>	64.00	+	
20	1 pc	Front bumper upper bracket <i>new</i>	149.50	+	
21	1 pc	Front bumper bottom carrier garnish <i>new</i>	136.00	+	
22	1 pc	Front bumper bottom carrier garnish moulding <i>new</i>	171.00	+	
23	1 pc	Front bumper lower chrome <i>new</i>	110.20	✓	
24	1 pc	Front bumper lower chrome Rh & LH <i>new</i>	221.60	✓	
25	1 set	Front bumper rivet <i>new</i>		100.00	+
26	1 pc	Front no. plate <i>Replaced</i>		35.00	✓
27	1 pc	Front no. plate holder <i>Replaced</i>		50.00	30
28	1 pc	Rear boot <i>Replaced</i>	2,861.50	2410	
29	1 pc	Rear boot Logo <i>new</i>	221.00	1285	
30	3 pcs	Rear boot Logo clip <i>new</i>		16.50	X
31	1 pc	Rear boot emblem CLA200 <i>new</i>	147.45	115	

32	1 pc	Rear boot emblem C&C <i>nr</i>		80.00	50	
33	1 pc	Rear boot mechanism lock <i>Drnd</i>	383.50	285		
34	1 pc	Rear boot inner trim garnish <i>nr</i>	257.20	x		
35	1 set	Rear boot inner trim garnish clip <i>KOL nr</i>		50.00	x	
36	1 pc	Rear boot weatherstrip seal ct nn	252.00	✓		
37	2 pcs	Rear taillamp R/L <i>RH cancelled</i>	1,845.00	923.50		
38	2 pcs	Rear taillamp lower bracket R/L <i>nr nr</i>	154.00	+1680		
39	1 pc	Rear bumper <i>Deled</i>	2,214.50	✓		
40	1 pc	Rear bumper reinforcement <i>Deled</i>	889.50	✓		
41	2 pcs	Rear bumper side retainer R/L NEC	148.00	✓		
42	1 pc	Rear bumper lower lid garnish <i>Deled</i>	327.50	✓		
43	1 pc	Rear bumper lower lid garnish moulding <i>lt</i>	367.20	280		
44	1 set	Rear bumper clip <i>nr</i>		50.00	30	
45	1 pc	Rear bumper tow hook cover <i>Deled</i>	62.00	-		
46	4 pcs	Rear bumper reverse sensor <i>2 pieces damaged</i>	1,025.40	500		
47	4 pcs	Rear bumper reverse sensor 'O' ring <i>nr 2 pieces</i>	52.00	✓		
48	6 pcs	Rear bumper reverse sensor holder bracket <i>nr nr</i>	180.00	x		
49	1 pc	Rear bumper reverse sensor wireharness <i>nr nr</i>	468.00	x		
50	1 pc	Rear bumper inner frame bracket - Center <i>Cancelled</i>	168.80	✓		
51	1 set	Rear bumper rivet <i>Not nr</i>	980	100.00	x	
52	1 pc	Rear end panel <i>Deled</i>	1,672.00	✓		
53	1 pc	Rear end panel top garnish <i>Cancelled</i>	212.00	✓		
54	1 pc	Rear end panel sealant <i>nr</i>		80.00	60	
55	1 pc	Rear no. plate <i>nr</i>		35.00	x	
56	1 pc	Rear no. plate holder <i>nr</i>		50.00	x	
57	1 pc	Rear under cover <i>nr nr</i>	284.50	x		
58	1 pc	Front safety belt RH <i>3 Adjusted</i>	874.90	✓		
59	2 pcs	Rear safety belt RH	1,910.40	✓		
		Sub Total:	31,397.95	646.50		0.00
			10%	0%		0%
		After Less %:	28,258.16	646.50		0.00

19136

S.N: 205

167222.40

		<u>Labour</u>	
1		To remove & refix accident damaged parts & realign accident affected area.	1,800.00 1000
2		To spray paint on accident affected area.	1,600.00 1000
3		To remove & refix air-con condenser & refiling gas.	150.00 x
4		To remove & refix radiator, fan motor & other attachment parts.	80.00 x
5		To remove & refix rear side covering, trim garnish & other attachment parts.	100.00 60
6		To check wiring & rewire parking sensor.	100.00 50
7		To diagnosis & reset after work.	350.00 200
8		To rust proof affected area.	120.00 60
		2370 Sub Total:	4,300.00
		Total:	33,204.66

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



Adrian C
1/s 25/06/24.

098 days.

total: 19797.4
1/s 15.8K

15.8K

15.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: