

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Ong See Choon
Blk 864A Tampines St 83
#08-446 Singapore 521864

Vehicle No : SNR 8446 J
Make : Toyota Noah
Year : 2019

NOT Withheld
11 Sep 8 5200h
Recovery After Rain
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet garnish	R	SCA	\$275.60	X
1 pc	Front o/s fender	R		\$955.60	X
1 pc	Front o/s headlamp	CM		\$3,050.70	X
1 pc	Front o/s headlamp garnish	RL		\$205.10	X
1 pc	Front o/s headlamp top panel	R		\$197.50	X
1 pc	Front radiator support panel	R		\$1,780.20	X
1 pc	Front grille base - upper	CM		\$286.70	X
1 pc	Front grille base - lower	CM		\$385.30	X
1 pc	Front grille top outer cover	RL		\$285.60	X
2 pcs	Front grille top outer cover moulding	\$197.30	RL	\$394.60	X
1 pc	Front grille centre outer cover	CM		\$376.80	X
1 pc	Front grille centre outer cover moulding	RL		\$205.10	X
1 pc	Front grille emblem	RL		\$75.10	X
1 pc	Front grille lower outer cover	CM		\$236.70	X
1 pc	Front grille lower outer cover moulding	RL		\$230.20	X
1 pc	Front bumper	RL	1CM	\$1,276.20	X
1 pc	Front o/s bumper side retainer	DI		\$95.10	X
1 pc	Front bumper reinforcement	RL		\$550.10	X
1 pc	Front bumper sponge	CM		\$185.60	X
1 pc	Front o/s bumper fog lamp garnish	R		\$135.70	X
				\$11,183.50	
Less 25 %				\$2,795.87	
				\$8,387.63	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	400
To putty & spray paint on accident affected portion.	\$1,200.00	450
Check/reconnect wiring.	\$60.00	20
Remove/refit air con condenser & top up gas	\$180.00	X
Total		\$11,027.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: