

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

not Authorized
her
means
23/10/24
3 days
1/5 + 1800
whenever

TO	: MS FIRST CAPITAL (SHB391R)	DATE	: 22-Oct-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR OWNER ID : SXXXX818A			
VEHICLE DETAILS VEHICLE NO. : SNS1225X MODEL / MAKE : BYD ATTO 3 CHASSIS NO. : LGXCE4CB6R2065667			
ACCIDENT DETAIL DATE : 13-Oct-24 TIME : 13:00 HRS			
CONTACT PERSON : MR. SIM 9844 0974			

Consultants hence notify
 • To survey before/after spray painting
 • To display damaged parts, "As is"
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature: _____
 Date: _____

P - _____
 S - _____
 L - _____
TOTAL : _____
 L/S -20% : _____
SUB TOTAL : _____

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE	1	\$ 8,230.00	\$ 8,230.00
2	REAR TAILGATE CHROME MOULDING	1	\$ 1,100.00	\$ 1,100.00
3	R/R OUTER TAILLAMP	1	\$ 1,800.00	\$ 1,800.00
4	R/R INNER TAILLAMP	1	\$ 1,300.00	\$ 1,300.00
5	REAR BUMPER	1	\$ 3,100.00	\$ 3,100.00
TOTAL PRICE				\$ 15,530.00
SUB TOTAL PRICE				\$ 15,530.00

rear bumper lower
 Rear fender outer protector o/s

\$ 1330.00
 \$ 280.00
 \$ 230.00

gross
 gross

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO REMOVE REAR TAILGATE AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	\$ 500.00		300
TO REMOVE AND INSTALL REAR TAILGATE GLASS	\$ 200.00	17	X
TO REMOVE REAR WIPER MOTOR ASSY AND LOCK ASSY OUT TO FACILITATE REPAIRS OF THE VEHICLE	\$ 100.00	17	X
TO RESPRAY FRONT BUMPER	\$ 600.00		300

TOTAL

\$ 1,400.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 15,530.00
TOTAL LABOUR COST	:	\$ 1,400.00
TOTAL REPAIR COST	:	\$ 16,930.00

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMP SUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	

16940
 102
 1658
 600
 2258
 202
 1800