

AUTOMOBILE HUB ENTERPRISE

TO	: ECICS	DATE	: 23/10/2024
VEHICLE NO	: SMP1604M (2016)		
VEHICLE MODEL	: MERCEDES BENZ C180	Veron.	
CHASSIS NO	: WDD2050402R130232		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Dented</i>		1841.00	1620 ✓
2	FRONT BUMPER SIDE HOLDER <i>Cracked</i>		98.00	✓
3	FRONT BUMPER SENSOR <i>new</i>		265.00	x
	FRONT BUMPER SIDE GRILLE <i>Cracked</i>		146.00	/
	FRONT BUMPER REINFORCEMENT <i>new</i>		656.00	x
4	FRONT FENDER <i>Dented</i>		1012.00	✓
5	FRONT FENDER INNER SHIELD <i>old</i>		221.00	/
6	HEADLAMP <i>Cracked</i>	6707	3985.00	3610 ✓
7	FRONT STAY ARM		541.00	x
8	FRONT LOWER ARM	603630	577.00	x
9	FRONT KNUCKLE ARM		1298.00	+
10	FRONT SHOCK ABSORBER		732.00	+
11	FRONT CONTROL ARM		521.00	+
12	FRONT WHEEL HUB C/W BEARING		587.00	+
			12480.00	
		Less 10%	1248.00	10%
			11232.00	
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS <i>new</i>		30.00	✓
2	FRONT FENDER INNER SHIELD CLIPS <i>new</i>		30.00	✓
3	FRONT WHEEL RIM <i>at</i>		1250.00	600 ✓
4	FRONT TYRE <i>new</i>		280.00	680 ✓
		Total Parts	1590.00	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ASSESSMENT (S\$)
LABOUR			
1	PANEL BEATING	800.00	400
2	SPRAY PAINTING	300.00	400
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	x
5	TO DISMANTLE FRONT UNDERCARRIAGE	350.00	x
6	TO PERFORM DIAGNOSTIC TEST	250.00	x
7	TO PERFORM WHEEL ALIGNMENT	150.00	80
	Labour Total :	2550.00	
TOTAL (PARTS & LABOUR):		15372.00	

910

Total: 7606.30

L/S: 6K ✓

04 Days