

Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg. Year: 15.9.2022

NOT Notified
Pushing B4p 91M
18 days

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER	1		<i>Bz</i> \$1,500.00	✓
2	REAR LH BUMPER RETAINER	1		<i>CM</i> \$500.00	✓
3	REAR RH BUMPER RETAINER	1		<i>Sn</i> \$500.00	X
4	REAR LH BUMPER SIDE SUPPORT BRACKET	1		<i>Bz</i> \$300.00	✓
5	REAR RH BUMPER SIDE SUPPORT BRACKET	1		\$300.00	7
6	REAR BUMPER LOWER	1		<i>Bz</i> \$1,200.00	✓
7	REAR BUMPER LOWER OUTER MOULDING	1		<i>Bz</i> \$1,000.00	✓
8	REAR LH BUMPER REFLECTOR	1		<i>CM</i> \$420.00	✓
9	REAR REVERSE SENSOR	2	<i>Short</i> \$425.00	\$1,700.00	44
10	REAR BUMPER CENTER BRACKET	1		<i>CM</i> \$450.00	✓
11	REAR BUMPER TOWING COVER	1		\$120.00	7
12	REAR BUMPER REINFORCEMENT	1		<i>Bz</i> \$900.00	✓
13	REAR LH BUMPER UNDER COVER	1		<i>Dir</i> \$300.00	✓
14	REAR BUMPER CENTER UNDER COVER	1		\$450.00	7
15	REAR LH BUMPER LOWER BRACKET	1		<i>Bz</i> \$300.00	✓
16	REAR RH BUMPER LOWER BRACKET	1		<i>R</i> \$280.00	X
17	REAR BUMPER CENTER INNER LOWER BRACKET	2	\$280.00	\$560.00	7
18	TAILLAMP LH	1		<i>Bz</i> \$960.00	✓
19	TAILLAMP RH	1		\$960.00	7
20	REAR END PANEL OUTER	1		<i>Bz</i> \$1,800.00	✓
21	REAR LH END PANEL OUTER EXTENSION	1		\$750.00	7
22	REAR END PANEL INNER	1		\$1,500.00	7
23	REAR END PANEL TRIM BOARD	1		\$680.00	7
24	SMART KEY ANTENNA	1		\$90.00	7
25	REAR BOOT	1		<i>Bz</i> \$4,000.00	✓
26	REAR BOOT RENAULT LOGO	1		<i>Re</i> \$300.00	✓
27	REAR BOOT SCENIC EMBLEM	1		<i>Re</i> \$200.00	✓
28	REAR BOOT RENAULT EMBLEM	1		<i>Re</i> \$280.00	✓
29	BOOT REFLECTOR LAMP LH	1		<i>Bz</i> \$950.00	✓
30	BOOT REFLECTOR LAMP RH	1		\$950.00	7
31	REAR BOOT OUTER GARNISH	1		<i>CM</i> \$1,400.00	✓
32	REAR BOOT WEATHERSTRIP	1		\$500.00	7
33	REAR BOOT LOCK	1		<i>Tr</i> \$250.00	✓
34	REAR BOOT OUTER STRIP MOULDING	1		\$800.00	7
35	REAR SPOILER	1		\$1,400.00	7
36	REAR WINDSCREEN	1		<i>Shorter</i> \$1,800.00	✓
37	REAR WIPER ARM	1		<i>Sn</i> \$300.00	X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg. Year: 15.9.2022

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

38	REAR WIPER BLADE	1		Sm \$150.00	X
39	REAR BOOT OUTER OPENING SWITCH	1		\$200.00	?
40	REAR LICENCE PLATE LAMP	1		\$90.00	?
41	REAR BOOT INNER LOWER TRIM BOARD	1		CM \$1,500.00	✓
42	REAR BOOT INNER UPPER TRIM BOARD	1		\$360.00	?
43	REAR LH BOOT INNER UPPER TRIM BOARD	1		\$400.00	?
44	REAR RH BOOT INNER UPPER TRIM BOARD	1		\$340.00	?
45	REAR LH BOOT HINGE	1		\$560.00	?
46	REAR RH BOOT HINGE	1		\$560.00	?
47	REAR LH BOOT STRUT	1		\$300.00	?
48	REAR RH BOOT STRUT	1		h \$300.00	X
50	REAR LH LUGGAGE SIDE TRIM	1		\$1,300.00	?
51	REAR LH LUGGAGE SIDE TRIM CENTER GARNISH	1		\$1,000.00	?
52	REAR LH LUGGAGE SIDE TRIM UPPER GARNISH	1		\$2,200.00	?
53	REAR RH LUGGAGE SIDE TRIM	1		\$1,300.00	?
54	REAR RH LUGGAGE SIDE TRIM UPPER GARNISH	1		\$2,100.00	?
55	ROOF LINING	1		Reform \$3,600.00	✓
56	REAR ROOF PANEL	1		Bu R \$6,100.00	?
57	REAR ROOF PANEL INNER MEMBER COVER	1		\$3,600.00	?
58	REAR LH FENDER PANEL OUTER	1		Buc \$4,850.00	✓
59	REAR LH FENDER PANEL AIR VENT	1		\$150.00	?
60	TAILLAMP PANEL LH	1		Bu \$1,050.00	✓
61	REAR LH FENDER PANEL QUARTER GLASS	1		\$1,000.00	?
62	REAR EXHAUST TAIL PIPE	1		Bu \$1,200.00	✓
63	REAR EXHAUST TAIL PIPE HEAT SHIELD - FRONT	1		\$360.00	?
64	REAR EXHAUST TAIL PIPE HEAT SHIELD - REAR	1		nd \$400.00	✓
65	REAR AXLE	1		\$7,800.00	?
66	REAR LH AXLE STUB	1		\$1,600.00	?
67	REAR LH ABS SENSOR BRACKET	1		\$120.00	?
68	REAR LH BRAKE DISC DUST COVER	1		\$100.00	?
69	REAR LH SUSPENSION SHOCK ABSORBER	1		Bu \$360.00	✓
70	REAR LH ABS SENSOR	1		\$180.00	?
71	REAR LH WHEEL RIM	1		REPAIR	
72	REAR LH DOOR PANEL	1		REPAIR	
73	REAR RH FENDER PANEL	1		REPAIR	
74	REAR LH CHASSIS	1		REPAIR	
75	REAR RH CHASSIS	1		REPAIR	
76	REAR ROOF INNER MEMBER	1		REPAIR	

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg.Year: 15.9.2022

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

SUB TOTAL	\$75,780.00
LESS 10%	-\$7,578.00
PARTS TOTAL	\$68,202.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		na \$55.00
2	REAR BUMPER LOWER CLIPS	1		na \$50.00
3	REAR BUMPER UNDER COVER CLIPS	1		na \$50.00
4	REAR BOOT INNER TRIM BOARD CLIPS	1		na \$50.00
5	REAR WINDSCREEN AND QUARTER GLASS SEALANT	1	na	40sn \$150.00
6	REAR WINDSCREEN AND QUARTER GLASS PRIMER	1	na	30sn \$100.00
7	REAR WINDSCREEN MOULDING	1		na \$150.00
8	REAR RECORDING CAMERA ON REAR WINDSCREEN	1		\$500.00
9	REAR WINDSCREEN SOLAR FILM	1		na \$400.00
10	REAR BOOT OUTER GARNISH CLIP	1		na \$50.00
11	REAR END PANEL OUTER & INNER SEALANT	1		na \$150.00
12	REAR FENDER PANEL SEALANT	1		na \$100.00
13	REAR LICENCE PLATE NUMBER WITH FRAME	1		na \$55.00
14	TAILLAMP GUIDE CLIPS	1		\$50.00
15	REAR REVERSE SENSOR MOUNTING BRACKET SET	1		\$200.00
16	REAR EXHAUST TAIL PIPE MOUNTING AND GASKET SET	1		\$50.00
17	REAR SPOILER CLIPS	1		\$50.00
18	ROOF LINING CLIPS	1		na \$50.00
19	REAR ROOF PANEL SEALANT	1		\$100.00
20	REAR WINDSCREEN "PRIVATE HIRE" DECAL FROM LTA	1		na \$80.00
S/N TOTAL				\$2,440.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

2000/
\$2,800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL OUTER & INNER, REAR LH & RH FENDER, REAR LH DOOR, REAR BOOT OUTER GARNISH, REAR LH CHASSIS, TAILLAMP PANEL LH, REAR END PANEL OUTER EXTENSION, REAR ROOF INNER MEMBER, REAR BODY DRIP PANEL

1400/
\$3,500.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN AND QUARTER GLASS TO ENABLE BODYWORK REPAIR

\$180.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg. Year: 15.9.2022

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	602 \$120.00
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	601 \$100.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00 ?
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$250.00 ?
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$120.00 201
TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, COVER, CUSHION SEAT, GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	\$650.00 1201
TO R&R TYRE AND RIM	UN \$100.00 X
TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	\$400.00 ?
TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	\$150.00 601
TO REMOVE AND REFIT REAR EXHAUST PIPE TO ENABLE BODYWORK REPAIR	\$170.00 601
MOUNT WORKBENCH - TO REALIGNMENT REAR CHASSIS AND REPAIR ACCIDENT AREAS	\$450.00 ?
LABOUR TOTAL	\$9,190.00

TOTAL \$79,832.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

