Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

Singapore 038988

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Foo Ai Ngoh Date: 18 Nov 2024

Preliminary Advice

Insured Vehicle No : YQ3801A

TP Vehicle No : YP82H Accident Date : 18/10/2024

Make : MITSUBISHI CANTER Assignment Date : 24/10/2024

Date of Inspection : 23/10/2024 Est. Duration of Repair : 7

Inspection At : SMC AUTO ENGINEERING WORKS (KAKI BUKIT) (HQ)

1 KAKI BUKIT AVE 6 #01-01 AUTO BAY

SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 17,050.00 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 9,450.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 9,450.00 |
| | | |
| Lump Sum Repair | :S\$ | 7,500.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us |
|---|---|--|
| | | have your authorisation. |
| | | |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.