



AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #07-16
Singapore 079120

Tel: 64193000

WDD1760422J406097

[illegible]



AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #07-16
Singapore 079120

Total Pages : 1/2

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
B.	Spare Parts - S/NETT				
1	Rear Bumper clips <i>new</i>	10	\$0.80	\$80.00	<i>30</i>
2	Front Bumper clips <i>new</i>	10	\$0.80	\$80.00	<i>30</i>
3	Front sensor <i>1 per door</i>	2		\$752.00	<i>250</i>
4	Reverse sensor set <i>2 per door</i>	4	\$376.00	\$1,504.00	<i>200</i>
5	Front Number plate with casing <i>new</i>	1		\$80.00	<i>x</i>
			Sub-Total 2	\$2,496.00	
			Total for Parts	\$11,228.70	
C.	Labour				
1	To check wiring.			\$100.00	<i>30</i>
	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. FRONT			\$400.00	<i>200</i>
	Spray painting all affected parts & areas. FRONT			\$500.00	<i>250</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. REAR			\$1,200.00	<i>800</i>
3	Spray painting all affected parts & areas. REAR			\$800.00	<i>600</i>
4	Labour - Remove & refit tailgate windscreen			\$180.00	<i>120</i>
			Total Labour	\$3,180.00	
			Total Repair Cost	\$14,408.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Total Repair Cost	\$14,408.70
--------------------------	--------------------

f Premium Carz Services Pte Ltd

Name	Adrian G
Contact	96893735
Survey Date	21/10/24
Recommender	Authorize / Not Authorize
Before Paint	Yes / No