

ASS. REC. BY:

REF:

AIG /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: Q 134K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 4086E Yr Regn: 06, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Noah C.C. 1797Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 250517 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR80 0496024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or DAVIGNA

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 19/10/24 D.O.I. 23/10/2024

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / NIS / UIC / Rooftop or

NIS Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

F - RS

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

ump Sum / I.B.I. (\$ _____)

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 22/10/2024
VEHICLE : SNA4086E
MAKE/MODEL : TOYOTA NOAH
CHASSIS NO : ZWR80-0496024
MILLAGE : 252517KM
TYRE SIZE : 195/65/R15
DOA : 19/10/24
TP INSURANCE : AIG

Not Notified
11 Day &
Penny After Rainy
3 days

List items

01 PC	Rear Taillamp (LH)	GR \$	1,780.70	✓
01 PC	Rear taillamp Chrome moulding (LH)	net \$	435.25	✓
01 PC	Rear bumper	rs	1,339.41	X
01 PC	Rear bumper side bracket (LH)	rs	121.90	X
01 PC	Rear bumper reflector (LH)	rs	251.20	X
01 PC	Rear fender cover (LH)	pd/imp	344.60	✓
01 PC	Rear tailgate	rs	1,812.70	X
01 PC	Rear tailgate Chrome moulding	rs	767.80	X
01 PC	Rear fender inner panel (LH)	rs	1,350.60	X
TOTAL PARTS COST			\$	8,204.16

Special Nett Item:

01 PC	Rear reverse camera	\$rs	450.00	X
01 PC	Rear windscreen sealant	\$nn	200.00	X
		\$	650.00	

Labour:

1.	To supply labour and parts to replace accident affected area	\$	600.00	3001
2.	To supply labour and paints to spray accident area	\$	800.00	6001
3.	To supply labour to re-wire replace parts	\$	150.00	201
4.	To supply labour to remove and refit rear windscreen	nn \$	200.00	X
		\$	1,750.00	

TOTAL PARTS	\$	8,204.16
SPECIAL NETT ITEM	\$	650.00
TOTAL LABOUR	\$	1,750.00
TOTAL COST OF REPAIR	\$	10,604.16

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: