



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 22/10/2024
VEHICLE : SNA4086E
MAKE/MODEL : TOYOTA NOAH
CHASSIS NO : ZWR80-0496024
MILLAGE : 252517KM
TYRE SIZE : 195/65/R15
DOA : 19/10/24
TP INSURANCE : AIG

Not Authorised
Library & 1700h
Running After Rain
3 days

List items

01 PC	Rear Taillamp (LH)	1056.20	LT \$	1,780.70	✓
01 PC	Rear taillamp Chrome moulding (LH)	314.10	na \$	435.25	✓
01 PC	Rear bumper		n \$	1,339.41	X
01 PC	Rear bumper side bracket (LH)		n \$	121.90	X
01 PC	Rear bumper reflector (LH)		n \$	251.20	X
01 PC	Rear fender cover (LH)	298.20	ndl n \$	344.60	✓
01 PC	Rear tailgate		n \$	1,812.70	X
01 PC	Rear tailgate Chrome moulding		n \$	767.80	X
01 PC	Rear fender inner panel (LH)		n \$	1,350.60	X
TOTAL PARTS COST		259		\$ 8,204.16	

Special Nett Item:

01 PC	Rear reverse camera	\$ 450.00	X
01 PC	Rear windscreen sealant	\$ 200.00	X
		\$ 650.00	

Labour:

1.	To supply labour and parts to replace accident affected area	\$ 600.00	300
2.	To supply labour and paints to spray accident area	\$ 800.00	800
3.	To supply labour to re-wire replace parts	\$ 150.00	200
4.	To supply labour to remove and refit rear windscreen	na \$ 200.00	X
		\$ 1,750.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 8,204.16
\$ 650.00
\$ 1,750.00
\$ 10,604.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: