

ASS. REC. BY:

REF:

C9/A1624100382/K9p3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £ 134K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 4086E Yr Regn: 06, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Toy Noah c.c. 1797Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 250517 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BWR80 0498024Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD / A/Rim orTyre Size: F: 195/85R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 19/10/24 D.O.I. 23/10/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/10	21 Lm @ 1700h. Confr. (red £ 8904.16, 842)
-------	--

Date/Time, File Pass to?

☐ : Prell. Report

1) 08/11 1700h

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS. SI

Fuel

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

MER-TP
1700

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 22/10/2024
VEHICLE : SNA4086E
MAKE/MODEL : TOYOTA NOAH
CHASSIS NO : ZWR80-0496024
MILLAGE : 252517KM
TYRE SIZE : 195/65/R15
DOA : 19/10/24
TP INSURANCE : AIG

Not Authorized
Liberty & Food
Recovery After Rainy
3 days

List items

01 PC	Rear Taillamp (LH)	1056.20	CU \$	1,780.70	✓
01 PC	Rear taillamp Chrome moulding (LH)	311.10	CU \$	435.25	✓
01 PC	Rear bumper		CU \$	1,339.41	X
01 PC	Rear bumper side bracket (LH)		CU \$	121.90	X
01 PC	Rear bumper reflector (LH)		CU \$	251.20	X
01 PC	Rear fender cover (LH)	298.70	CU \$	344.60	✓
01 PC	Rear tailgate		CU \$	1,812.70	X
01 PC	Rear tailgate Chrome moulding		CU \$	767.80	X
01 PC	Rear fender inner panel (LH)		CU \$	1,350.60	X
TOTAL PARTS COST		258		<u>\$ 8,204.16</u>	

Special Nett Item:

01 PC	Rear reverse camera	\$ 450.00	X
01 PC	Rear windscreen sealant	\$ 200.00	X
		<u>\$ 650.00</u>	

Labour:

1.	To supply labour and parts to replace accident affected area	\$ 600.00	300
2.	To supply labour and paints to spray accident area	\$ 800.00	600
3.	To supply labour to re-wire replace parts	\$ 150.00	201
4.	To supply labour to remove and refit rear windscreen	CU \$ 200.00	X
		<u>\$ 1,750.00</u>	

TOTAL PARTS

\$ 8,204.16

SPECIAL NETT ITEM

\$ 650.00

TOTAL LABOUR

\$ 1,750.00

TOTAL COST OF REPAIR

\$ 10,604.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: