

Not Authored
1/1 Sep 86400/r

AAD2410-073

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Date of Registration:

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 DUCT ASSY, QUARTER VENT, LH
- 1 TROUGH, BACK DOOR OPENING, LH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 DUCT ASSY, QUARTER VENT, RH
- 1 TROUGH, BACK DOOR OPENING, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 PAN, REAR FLOOR
- 1 BOX, DECK FLOOR, REAR
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 PANEL ASSY, DECK TRIM SIDE, LH

22 OCT 2024

SHD9878J

JTDKB3FU003092580

200303878K

TOYOTA

PRIUS GEN 4

21/10/2024

SJQ4541X/II

6/11/2020

LIST

\$	<i>R</i>	612.68	✓
\$	<i>B</i>	419.90	✓
\$	<i>DI</i>	27.93	—
\$	<i>B</i>	472.19	✓
\$	<i>DI</i>	167.48	—
\$	<i>CM</i>	167.48	✓
\$	<i>SL</i>	49.25	X
\$	<i>SL</i>	49.25	X
\$	<i>R</i>	1,099.46	X
\$	<i>SL</i>	176.09	X
\$	<i>SL</i>	93.98	X
\$	<i>SL</i>	130.31	X
\$	<i>R</i>	1,099.46	X
\$	<i>SL</i>	176.09	X
\$	<i>SL</i>	93.98	X
\$	<i>SL</i>	130.31	X
\$	<i>SL</i>	428.19	X
\$	<i>SL</i>	329.49	X
\$	<i>SL</i>	88.41	X
\$	<i>SL</i>	428.19	X
\$	<i>SL</i>	329.49	X
\$	<i>SL</i>	88.41	X
\$	<i>DI</i>	220.50	✓
\$	<i>SL</i>	304.92	X
\$	<i>CM</i>	290.43	✓
\$	<i>R</i>	734.90	X
\$	<i>SL</i>	133.25	X
\$	<i>R</i>	395.12	X
\$	<i>R</i>	394.38	X
\$	<i>R</i>	448.98	X

AAD2410-073

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

- 1 PANEL ASSY, DECK TRIM SIDE, RH
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 WEATHERSTRIP, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	Pl	448.98	X
\$	sm	159.39	X
\$	Bj	824.46	✓
\$	Bj	1,443.86	✓
\$	nd/di	469.25	✓
\$	cm	1,156.89	✓
\$	sm	326.76	X
\$	sm	305.66	X
\$	sm	305.66	X
\$	K	77.18	X
\$	K	77.18	X
\$	mu	68.88	✓
\$	mu	68.88	✓
\$	mu	90.30	✓
TOTAL		\$ 15,403.83	
25%		\$ 3,850.96	
		\$ 11,552.87	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE WITH HOLDER
- 1 FENDER LINER CLIP
- 1 END PANEL TRIM CLIP

\$	nd	700.00	220sn
\$	mu	95.00	60sn
\$	mu	150.00	80sn
\$	mu	200.00	✓
\$	mu	130.00	60sn
\$	mu	100.00	30sn
\$	mu	100.00	30sn
\$	nsp	180.00	X
\$	na	250.00	X
\$	na	85.00	X
\$	nd	140.00	45sn
\$	na	65.00	X
\$	na	65.00	X
TOTAL		\$ 2,260.00	

TOTAL PARTS \$ 13,812.87**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 180d

AAD2410-073

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	801
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	501
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	301
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

AAD2410-073

TOTAL	\$	8,440.00
--------------	-----------	-----------------

Over All Total	\$	22,252.87
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

~~09 DAYS~~

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: