

ASS. REC. BY:

REF:

W  
TY / 24100325 / 16a3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7996A

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.G

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

698238

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU903080363

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F: Laufey 195/5R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

21/10/24

D.O.I.

22/10/2024

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Get BZ

22/10

11:00pm @ 1050h Car hit

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

: Fines

: Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL:

Not Authored  
L1 Sup \$1050h

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHB7996A**

**AAD2410-074**

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHB7996A

JTDBK3FU903080363

200303878K

TOYOTA

PRIUS

21/10/2024

YQSG90P / TL

24/5/2019

22 OCT 2024

**PART**

**LIST**

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 LENS AND BODY, REAR LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS AND BODY, REAR LAMP, LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 SPOILER SUB-ASSY, REAR
- 1 SEAL, REAR SPOILER
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 BOARD, BACK DOOR TRIM
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH

|    |        |          |     |
|----|--------|----------|-----|
| \$ | RC     | 558.39   | X   |
| \$ | ms rc  | 19.43    | ✓   |
| \$ | RC     | 148.58   | X   |
| \$ | RC     | 148.58   | X   |
| \$ | RC     | 111.41   | X   |
| \$ | RC     | 111.41   | X   |
| \$ | nd/cms | 726.92   | ✓   |
| \$ | By     | 419.90   | ✓   |
| \$ | RC     | 155.72   | } X |
| \$ | RC     | 155.72   |     |
| \$ | RC     | 220.50   |     |
| \$ | RC     | 304.92   |     |
| \$ | RC     | 290.43   | } X |
| \$ | RC     | 31.50    |     |
| \$ | RC     | 824.46   |     |
| \$ | RC     | 570.15   |     |
| \$ | RC     | 634.73   | } X |
| \$ | RC     | 81.48    |     |
| \$ | RC     | 559.13   |     |
| \$ | RC     | 634.73   |     |
| \$ | RC     | 81.48    | } X |
| \$ | RC     | 1,443.86 |     |
| \$ | RC     | 1,986.92 |     |
| \$ | RC     | 21.32    |     |
| \$ | RC     | 326.76   | } X |
| \$ | RC     | 65.73    |     |
| \$ | RC     | 284.55   |     |
| \$ | RC     | 305.66   |     |
| \$ | RC     | 305.66   | } X |
| \$ | RC     | 77.18    |     |

CNA

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel NcFax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHB7996A****AAD2410-**

|       |                                            |    |    |           |   |
|-------|--------------------------------------------|----|----|-----------|---|
| 1     | HINGE ASSY, BACK DOOR, RH                  | \$ | R  | 77.18     | X |
| 1     | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE       | \$ | Sn | 1,171.38  | X |
| 1     | PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2 | \$ | nn | 68.88     | X |
| 1     | PLATE, BACK DOOR NAME, NO.1                | \$ | nn | 68.88     | X |
| 1     | ORNAMENT SUB-ASSY, BACK DOOR               | \$ | nn | 90.30     | X |
| TOTAL |                                            | \$ |    | 13,083.74 |   |
| 25%   |                                            | \$ |    | 3,270.93  |   |
|       |                                            | \$ |    | 9,812.80  |   |

**SPECIAL NETT**

|             |                              |    |    |           |      |
|-------------|------------------------------|----|----|-----------|------|
| 1SET        | PARKING AID                  | \$ | Sn | 700.00    | X    |
| 1           | REAR BUMPER CLIP             | \$ | nn | 65.00     | 601n |
| 1           | REAR RH BUMPER RETAINER CLIP | \$ | nn | 65.00     | X    |
| 1           | REAR NUMBER PLATE            | \$ | Sn | 180.00    | X    |
| 1           | REAR TAIL LAMP CLIP          | \$ | nn | 65.00     | X    |
| 1           | END PANEL INNER TRIM CLIP    | \$ | nn | 60.00     | X    |
| 1           | BOOT STICKER TRANSCAB        | \$ | nn | 100.00    | X    |
| 1           | BOOT STICKER TEL NO          | \$ | nn | 100.00    | X    |
| 1           | REAR BUMPER PROTECTOR        | \$ | nn | 180.00    | 301n |
| 2           | WINDSCREEN SEALANT           | \$ | nn | 150.00    | X    |
| 1           | WINDSCREEN MOULDING          | \$ | nn | 200.00    | X    |
| 1           | WINDSCREEN INNER SPONGE SEAL | \$ | nn | 130.00    | X    |
| TOTAL       |                              | \$ |    | 1,995.00  |      |
| TOTAL PARTS |                              | \$ |    | 11,807.80 |      |

**LABOUR**

|                                                                                                                           |    |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----|----------|------|
| To rust-proofing of the affected areas.                                                                                   | \$ | nn | 600.00   | X    |
| Putty and spray painting of the affected portion.                                                                         | \$ |    | 1,200.00 | 2201 |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ |    | 2,000.00 | 2001 |
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                                                    | \$ | nn | 170.00   | X    |
| To transfer of tailgate fittings and conduct water seepage test.                                                          | \$ | nn | 170.00   | X    |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHB7996A****AAD2410-**

To remove and refit interior fittings, trimmings, garnish,  
fittings and other, to enable repair.

\$ *un* 380.00 X

To reinstall rear bumper parking sensor.

\$ *7* 170.00 X

To check steering geometry and computer wheel alignment

\$ *5* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform  
Water Seepage Test.

\$ *h* 170.00 X

**TOTAL** \$ **5,080.00**

**OVERALL TOTAL** \$ **16,887.80**

*2 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: