

NOT Withheld
L1 Reg 81050h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB7996A

AAD2410-074

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

22 OCT 2024

SHB7996A

JTDKB3FU903080363

200303878K

TOYOTA

PRIUS

21/10/2024

YQSG90P / III

24/5/2019

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 LENS AND BODY, REAR LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS AND BODY, REAR LAMP, LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 SPOILER SUB-ASSY, REAR
- 1 SEAL, REAR SPOILER
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 BOARD, BACK DOOR TRIM
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH

\$	R	558.39	X
\$	ms rd	19.43	✓
\$	R	148.58	X
\$	R	148.58	X
\$	R	111.41	X
\$	R	111.41	X
\$	rd/cma	726.92	✓
\$	R	419.90	✓
\$	R	155.72	✓
\$	R	155.72	✓
\$	R	220.50	✓
\$	R	304.92	✓
\$	R	290.43	✓
\$	R	31.50	✓
\$	R	824.46	✓
\$	R	570.15	✓
\$	R	634.73	✓
\$	R	81.48	✓
\$	R	559.13	✓
\$	R	634.73	✓
\$	R	81.48	✓
\$	R	1,443.86	✓
\$	R	1,986.92	✓
\$	R	21.32	✓
\$	R	326.76	✓
\$	R	65.73	✓
\$	R	284.55	✓
\$	R	305.66	✓
\$	R	305.66	✓
\$	R	77.18	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2410-**SHB7996A**

- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	R	77.18	X
\$	Sm	1,171.38	X
\$	nn	68.88	X
\$	nn	68.88	X
\$	nn	90.30	X
TOTAL		\$ 13,083.74	
25%	\$	3,270.93	
	\$	9,812.80	

SPECIAL NETT**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR NUMBER PLATE
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Sm	700.00	X
\$	nn	65.00	60mm
\$	nn	65.00	X
\$	Sm	180.00	X
\$	nn	65.00	X
\$	nn	60.00	X
\$	nn	100.00	X
\$	nn	100.00	X
\$	nn	180.00	30mm
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
TOTAL		\$ 1,995.00	
TOTAL PARTS		\$ 11,807.80	

LABOUR

To rust-proofing of the affected areas.

\$ nn 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 2201

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 2001

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 170.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB7996A**AAD2410-**

To remove and refit interior fittings, trimmings, garnish,
fittings and other, to enable repair.

\$ *nn* 380.00 X

To reinstall rear bumper parking sensor.

\$ *7* 170.00 X

To check steering geometry and computer wheel alignment

\$ *5* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

\$ *h* 170.00 X**TOTAL \$ 5,080.00****OVERALL TOTAL \$ 16,887.80***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: